

## CONTENTS

Ceramic Fracture Mode-Intergranular vs Transgranular Fracture	1
The VAMAS Fractography Round Robin: A Piece of the Fractography Puzzle	55
Standardized Guidelines for Fractography of Advanced Ceramics-A View from Europe	71
Fracture Toughness Estimation by Fractographic Analysis of Tensile Specimens	91
Fractography and the Surface Crack in Flexure (SCF) Method for Evaluating Fracture Toughness of Ceramics	107
Analysis of Machining Damage in Engineering Ceramics by Fracture Mechanics, Fractography, and X-Ray Diffraction	145
Fractography Used with Lifetime Prediction Tests on Commercial Grades of Alumina and Silicon Carbide	171
The Origin of Strength-Limiting Defects in a Toughened SiC (Hexoloy SX-SiC)	181
Spatial and Temporal Probes of Fracture, Wear, and Deformation	193
Combination of Fractography and Computed Tomography for the Determination of the Cause of Fracture (Case Study)	257
Growth of Indentation-Induced Flaws in RBSiC and RBSiC-TiB <sub>2</sub> Composites Under an Applied Stress	273
Failure Analysis of an $\alpha$ -SiC Tube Subjected to Thermal Cycling in an Oxygen-Steam Atmosphere	301
Fractographic Investigation of Flaws in Sintered SiC Fiber	317
Microstructural Considerations for Fractographic Analysis of Polyphase Ceramics via Transmission Electron Microscopy	339
Utilization of Fractography in the Evaluation of High-Temperature Dynamic Fatigue Experiments	353
The Use of Laser Raman Microprobe Spectroscopy for Investigating Residual Surface Strain in Selected Ceramics	367
Fractography, Fracture Mechanics, and Fractal Geometry: An Integration	385
Fractal Analysis of Fracture Surfaces Using the Patchwork Method	395
Mechanisms for Hackle Formation and Crack Branching	409
Hackles Revisited	447
Indentation Crack Shapes and Their Evolution During Subcritical Crack Growth in Ion-Exchanged Glasses	473
Crack Initiation During Indentation of Normal and Anomalous Glasses-A Study Using Fractography and Acoustic Emission	491
Structural Implications of Elastic Properties, Fracture Toughness, and Fracture Surface Energies of R <sub>2</sub> O-Al <sub>2</sub> O <sub>3</sub> -SiO <sub>2</sub> Glasses	503
Arc-Induced Fractures from Lampmaking Test Equipment	517
Failure Analysis of a Fiberglass-Reinforced Plastic Pressure Vessel	527
Index	545