

# TABLE OF CONTENTS

Chapter	Page
<b>1 RULES AND SCALES</b> ..... DEFINITIONS— <i>rule . . . scale</i> . TYPES OF RULES AND SCALES AND THEIR USES— <i>graduations— numbers . . . flexible . . . narrow steel rule . . . hook rule . . . reading the            rule . . . shrink scales . . . decimal rules.</i>	1
<b>2 SEMI-PRECISION AND COMMON PRECISION TOOLS</b> ..... DEFINITIONS— <i>precision tools . . . non-precision tools . . . semi-precision tools</i> . SEMI-PRECISION TOOLS— <i>combination square . . . dividers . . . trammel . . . calipers . . .            outside . . . inside . . . hermaphrodite . . . telescoping gages . . . screw pitch gage . . .            radius gage . . . thickness gage . . . surface gage . . . parallels-adjustable . . . non-            adjustable . . . V-block . . . planer gage . . . solid square</i> . PRECISION TOOLS— <i>microm-            eters . . . principles . . . to read . . . screw thread micrometer . . . inside micrometer . . .            depth micrometer . . . tube micrometer . . . verniers— principle . . . height gage . . .            vernier caliper . . . vernier depth gage . . . gear tooth vernier caliper . . . Universal            vernier bevel protractor . . . how to read the protractor</i> . INDICATING GAGES— <i>dial            indicator . . . Universal indicator</i> .	6
<b>3 SHAPER — PLANER</b> ..... SHAPER HISTORY . . . DESCRIPTION . . . CRANK SHAPER . . . IMPORTANT PARTS. SHAPER OPERATION— <i>to set the length of stroke . . . to set the position of the stroke            . . . holding the work . . . clamp or vise . . . shaping a block of rectangular form . . . to            shape an inside square corner . . . shaping a job to layout . . . angular work . . . to cut            a dovetail . . . compound angles . . . solution of . . . work operations square wedge</i> . WORK DIFFICULTIES— <i>chattering tool . . . warping of work . . . checking the square-            ness of vise</i> . SPEEDS AND FEEDS— <i>factors involved . . . tables of strokes per minute . . .            formula to determine speeds</i> . CUTTING TOOLS— <i>compared to lathe tools . . . tools            commonly used . . . Do's and Don'ts</i> . VERTICAL SHAPER (SLOTTER)— DEFINITION . . . <i>holding the work . . . setting the length of stroke . . . position of the stroke . . . work            difficulties</i> . PLANER — DEFINITION . . . <i>difference between shaper and planer . . . his-            tory . . . size . . . planer parts . . . feeds . . . holding the work . . . clamping hints</i> .	36
<b>LATHE</b> ..... HISTORY — <i>tree lathe</i> . DEFINITION — <i>engine lathe</i> . CLASSIFICATION — <i>screw machine            . . . horizontal turret lathe . . . vertical turret lathe . . . back-off lathe</i> .	67
<b>TOOL ROOM LATHES</b> ..... <i>Bench lathe . . . tool room lathe . . . getting acquainted with the lathe . . . lining up            centers . . . cutting tools . . . clearance . . . holders . . . grinding tool bits . . . setting            the tool . . . cutting speed</i> .	72
<b>6 LATHE WORK</b> ..... <i>Centering . . . center drilling . . . facing . . . turning . . . filing . . . shoulders . . . chuck            and mandrel work . . . draw bar and collets . . . originating and finishing the hole . . .            boring . . . counterboring . . . undercutting . . . steady rest work . . . knurling . . .            tapers— external . . . taper attachment . . . internal tapers . . . checking tapers . . .            threading . . . Do's and Don'ts</i> .	85
<b>7 MILLING MACHINES</b> ..... INTRODUCTION — <i>historical note</i> . CLASSIFICATIONS— <i>types . . . manufacturing . . .            planer . . . knee and column . . . special . . . knee and column— vertical, plain . . . Universal            horizontal</i> . ATTACHMENTS— <i>vises . . . plain flanged . . . swivel . . . Universal swivel . . .            Vertical . . . dividing head . . . vertical milling attachment . . . heavy duty— light duty            . . . compound vertical milling attachment . . . rack milling attachment . . . rotary            attachment</i> . CUTTERS— <i>classification . . . formed, inserted, saw tooth . . . plain milling            cutters . . . side milling cutters . . . interlocking side milling cutters . . . radius cutters            . . . concave cutters . . . corner rounding cutters . . . angular cutters . . . double angle            cutters . . . tap and reamer fluting cutters</i> . ARBORS— <i>standard . . . stub . . . expansion</i> . END MILLS— <i>two-lipped . . . shell end mills . . . face milling cutter . . . fly cutter            . . . T-slot cutter . . . Woodruff key seater</i> .	122

Chapter	Page
<b>8 MILL OPERATIONS</b> .....	<b>139</b>
<p><b>MILLING PRACTICES</b>—<i>holding the work . . . clamps, vises, dividing head . . . how to true up a job in a chuck . . . spring collets . . . between centers . . . angle plate . . . V-block . . . fixtures . . . speeds and feeds—examples, formula, feed, coolant . . . general suggestions—set-up, selection of cutter, up-feed, down-feed.</i> <b>MILLING SET UP AND OPERATIONS</b>—<i>slab milling procedure . . . gang milling . . . straddle milling . . . example . . . key-way cutting procedure.</i></p>	
<b>9 DIVIDING HEAD WORK</b> .....	
<p><b>DIVIDING HEAD</b>—<i>kinds—Milwaukee, Brown &amp; Sharpe . . . classifications . . . rapid, plain, angular, graduating, differential . . . helical and spiral milling . . . DEFINITIONS—helical . . . spiral . . . examples of helical milling . . . solutions . . . procedures . . . spiral milling—solutions . . . procedures.</i></p>	
<b>10 VERTICAL MILL</b> .....	
<p><b>VERTICAL MILLING MACHINE</b>—<i>work operations . . . boring . . . procedures.</i> <b>MILLING SUGGESTIONS</b>—<i>set-up . . . selection of cutters . . . selection of speeds and feeds.</i> <b>SAFETY</b>—<i>common precautions . . . Do's and Don'ts.</i></p>	
<b>11 CYLINDRICAL GRINDERS</b> .....	
<p><b>DEFINITIONS. CLASSIFICATIONS</b>—<i>external . . . internal . . . surface . . . cutter . . . tool grinder . . . off-hand grinder . . . plain cylindrical grinders . . . types of work . . . Universal cylinder grinder . . . holding the work . . . driving the work . . . adjusting the machine . . . wheel feed . . . speed of work.</i> <b>WORK OPERATIONS</b>—<i>plain cylinders . . . tapers . . . general comments . . . mottled, checked, or cracked work . . . undercuts . . . plunge-cut . . . dressing the wheel . . . truing . . . glazing . . . loading . . . gaging cylindrical work . . . common amplifier.</i> <b>SAFETY SUGGESTIONS</b>—<i>Centerless grinder.</i></p>	
<b>12 INTERNAL GRINDERS</b> .....	
<p><b>DEFINITION. CLASSIFICATION</b>—<i>work rotating type . . . planetary type . . . centerless type.</i> <b>METHODS OF HOLDING WORK</b>—<i>chucking the work . . . internal cylindrical grinding—thirteen step analysis . . . internal taper grinding . . . flat work . . . chuck and steady rest . . . center and steady rest . . . face plate and angle plate . . . face plate and V-block . . . special fixtures.</i> <b>SAFETY SUGGESTIONS</b>—<i>centerless grinder.</i></p>	
<b>13 SURFACE GRINDERS</b> .....	
<p><b>DEFINITION</b>—<i>rotary type . . . planer type . . . vertical spindle rotary . . . work operations . . . horizontal planer type . . . holding the work . . . work operations witness marks . . . grinding work parallel . . . grinding work square . . . angular work . . . V-block work—work operations . . . slot grinding—work operations . . . radius grinding . . . surface grinder wheels.</i> <b>GENERAL INFORMATION</b>—<i>safety . . . wheel selections.</i> <b>SAFETY SUGGESTIONS.</b></p>	
<b>14 CUTTER GRINDING</b> .....	
<p><b>DEFINITION</b>—<i>machines.</i> <b>CUTTER GRINDING WHEELS</b>—<i>straight . . . flaring cup . . . disk . . . dish . . . abrasive, grain size, and bond . . . direction of rotation . . . tooth rests . . . cutter grinding classifications.</i> <b>CUTTER SHARPENING</b>—<i>plain milling cutters—work operations . . . side milling cutters—work operations . . . end mills . . . face mills . . . helical tooth cutters . . . staggered tooth cutters . . . angular cutters . . . formed cutters . . . taps . . . reamers—machine reamers, hand reamers . . . Do's and Don'ts for cutter grinding.</i></p>	
<b>15 GRINDING WHEELS</b> .....	
<p><b>DEFINITION. <i>Kind of abrasive . . . size of abrasive . . . kind of bond . . . amount of bond . . . abrasives . . . bonds . . . wheel hardness.</i> <b>GENERAL SUGGESTIONS.</b></b></p>	
<b>16 BENCH HAND TOOLS AND THEIR OPERATION</b> .....	
<p><i>Hammers . . . pliers . . . wrenches . . . screw drivers . . . miscellaneous . . . chisels . . . files . . . hacksaws.</i></p>	

<i>Chapter</i>	<i>Page</i>
<b>17 BENCH. MATERIALS — ROUTING — INSPECTION</b> .....	<b>254</b>
<p><i>MATERIALS — aluminum . . . copper . . . brass and bronze . . . cast iron . . . cold rolled . . . SAE chromium . . . chrome vanadium . . . tool steel . . . high speed steel. JOB PROCESSING — stock order . . . routing card. GAGES AND INSPECTION — kinds . . . use.</i></p>	
<b>18 BENCH. LAYOUT — DRILLING — THREADING — SCRAPING — HEAT TREATING</b> .....	<b>264</b>
<p><i>Layout . . . drills . . . reamers . . . counterbores . . . countersinks . . . threads . . . scraping . . . heat treating — manganese, silicon, chromium, nickel, vanadium, tungsten, molybdenum. GENERAL SUGGESTIONS.</i></p>	
<b>19 FORMULAS AND TABLES</b> .....	<b>287</b>
<p><i>Circles . . . areas . . . solids . . . decimal equivalents — inches to millimeters . . . diameters of numbered drills . . . diameters of lettered drills . . . allowance for machine fits . . . table of cutting speeds . . . taper pins and reamers . . . SAE standard taper dimensions . . . American National Coarse and Fine Thread dimensions and tap drill sizes . . . Woodruff key seat cutter sizes . . . table of co-ordinates for the jig gorer.</i></p>	
<b>INDEX</b> .....	<b>301</b>