

# Contents

## PREFACE

## TO THE STUDENT

xix

## INTRODUCTION

### 1. THE MACHINIST'S TRADE

1

What is a Machine Shop?	Commercial Manufacturing Shop Classified?
What May Constitute the Equipment of a Machine Shop?	What Is the Knowledge One Must Have to Be an Expert Machinist?
What Are the Standard Machine Tools?	What Chances Has a Machinist for Promotion?
What is Meant by Bench Work and Floor Work?	What Are the Essential Characteristics of a Machinist?
Are There Many Specified Divisions in the Machinist's Trade?	How Are These Characteristics Acquired?
How Are the Employees of a	

## SAFETY

### 2. SAFETY IN THE MACHINE SHOP

23

What Are Accidents?	General Safety Precautions
Present Conditions	Clothing and Equipment
Machine Tools and Their Hazards	Hand Tools
Housekeeping	Test on Safety Practices
Precautions and Safe Practices for the Machine Shop	

## MEASURING TOOLS

### 3. MEASURING TOOLS OF THE MACHINE SHOP

59

Accuracy	Setting and Reading an Outside Caliper
Care of Measuring Tools	The Micrometer Caliper
Linear Measurements	Principle of the Micrometer
Round-work Measurements	How to Read a Micrometer Caliper
Scales	Holding a Micrometer
Calipers	The Vernier Caliper
Measuring with a Caliper	

How to Read Micrometers Graduated in Ten-thousandths	Checking Micrometers Using Blocks
How to Read a Universal Bevel Protractor with a Vernier	The Sine Bar
Gage Blocks	Theory of the Sine Bar
How to Obtain Various Dimensions Using Gage Blocks	How to Use the Sine Bar
	Dial Indicators
	How to Use Indicators

## **BENCH WORK**

### **4. HAMMERS, SCREW DRIVERS, WRENCHES, HACKSAWS**

The Use of Hand Tools	A Few Suggestions Regarding the Use of Wrenches
Care of Hand Tools	Action of Check Nut
Hammers	Hacksaws
Soft Hammers	Proper Number of Teeth
Screw Drivers	Using the Hacksaw
Grinding the Blade	Hints on Hacksawing
Safety Rules for Use of Screw Drivers	Power Sawing
Wrenches	

### **5. CHIPPING, FILING, SCRAPING**

Chipping	Holding the File
Cold Chisels	Position of the Body When Filing
Safety Rules for Chipping	The Operation of Filing
Grinding a Cold Chisel	Drawfiling
The Operation of Chipping	Filing Soft Metals
Hints on Chipping	Needle-handle Files
The Use of Files	Don'ts in Filing
Machine-shop Files	Reasons for Scraping
The Safe Edge	Tools Used for Scraping a Flat Surface
Convexity of Files	Sharpening the Flat Scraper
Taper of Files	The Scraping Operation
File Handles	Hints on Scraping
Care of Files	Scraping Curved Surfaces
Pinning	
Cross Filing	

### **6. LAYING OUT**

Tools Used for Laying-out Work	Prick Punch
Bench Plate or Surface Plate	Divider
Hammer	Vernier Caliper
Center Punch	Hermaphrodite Caliper

**CONTENTS**

Scale	Height Gage
Bevel Protractor	The Surface Gage
Parallels	Trammel Points
Square	Scribing the Lines
Angle Plates	The Operation of Laying Out
Parallel Clamps	

**THE DRILL PRESS****7. DRILL-PRESS CONSTRUCTION 161**

The Drilling Machine	The Sensitive Drill Press
The Standard Drill Press: Floor Type	The Radial Drill
Care of the Table	The Gang Drill
The Standard Drill Press: Bench Type	Parts of the Drill Press

**8. DRILLS AND DRILLING 173**

Drilling-machine Operations	Speeds and Feeds of Twist Drills
Tool Holding Devices	Calculation for R.P.M. of Drill
Sockets and Sleeves	The Use of Cutting Oils and Coolants
Drill Chucks	Work-holding Devices
Parts of the Drill and Their Functions	Jigs
The Straight-fluted Drill	The Use of Clamps and Stops
The Flat Drill	Bolts
The Three-fluted Drill	Clamps
Oil-tube Drills	Clamping Blocks
Sharpening a Drill	Shims
Drill-grinding Machine	Hints on Clamping
Principles of Sharpening a Drill	Examples of Drilling Setups
Lip Clearance	Laying Out for Drilling
Angle of Clearance at Center of Drill	Example of Laying Out
Angle and Length of Lip	Use of Toolmakers' Buttons in Drilling
Rake	Hints on Drilling
The Operation of Sharpening a Drill	Drilling the Hole
Drill Points for Different Materials	Drilling Large Holes
Thinning the Point of a Drill	

**9. OTHER DRILL-PRESS TOOLS AND OPERATIONS 211**

Reamers	Chucking or Machine Reamers
Reamer Terms	Shell Reamers
Handling Reamers	Hand Reamers
Stock Removal Allowance	Adjustable Reamers
Alignment of Reamers	The Expansion Reamer
Types of Reamers	

Taper Reamers  
High-speed Reamers  
Carbide-tipped Reamers  
Emergency Reamers  
To Avoid Chattering of Reamers  
Hints on Reaming  
The Operation of Reaming  
Duplicating a Drilled and Reamed Part  
The Counterbore  
The Countersink  
Boring in a Drill Press  
Taps and Tapping  
Tap Terms  
Types of Taps

Hand Taps  
Machine-screw Taps  
Tapered Taps  
Tapper Taps  
Pulley Taps  
Machine Taps  
Gun Taps  
Tap-size Drills  
Advantages of Tapping by Power  
Tapping in a Drill Press  
Tapping Troubles  
Using a Piece Already Drilled as a Template  
Checking a Tapped Hole  
Tapping Dies

## **THE LATHE**

### **10. LATHE CONSTRUCTION AND MANIPULATION**

The Engine Lathe  
Function of the Lathe  
Determining the Size of a Lathe  
General Lathe Operations  
Types of Lathes  
Bench Lathes  
Quick Change Gear Lathes  
Running a Lathe  
Cleaning and Oiling  
A Few Safety Suggestions  
Some Very Important Precautions  
Description and Functions of Lathe Parts  
The Bed  
The Headstock  
The Tailstock  
The Carriage  
How to Operate the Thread Dial  
Micrometer Collars  
Power Carriage Feeds on Quick-change Gear Lathes

Power Carriage Feeds on Standard change Gear Lathes  
Speeds of Pulleys and Gears  
Driving and Driven Pulleys  
Driving and Driven (Follower) Gears  
Simple Gear Train  
Compound Gear Train  
Direct Spindle Speeds  
Lockpin  
Back Gears  
Indirect Spindle Speeds, Back Gear  
Revolutions Per Minute (R.P.M.)  
Sliding Gears  
Other Features of High-duty Lathe  
The Cam-lock Spindle Nose  
Attachments  
The Electric Motor  
Antifriction Bearings

### **11. CUTTING TOOLS AND CUTTING OPERATIONS**

Kinds and Care of Tools  
Cutting-tool Efficiency

Simple Fundamental Factors Governing Lathe Cutting-tool Design

Simple Fundamentals Governing the  
Form and Application of Lathe  
Tools  
Cutting Tools Used in Lathe Work  
Steels of Which Cutting Tools Are  
Made  
Terms Generally Used to Designate  
Different Lathe Tools  
The Cutting Edge and the Faces  
That Form It  
Contour of the Turning Tool  
Tool Angles  
Cutting Angle

Clearance and Clearance Angles  
Rake Angles  
Keeping Cutting Tools Sharp  
Grinding Cutting Tools  
Don'ts in Tool Grinding  
Cemented-carbide Tools  
Roughing and Finishing Cuts  
Definitions  
The Time Element  
Cutting Speeds and Feeds  
Cutting-speed Calculations  
Value of High Speed  
What Happens When Metals Are Cut

## **12. CENTERING**

Holding Work in the Lathe  
Lathe Dogs for Driving Work on  
Centers  
Importance of Carefully Locating the  
Center  
Methods of Locating Centers  
Divider Method  
Hermaphrodite-caliper Method  
Center-head Method

Surface-gage Method  
Diagonal-line Method  
Centering-machine Method  
Use of Center Punch  
Drilling and Reaming the Center  
Sizes of Centers  
Correct Center Hole  
Poorly Drilled Center Holes

## **13. FACING**

General Information  
Facing on Centers: Adjusting the  
Work

The Facing Operation  
Typical Facing Job

## **14. TURNING**

Principles of Turning  
Position of the Dead Center  
Accuracy of the Live Center  
Cleaning and Truing the Lathe  
Centers  
Setting the Tool  
Direction of the Feed  
The Use of a Protecting Piece  
Adjusting the Work on Centers  
Oiling and Readjusting the Centers  
Lubricating the Tool

Graduations on the Crossfeed Screw  
Lost Motion in the Crossfeed  
Cutting Speed and Feed  
An Example of Turning  
Alignment of Centers  
Quicker Methods of Aligning Centers  
Setting the Speed  
The Roughing Cut  
The Finishing Cut  
Turning Duplicate Parts  
Filing in the Lathe

Suggestions When Filing  
 Polishing in the Lathe  
 Suggestions for Polishing  
 Shoulder Turning  
 Roughing to the Shoulder  
 Finishing the Diameter and Square  
 Shoulder  
 The Forming Tool  
 Necking

The Center Rest  
 The Follower Rest  
 Knurling  
 Holding Work on a Mandrel  
 The Standard Mandrel  
 Using a Mandrel  
 Other Forms of Mandrels  
 To Turn a Crankshaft or an Eccen

## **15. CHUCKING WORK**

Kinds of Chucks  
 The Independent Chuck  
 The Universal Chuck  
 The Combination Chuck  
 The Headstock-spindle Chuck  
 The Drill Chuck  
 The Draw-in-collet Chuck  
 Selecting a Chuck  
 Removing Chuck from Lathe Spindle  
 Mounting the Chuck on the Spindle  
 Methods of Adjusting the Work in a  
 Chuck  
 Chalk Method  
 Scriber Method  
 Wiggler Method  
 Dial-indicator Method  
 Radial Facing

Cutting Off Bar Stock in a Lathe  
 The Cutting-off Tool  
 The Cutting-off Operation  
 Chattering  
 Drilling and Reaming in a Lathe  
 Spotting the Center  
 Operation of Drilling the Hole  
 Machine Reaming  
 Use of Drill Chuck  
 Hand Reaming  
 Boring in the Lathe  
 Reasons for Boring  
 The Boring Tool  
 The Boring-tool Holder  
 Grinding and Setting a Boring To  
 Boring in the Lathe  
 Hints on Boring in the Lathe

## **16. TAPERS AND ANGLES**

Tapers  
 Standard Tapers  
 Taper Turning  
 Setover of Tailstock Method  
 Rules for Offset When Turning Taper  
 Methods of Gaging Offset  
 Setting the Turning Tool  
 Methods of Measuring Tapers  
 Fitting a Taper to a Gage  
 Gaging the Size of a Taper  
 Duplicating a Taper Piece  
 Turning a Taper with a Square-nosed  
 Tool

Filing a Taper  
 The Taper Attachment  
 Parts of the Taper Attachment  
 Types of Connections  
 Using the Taper Attachment  
 Taking Up Lost Motion  
 Boring Tapers with Taper  
 Attachment  
 Boring Tapers with Compound R  
 Fitting Taper Holes  
 Turning Angles  
 Classification of Angles

The Use of the Compound Rest for  
Turning Angles  
Setting the Compound Rest

Turning the Angle  
The Bevel Protractor

**17. THREADS AND THREAD CUTTING**

417

Thread Standards  
American National Thread System  
SAE Standard System  
American National Acme Thread  
System  
The Unified Thread System  
American Standard Pipe Thread  
System  
Definitions of Thread Terms  
Terms Relating to Fits  
Wire Measurement Symbols  
Dimensional Symbols  
Identification Symbols  
General Dimensions and  
Characteristics of Screw-thread  
Forms  
The Sharp V Thread  
The American National Thread  
The American National Acme  
Thread  
The 29-deg. Worm Thread  
The Square Thread  
The International Standard Metric  
Thread  
The British Standard Whitworth  
Thread  
The British Association Thread  
The Unified Screw Thread  
Tapping in the Lathe  
Tap-drill Sizes  
Hand Tapping  
Machine Tapping  
The Threading Die  
Gearing a Lathe for Cutting Threads  
Definitions of Gear Terms  
Gearing the Lathe for Cutting  
Threads  
Operations of the Gears

Calculating the Size of Gears to Cut  
a Given Thread  
Compound Gearing  
Thread Cutting  
Preliminary Hints on Thread Cutting  
The Thread Stop  
Four Ways of Catching the Thread  
After Resetting the Tool  
Using the Apron-control Handle  
Operation of Cutting the Thread in  
the Lathe  
How to Cut a Screw Thread in a  
Lathe Without Using a Threading  
Dial  
The Three-wire Method of  
Measuring Threads  
Measuring the American National  
Form of Thread  
Measuring the V Thread  
Measuring the Whitworth Thread  
The Use of the Compound Rest for  
Cutting Threads  
Cutting a Thread without the Use of  
the Reverse Belt  
To Cut a Left-hand Thread  
To Cut a Thread on a Taper  
The Square Thread  
The Square-thread Tool  
Cutting a Square Thread  
The Square-thread Tap  
The Acme Thread  
Cutting an Acme Thread  
Boring an Internal Thread  
Cutting Metric Screw Threads  
Multiple Threads  
Cutting a Multiple Thread  
Checking Threads  
Thread Gages  
Dial Threads

## CONTENTS

### APPENDIX

Rules for Finding the Diameters and Speeds of Pulleys	515
Rules for Finding the Number of Teeth and Velocity of Gears	516
Machine Fits	518
Fastening a Belt	519
Geometrical Progressions	521
The Screw-thread Micrometer	522
Wire Gages and Sheet-metal Gages	523

### LIST OF TABLES

1. Decimal and Millimeter Equivalents of Fractional Parts of an Inch	525
2. Cutting Speeds: Lathe Work, Drills, Milling Cutters	526
3. Morse Tapers	527
4. Brown & Sharpe Tapers	528
5. Taper Pins and Reamers (Pratt & Whitney Company)	529
6. Tapers per Foot and Corresponding Angles	530
7. Different Standards for Wire Gages and Sheet-metal Gages in Use in the United States	
8. American National Screw Threads: National Coarse (NC) and National Fine (NF)	532
9. Acme 29-deg. Screw Threads	534
10. American (N.P.T.) Standard Taper Pipe Taps	535
11. British Standard Whitworth Threads	536
12. British Standard Fine Threads	536
13. British Association Screw Threads	537
14. French (Metric) Standard Screw Threads	538
15. International Standard Screw Threads	539
16. The Metric System of Measurement	540
17. Metric Conversion Table	541



18. Decimal Equivalents of the Number and Letter Sizes of Twist Drills	5
19. Mensuration	5
20. Diagonals of Hexagons and Squares	5
21. Weights of Flat Bar Steel and Wrought Iron	5
22. Weights of Steel and Wrought Iron	5
23. Trigonometric Functions	5
24. Mathematical Method of Finding Slant Angles of Square-thread Tools	5
25. Constants for 5-in. Sine Bar	5