

## CONTENT

	Page
Preface	v
1. INTRODUCTION	
1.1 Examples and definitions	1
1.2 Where inspection?	4
1.3 Classification of inspection plans	5
1.4 Flow chart for acceptance inspection	9
2. ACCEPTANCE SAMPLING : BASIC IDEAS	
2.1 The OC-Curve	13
2.2 The average run length	17
2.3 The process curve	18
2.4 Some methods of choosing sampling plans	21
2.5 Tables of sampling plans	29
2.6 Inspection by variables	32
3. CONTROL CHARTS	
3.1 Statistical quality control	42
3.2 Simple control charts for variables	43
3.3 Properties of the charts	47
3.4 The economic design of $\bar{x}$ -charts	53
3.5 Specifications for variables	56
3.6 Control charts for qualitative data	62
3.7 Other types of chart for variables	65
4. CUMULATIVE SUM CHARTS	
4.1 Introduction	68
4.2 Decision rules	71
4.3 Properties of the decision rules	79
4.4 Theory of the decision interval scheme	82
4.5 The economic design of CUSUM control charts	89
4.6 Estimation from CUSUM charts	91
4.7 Other CUSUM charts	93
4.8 Conclusion	93
5. CONTINUOUS SAMPLING PLANS	
5.1 Basic description and aims	95
5.2 CSP-1 and the AOQL criterion	96
5.3 Theory of CSP-1	100
5.4 The AEDL criterion	102
5.5 Decision-theory approach to CSP-1	103
5.6 Modifications to CSP-1	105
5.7 Process trouble shooting	108
5.8 Adaptive control	110
5.9 Use of CUSUM techniques	112
Paper and books for further reading	115
Appendix I Theoretical models for industrial processes	116
Appendix II Statistical Tables	118
References	122
Index	127