530.8 COO

Contents

Chapter 1. INTRODUCTION 1

1–1. What are experiments? 1
1–2. Types of measurement 3
1–3. Choice of suitable instruments 6
1–4. The resolution and accuracy of instruments 7
1–5. The microscope 7
1–6. The eye as a microscope lens 10
1–7. Magnification obtainable with a microscope 11
1–8. Depth of focus of a lens 12
1–9. The chemical balance 13
1–10. Theoretical limit of resolution of the balance 15
1–11. Accuracy of instruments and errors of measurement . . . 15
1–12. Errors of the caliper micrometer 16
1–13. Errors of a dynamic measuring device: the voltmeter . . . 21
1–14. Design of experiments to reduce errors 25

Chapter 2. EXPERIMENTAL STATISTICS 29

2–1. Internal and external estimates of measurement error . . . 29
2–2. External estimates of the error 30
2–3. Independence and dependence of errors 32
2–4. How to estimate the external error of a measurement . . . 35
2–5. Internal estimates of the error 36
2–6. Properties of the normal distribution 38
2–7. Use of the normal distribution to eliminate data 40
2–8. Use of the normal distribution to relate various definitions of error 41
2–9. Use of the normal distribution to estimate the extreme of a distribution 41
2–10. Use of the normal distribution to calculate the probable error in $\bar{x}$ 42
2–11. How to set up a normal distribution calculation 44
2–12. Short cuts in calculating σ 48
2–13. Testing a distribution for normalcy: the χ^2 test 49
2–14. Nonnormal distributions 53
2–15. How to draw the "best" straight line through a set of points 56

Chapter 3. DYNAMICS OF MEASUREMENT 69

3–1. First-order systems 70
3–2. Second-order systems (where input is a force) 78

3–3. Second-order systems (where input is a displacement) . . . 84
3–4. Compensating networks 87
3–5. Harmonic analysis 97
3–6. Dynamic data analysis 106

Chapter 4. DISPLACEMENT MEASUREMENT 113

4–1. Displacement measuring by mechanical means 114
4–2. Optical measuring methods 116
4–3. Fluid gages 121
4–4. Displacement measurement through electrical means . . . 124

Chapter 5. FORCE AND TORQUE MEASUREMENT 153

5–1. Preliminary requirements 153
5–2. Systems for measuring force 154
5–3. Axially loaded members 158
5–4. Cantilever beams 159
5–5. Rings 160
5–6. Torque tubes 165
5–7. General considerations 165

Chapter 6. TEMPERATURE MEASUREMENT 169

6–1. Temperature-measuring devices 170
6–2. Sources of error in thermocouples 177
6–3. Pyrometry 179
6–4. Other measuring techniques 182
6–5. Dynamics of thermal measurement 183
6–6. Velocity error 185
6–7. Radiation error 186
6–8. Temperature measurement in moving and sliding members . . 187
6–9. Sliding temperature measurement 190

Chapter 7. MEASUREMENTS ON FLUIDS 195

7–1. Flow measurement 195
7–2. Pressure measurement 204
7–3. Vacuum gages 212
7–4. Cleanliness considerations 214
7–5. Leak detection 215
7–6. Dynamics of pressure measurement 215

Chapter 8. RADIOTRACER TECHNIQUES 225

8–1. Introduction 225
8–2. The constitution of atoms 225

8–3. Stability of nuclides: radionuclides 226
8–4. Decay of radioactive nuclei 229
8–5. Multiple decay 230
8–6. Half-life of radionuclides 231
8–7. Penetrating power of radioactive decay particles 232
8–8. Detection of radiation 234
8–9. The geiger counter 234
8–10. Photographic film 237
8–11. Comparison of geiger counters and photographic film as radioactivity detectors 238
8–12. Obtaining radioactive material 240
8–13. Quantitative aspects of irradiation 241
8–14. Amount of radioactivity required for tracer experiments . . 244
8–15. The statistics of radiotracer measurements: Poisson statistics 245
8–16. Resolution and accuracy of radiotracer counting methods . . 248
8–17. Experimental uses of radioactivity: nontracer uses 250
8–18. Tracer applications of radiotracers 252
8–19. Calibration of radioactive materials 253

APPENDIX 1. Time-variant physical quantities: the use of complex numbers 259

APPENDIX 2. Experiments with random numbers 265

APPENDIX 3. Illustrative experiments 272

APPENDIX 4. The use of analog computers in measurement analysis 295

APPENDIX 5. Tables of physical quantities 299

INDEX 310