620.43 JEL

CONTENTS

		Page
Chapter 1.	**INTRODUCTION**	
1.1	Particle size analysis	7
1.2	Disperse systems	7
1.3	Particles	8
1.4	Means of expressing the size, shape and polydispersity of particles	9
1.5	Survey of methods	16
1.6	Sample preparation	16
Chapter 2.	**OPTICAL METHODS**	**18**
2.1	Microscopy	18
2.2	Automatic evaluation of microphotographs and oscilloscopic microscopy	23
2.3	Ultramicroscopy	25
2.4	Electron microscopy	27
2.5	Light scattering	35
2.6	X-Ray analysis	48
Chapter 3.	**MECHANICAL METHODS**	**58**
3.1	Sieve analysis	58
3.2	Ultrafiltration	63
3.3	Gel permeation chromatography	65
Chapter 4.	**GRAVITATION METHODS**	**70**
4.1	Sedimentation	70
4.2	Centrifugation	79
4.3	Ultracentrifugation	85
4.4	Sedimentation and classification in a stream	92
Chapter 5.	**OSMOTIC METHODS**	**94**
5.1	Diffusion methods	94
5.2	Osmometry	102
Chapter 6.	**TRANSLATIONAL METHODS**	**107**
6.1	Viscometry	107
6.2	Permeametric determination of the specific surface	114
6.3	The transient flow method	120
6.4	Liquid permeametry	123
Chapter 7.	**PORE SIZE ANALYSIS**	**126**
7.1	Analysis of pore distribution	126
7.2	Determination of the pore distribution	129
7.3	Determination of the pore distribution by the desorption method	130
Chapter 8.	**ADSORPTION METHODS**	**134**
8.1	The B. E. T. method	134
8.2	The thermal desorption method	142
8.3	The Harkins and Jura relative method	144
Chapter 9.	**CONDUCTOMETRIC METHODS**	**147**
Chapter 10.	**MISCELLANEOUS METHDOS**	**150**
10.1	Radiometric methods	150
10.2	Pulse methods	152