620.43 LOW

CONTENTS

Page

PART ONE, THEORETICAL

CHAPTER ONE Introduction 3
1. Real Surfaces 3
2. Factors Affecting Surface Area 3

CHAPTER TWO Surface Area from Size Distributions 6

CHAPTER THREE Gas Adsorption 8
1. Introduction 8
2. Physical and Chemical Adsorption 9
3. Physical Adsorption Forces 10

CHAPTER FOUR Adsorption Isotherms 13

CHAPTER FIVE Langmuir and BET Theories 16
1. The Langmuir Isotherm, Type I 16
2. The Brunauer, Emmett, and Teller (BET) Theory 20
3. Surface Areas from the BET Equation 25
4. The Meaning of Monolayer Coverage 26
5. The BET Constant and Site Occupancy 27
6. Applicability of the BET Theory 28
7. Some Criticism of the BET Theory 32

CHAPTER SIX The Single Point BET Method 34

CHAPTER SEVEN Adsorbate Cross-Sectional Areas 40
1. Cross - Sectional Areas from the Liquid Molar Volume 40
2. Nitrogen as the Standard Adsorbate 42
3. Some Adsorbate Cross – Sectional Areas 43

CHAPTER EIGHT Other Surface Area Methods 46
1. Harkins and Jura Relative Method 46
2. Harkins and Jura Absolute Method 49
3. Permeametry 51

CHAPTER NINE Pore Analysis by Adsorption 57
1. The Kelvin Equation 57
2. Adsorption Hysteresis 61
3. Types of Hysteresis 62
4. Total Pore Volume 64
5. Pore Size Distributions 65
6. Modelless Pore Size Analysis 74
7. V-t Curves 76

CHAPTER TEN Microporosity 80
1. Introduction 80
2. Langmuir Plots for Microporous Surface Area 81
3. Extensions of Polanyi's Theory for Micropore Volume and Area 81
4. The M P Method 85

CHAPTER ELEVEN Mercury Porosimetry 90
1. Calculation of Pore Radii 90

2. Surface Area from Intrusion Curves 92
3. Pore Size Distributions 94
4. Pore Surface Distribution 95
5. Comparisons of Porosimetry and the Kelvin Equation 98
6. Hysteresis 99

PART TWO, EXPERIMENTAL

CHAPTER TWELVE Adsorption Measurements-Preliminaries 103
1. Reference Standards 103
2. Other Preliminary Precautions 104
3. Representative Samples 105
4. Sample Conditioning 109

CHAPTER THIRTEEN Vacuum Volumetric Measurements 112
1. Nitrogen Adsorption 112
2. Deviations from Ideality 115
3. Sample Cells 116
4. Evacuation and Outgassing 117
5. Temperature Control 117
6. Isotherms 117
7. Low Surface Areas 120
8. Saturated Vapor Pressure, P o of Nitrogen 122

CHAPTER FOURTEEN Dynamic Methods 124
1. Influence of Helium 124
2. Nelson and Eggertsen Continuous Flow Method 126
3. Carrier Gas and Detector Sensitivity 129
4. Design Parameters for Continuous Flow Apparatus 131
5. Signals and Signal Calibration 136
6. Adsorption and Desorption Isotherms by Continuous Flow 140
7. Low surface Area Measurements 143
8. Data Reduction-Continuous Flow 147
9. Single Point Method 149

CHAPTER FIFTEEN Other Flow Methods 151
1. Pressure Jump Method 151
2. Continuous Isotherms 152
3. Frontal Analysis 153

CHAPTER SIXTEEN Gravimetric Method 158
1. Electronic Microbalances 158
2. Buoyancy Corrections 159
3. Thermal Transpiration 160
4. Other Gravimetric Methods 161

CHAPTER SEVENTEEN Comparison of Experimental Adsorption Methods 163

CHAPTER EIGHTEEN Chemisorption 167
1. Introduction 167
2. Chemisorption Equilibrium and Kinetics 168
3. Determination of Chemisorption Isotherms 171
4. Surface Titrations 173

CHAPTER NINTEEN Density Measurement 175
1. True Density 175
2. Apparent Density 179
3. Bulk Density 179
4. Tap Density 180
5. Effective Density 180

CHAPTER TWENTY Mercury Porosimetry **181**
1. Introduction 181
2. Pressure Generators 181
3. Dilatometer 182
4. Continuous Intrusion 184
5. Logarithmic Signals 185
6. Low - Pressure Intrusion 186
7. Contact Angle for Mercury 188

INDEX **197**