668.412 BEB

CONTENTS

1 INTRODUCTION **1**

2 COMPRESSION AND DISPLACEMENT MOULDS **4**

2.1 Positive moulds 4
2.2 Open flash type moulds 5
2.3 Semi-positive moulds 7
2.4 Multi tools 15
2.5 Self-contained tools 18
2.6 Methods of extraction 23
2.7 Core pins and loose parts 24
2.8 Keyways 28
2.9 Location dowels 28
2.10 Large moulds 29
2.11 Mounting compression moulds tools 34
2.12 Split moulds 38
2.13 Summary of procedure in compression moulds design 45
2.14 Mould charging 45
2.15 Examples for drawing practice 47

3 TRANSFER MOULDS **54**

3.1 Principles of transfer moulding 54
3.2 Bottom transfer with auxiliary ram 56
3.3 Transfer moulds for standard presses 59
3.4 Separate pot transfer moulds 62
3.5 Tapered split moulds 65
3.6 Continuous process transfer moulding 71
3.7 Feeds and air vents 71
3.8 Examples for drawing practice 74

4 HOBBING OF MOULDS **79**

4.1 Some Considerations of hobbing conditions 79
4.2 Hob materials 81
4.3 Hobbing blanks 83
4.4 Hobbing bolsters 84
4.5 Hobs 86
4.6 Engraving and embossing 93

4.7 Hobbing procedure 98
4.8 Method of hob removal 99
4.9 Conclusion 100

5 FERROUS METALS FOR MOULD MAKING 101
5.1 Cast iron 101
5.2 Steel 102
5.3 Heat treatment of steel 104
5.4 Mould materials 108
5.5 Factors governing the choice of mould steels 118
5.6 Non-ferrous metals 118

INDEX 121