Contents

Preface to the Fourth Edition vii
Preface to the First Edition ix

1 Introduction
1.1 Basic Process
1.2 Scope of the Book 2
1.3 General Literature Survey 2
1.4 History of Polymer Extrusion 4
References 6

Part I Extrusion Machinery

2 Different Types of Extruders 11
2.1 The Single Screw Extruder 11
2.1.1 Basic Operation 12
2.1.2 Vented Extruders 13
2.1.3 Rubber Extruders 14
2.2 The Multiscrew Extruder 18
2.2.1 The Twin Screw Extruder 18
2.2.2 The Multiscrew Extruder with More Than Two Screws 19
2.2.3 The Gear Pump Extruder 20
2.3 Disk Extruders 21
2.3.1 Viscous Drag Disk Extruders 21
2.3.2 The Elastic Melt Extruder 26
2.3.3 Overview of Disk Extruders 27
2.4 Ram Extruders 12
2.4.1 Single Ram Extruders 28
2.4.2 Multi Ram Extruder 31
Appendix 2.1 32
References 33

3 Extruder Hardware 36
3.1 Extruder Drive 36
3.1.1 AC Motor Drive System 36
3.1.2 DC Motor Drive System 36
3.1.3 Hydraulic Drive System 41
3.1.4 Comparison of Various Drive Systems 43
3.1.5 Reducer 44
3.1.6 Constant Torque Characteristics 45
3.2 Thrust Bearing Assembly 46
3.3 Barrel and Feed Throat 48
3.4 Feed Hopper 52
3.5 Extruder Screw 53
3.6 Die Assembly 54
3.6.1 Screens and Screen Changers 55

3.7 Heating and Cooling Systems . . 57
3.7.1 Electric Heating 58
3.7.2 Fluid Heating 59
3.7.3 Extruder Cooling 59
3.7.4 Screw Heating and Cooling 62
References 63

4 Instrumentation and Control 65
4.1 Instrumentation Requirements 65
4.1.1 Most Important Parameters 66
4.2 Pressure Measurement 66
4.2.1 The Importance of Melt Pressure . . . 66
4.2.2 Different Types of Pressure Transducers 67
4.2.3 Mechanical Considerations 70
4.2.4 Specifications 72
4.2.5 Comparisons of Different Transducers . 74
4.3 Temperature Measurement 75
4.3.1 Methods of Temperature Measurement 75
4.3.2 Barrel Temperature Measurement . . . 78
4.3.3 Stock Temperature Measurement . . . 80
4.4 Other Measurements 84
4.4.1 Power Measurement 84
4.4.2 Rotational Speed 85
4.4.3 Extrudate Thickness 86
4.4.4 Extrudate Surface Conditions 89
4.5 Temperature Control 91
4.5.1 On-Off Control 91
4.5.2 Proportional Control 92
4.5.3 Controllers 99
4.5.4 Time-Temperature Characteristics . . 101
4.5.5 Tuning of the Controller Parameters . . 107
4.6 Total Process Control 112
4.6.1 True Total Extrusion Process Control . 113
References 114

Part II Process Analysis

5 Fundamental Principles 119
5.1 Balance Equations 119
5.1.1 The Mass Balance Equation . . 119
5.1.2 The Momentum Balance Equation 120
5.1.3 The Energy Balance Equation . 121
5.2 Basic Thermodynamics 122
5.2.1 Rubber Elasticity 126
5.2.2 Strain Induced Crystallization . 128
5.3 Heat Transfer 128
5.3.1 Conductive Heat Transfer . . . 129
5.3.2 Convective Heat Transfer . . . 129
5.3.3 Dimensionless Numbers 129

5.3.4 Viscous Heat Generation 136
5.3.5 Radiative Heat Transport 136
5.4 Basics of Devolatilization 141
5.4.1 Devolatilization of Particular Polymer 146
5.4.2 Devolatilization of Polymer Melts . 147
Appendix 5.1 151
References 153

6 Important Polymer Properties 155
6.1 Properties of Bulk Materials 155
6.1.1 Bulk Density 155
6.1.2 Coefficient of Friction 157
6.1.3 Particle Size and Shape 162
6.1.4 Other Properties 164
6.2 Melt Flow Properties 164
6.2.1 Basic Definitions 164
6.2.2 Power Law Fluid 170
6.2.3 Other Fluid Models 174
6.2.4 Effect of Temperature and Pressure 175
6.2.5 Viscoelastic Behavior 179
6.2.6 Measurement of Flow Properties . 180
6.3 Thermal Properties 192
6.3.1 Thermal Conductivity 192
6.3.2 Specific Volume and Morphology 194
6.3.3 Specific Heat and Heat of Fusion . 198
6.3.4 Specific Enthalpy 199
6.3.5 Thermal Diffusivity 200
6.3.6 Melting Point 202
6.3.7 Induction Time 202
6.3.8 Thermal Characterization 204
6.4 Polymer Property Summary 205
References 207

Functional Process Analysis 210
7.1 Basic Screw Geometry 210
7.2 Solids Conveying 213
7.2.1 Gravity Induced Solids Conveying 213
7.2.2 Drag Induced Solids Conveying 222
7.3 Plasticating 253
7.3.1 Theoretical Model of Contiguous Solids Melting 254
7.3.2 Other Melting Models 272
7.3.3 Power Consumption in the Melting Zone . . . 276
7.3.4 Computer Simulation 278
7.3.5 Dispersed Solids Melting 279
7.4 Melt Conveying 285
7.4.1 Newtonian Fluids 287
7.4.2 Power Law Fluids 299
7.4.3 Non-Isothermal Analysis 310
7.5 Die Forming 344
7.5.1 Velocity and Temperature Profiles 345

7.5.2 Extrudate Swell 352
7.5.3 Die Flow Instabilities . . 354
7.6 Devolatilization 358
7.7 Mixing 362
7.7.1 Mixing in Screw Extruders 363
7.7.2 Static Mixing Devices . 376
7.7.3 Dispersive Mixing . . . 386
7.7.4 Backmixing 398
Appendix 7.1 405
Appendix 7.2 407
Appendix 7.3 407
References 414

Part III Practical Applications

8 Extruder Screw Design 425
8.1 Mechanical Considerations 425
8.1.1 Torsional Strength of the Screw Root 425
8.1.2 Strength of the Screw Flight 427
8.1.3 Lateral Deflection of the Screw 429
8.2 Optimization for Output 434
8.2.1 Optimizing for Melt Conveying 434
8.2.2 Optimizing for Plasticating 444
8.2.3 Optimizing for Solids Conveying 450
8.3 Optimizing for Power Consumption 452
8.3.1 Optimum Helix Angle 453
8.3.2 Effect of Flight Clearance 455
8.3.3 Effect of Flight Width 456
8.4 Single Flighted Extruder Screws 460
8.4.1 The Standard Extruder Screw 460
8.4.2 Modifications of the Standard Extruder Screw . 461
8.5 Devolatilizing Extruder Screws 463
8.5.1 Functional Design Considerations 464
8.5.2 Various Vented Extruder Screw Designs . . . 467
8.5.3 Vent Port Configuration 474
8.6 Multi-Flighted Extruder Screws 476
8.6.1 The Conventional Multi-Flighted Extruder Screws 476
8.6.2 Barrier Flight Extruder Screws 477
8.7 Mixing Screws 491
8.7.1 Dispersive Mixing Elements 491
8.7.2 Distributive Mixing Elements 521
8.8 Scale-Up 525
8.8.1 Common Scale-Up Factors 526
8.8.2 Scale-Up for Heat Transfer 528
8.8.3 Scale-Up for Mixing 529
8.8.4 Comparison of Various Scale-Up Methods . . 531
8.9 Rebuilding Worn Screws and Barrels 532
8.9.1 Application of Hardfacing Materials 533
8.9.2 Rebuilding of Extruder Barrels 536
References 536

9 Die Design 539
9.1 Basic Considerations 539
9.1.1 Balancing the Die by Adjusting the Land Length 540
9.1.2 Balancing by Channel Height 544
9.1.3 Other Methods of Die Balancing 546
9.2 Film and Sheet Dies 547
9.2.1 Flow Adjustment in Sheet and Film Dies . . . 549
9.2.2 The Horseshoe Die 550
9.3 Pipe and Tubing Dies 552
9.3.1 Tooling Design for Tubing 555
9.4 Blown Film Dies 559
9.4.1 The Spiral Mandrel Geometry 561
9.4.2 Effect of Die Geometry on Flow Distribution . 562
9.4.3 Summary Spiral Mandrel Die Design Variables 565
9.5 Profile Extrusion Dies 566
9.6 Coextrusion 567
9.6.1 Interface Distortion 570
9.7 Calibrators 572
References 574

10 Twin Screw Extruders 576
10.1 Introduction 576
10.2 Twin versus Single Screw Extruder 577
10.3 Intermeshing Co-Rotating Extruders 579
10.3.1 Closely Intermeshing Extruders 579
10.3.2 Self-Wiping Extruders 581
10.4 Intermeshing Counter-Rotating Extruders 596
10.5 Non-Intermeshing Twin Screw Extruders 605
10.6 Coaxial Twin Screw Extruder 617
10.7 Devolatilization in Twin Screw Extruders 618
10.8 Commercial Twin Screw Extruders 623
10.8.1 Screw Design Issues for Co-Rotating Twin Screw Extruders 626
10.8.2 Scale-Up in Co-Rotating Twin Screw Extruders 628
10.9 Overview Twin Screw Extruders 630
References 632

11 Troubleshooting Extruders 634
11.1 Requirements for Efficient Troubleshooting 634
11.1.1 Instrumentation 634
11.1.2 Understanding of the Extrusion Process . . . 635
11.1.3 Collect and Analyze Historical Data (Timeline) 635
11.1.4 Team Building 636
11.1.5 Condition of the Equipment 636
11.1.6 Information on the Feed Stock 637
11.2 Tools for Troubleshooting 638
11.2.1 Temperature Measurement Devices 638
11.2.2 Data Acquisition Systems (DAS) 639
11.2.3 Light Microscopy 641
11.2.4 Thermochromic Materials 642
11.2.5 Thermal Analysis 643
11.2.6 Miscellaneous Tools 644

11.3 Systematic Troubleshooting 644
11.3.1 Upsets versus Development Problems 644
11.3.2 Machine Related Problems 644
11.3.3 Polymer Degradation 666
11.3.4 Extrusion Instabilities 681
11.3.5 Air Entrapment 691
11.3.6 Gel Problems 693
11.3.7 Die Flow Problems 696
References 701

12 Modeling and Simulation of the Extrusion Process 706
Paul J. Gramann, Bruce A. Davis, and Tim A. Osswald
12.1 Introduction 706
12.2 Background 707
12.2.1 Analytical Techniques 707
12.2.2 Numerical Methods 708
12.2.3 Remeshing Techniques in Moving Boundary Problems . . 711
12.2.4 Rheology 713
12.3 Simulating 3-D Flows with 2-D Models 714
12.3.1 Simulating Flows in Internal Batch Mixers with 2-D Models 714
12.3.2 Simulating Flows in Extrusion with 2-D Models 717
12.3.3 Simulating Flows in Extrusion Dies with 2-D Models . . . 722
12.4 Three-Dimensional Simulation 725
12.4.1 Simulating Flows in the Banbury Mixer with 3-Dimensional Models 725
12.4.2 Simulating Flows in Extrusion Dies with 3-Dimensional Models 726
12.4.3 Simulating Flows in Extrusion with 3-Dimensional Models . 731
12.4.4 Static Mixers 746
12.5 Conclusions 749
References 749

Index 755