669.94 CAH 2nd ed.

CONTENTS

		Page
Chapter 1	THE HISTORICAL DEVELOPMENT OF PHYSICAL METALLURGY	
1.	Introduction	1
2.	Before the nineteenth century	1
3.	The nineteenth century	4
4.	1900-1940	13
5.	1940-1963	21
Chapter 2	STRUCTURE OF THE PURE METALS	
1.	Electronic structure and the periodic table	33
2.	Bonding forces in crystals	42
3.	Crystal structures of the metallic elements	49
4.	Physical properties related to cohesive forces	57
	References	68
Chapter 3	ELECTRON THEORY OF METALS	
1.	Introduction	71
2.	Atoms in Lattices	71
3.	Statistics of the conduction electrons	77
4.	Quantum mechanical models of the conduction electron	79
5.	Topology of the fermi surface	101
6.	Determination of the fermi surface	108
7.	Impurities and alloys	127
8.	Ferromagnetism	133
9.	Superconductivity	141
	References	155
Chapter 4	STRUCTURE OF SOLID SOLUTIONS	
1.	Solid solubility	159
2.	Terminology (Types of Solid Solutions)	161
3.	Factors Governing Solid Solubility (Hume-Rothery Rules for Primary solid Solutions)	164
4.	The meaning of electron concentration	167
5.	Termination of primary solid solubility	169
6.	The atomic size in solid solution	175
7.	Intermediate phases with wide solid solubility	188
8.	Lattice spacings in solid solutions	197
9.	Defect structures	210
10.	Order in solid solutions	217
	References	224
Chapter 5	STRUCTURE AND PROPERTIES OF SOME INTERMEDIATE PHASES	
1.	Introduction	229
2.	The free energy of intermediate phases	230
3.	Electron concentration and the brillouin zone	232
	References	276
Chapter 6	METALLURGICAL THERMODYNAMICS	
	Introduction	281
1.	First law of thermodynamics	281
2.	Entropy and the second law	282
3.	Conditions for Equilibrium	285
4.	Phase Diagrams	286

5. The Chemical Potential 288
6. Gibbs' phase rule 291
7. Entropy of mixing 292
8. Solubility 295
9. Equilibrium constants 299
10. Surface effects 303
References 306

Chapter 7 PHASE DIAGRAMS AND THEIR DETERMINATION
1. Introduction 309
2. Derivation of simple types of phase diagram from free energy principles 311
3. Ternary systems 324
4. The phase rule 331
5. Rules affecting the construction of equilibrium diagrams 332
6. Quaternary systems 334
7. Application of thermal analysis for the determination of liquid-solid equilibrium 336
8. The segregation method for liquidus determination 345
9. Application of annealing and quenching methods to liquid –solid equilibrium 348
10. Application of annealing and quenching methods to solid state equilibrium 350
11. The application of X-ray methods to the study of equilibrium diagrams 356
12. Electrical conductivity methods 363
13. Dilatometric methods 368
14. Miscellaneous methods 369
15. Special methods 372
16. The investigation of order-disorder transformations 373
17. Conclusion 380
References 380

Chapter 8 DIFFUSION
Introduction 383
1. Fick's laws of diffusion 383
2. Solutions to the diffusion equation 385
3. Atomic movements and D 390
4. Calculation of jump frequency $\mathbf{r}$ 391
5. Vacancy mechanism 393
6. Diffusion in substitutional alloys 394
7. Diffusion along grain boundaries and dislocations 397
8. Non-equilibrium defect concentration 400
References 401

Chapter 9 SOLIDIFICATIONS
Introduction 403
1. Fundamentals 403
2. Atomic kinetics 410
3. Solute manipulation 411
4. Solid-liquid interface morphology 422
5. Defects 442
6. Applications 452
7. Ingot solidification 457
References 467

Chapter 10 PHASE TRANSFORMATIONS
1. General survey of phase transformations 471
2. Nucleation processes 479
3. Theory of growth processes 500
4. Formal kinetics of nucleation and growth transformations 516
5. Transformations at constant composition 527
6. Precipitation from supersaturated solid solution 534
7. Eutectoidal transformations 549
8. Martensitic transformations 552
9. Notation used in chapter 10 580

References 584

Chapter 10a PHYSICAL METALLURGY OF STEELS
1. Iron and steel 589
2. Alloys of Iron 595
3. Transformation reactions 605
4. Deformation and recrystallisation 618
5. Mechanical properties 623
6. Other physical properties 646
7. Solidification 648
References 651

Chapter 11 ELEMENTS OF METALLOGRAPHY
1. Preparation 655
2. The optical microscope 661
3. Special optical techniques 665
4. Electron microscopy 678
5. X-ray microscopy and microanalysis 690
6. Field ion microscopy 699
References 701

Chapter 12 MICROSTRUCTURES
1. Introduction 705
2. Geometric aspects of microstructures 706
3. Quantitative metallography 746
References 783

Chapter 13 DISLOCATIONS
1. The geometry of dislocations in continua 787
2. Elastic properties of dislocation in continua 793
3. Stationary dislocations in crystals 805
4. The geometry of moving dislocations in crystals 815
5. Frictional forces on moving dislocations in otherwise perfect crystals 823
6. Interactions between dislocations and other defects 827
7. Origin of dislocations 836
8. Techniques for the investigation of dislocations 844
References 849

Chapter 14 POINT DEFECTS
Introduction 857
1. Fundamental properties of point defects in metals 857
2. Thermodynamic origin of point defects 865
3. Quenched-in vacancies in metals 872
4. Point defects produced by plastic deformation 894
5. Field ion microscopy of point defect 907
6. Controlled deviations from stoichiometry 909
Acknowledgements 910
References 910

Chapter 15 MECHANICAL PROPERTIES, MILDLY TEMPERATURE DEPENDENT
1. Introduction 921
2. Stress-strain curves 922
3. Effect of temperature on stress-strain curves 934
4. Work-softening 939
5. Theories of work-hardening 940
6. Theory of the temperature dependence of the flow stress 952
7. Luders bands and yield points 955
8. Dependence of the lower yield stress on grain size 959
9. Fracture and fracture stress 961
10. Bauschinger effect 966
11. Mechanical twinning 967

12. Fatigue 970
References 978

Chapter 16 MECHANICAL PROPERTIES, STRONGLY TEMPERATURE-DEPENDENT
1. Creep of metals 983
References 1009

Chapter 17 MECHANICAL PROPERTIES OF SOLID SOLUTIONS AND INTERMETALLIC COMPOUNDS
Introduction 1011
1. Solid solution hardening 1012
2. Precipitation-hardening 1046
3. Order hardening 1059
4. Plasticity of intermetallic compounds 1070
Acknowledgement 1076
References 1076

Chapter 18 MECHANICAL PROPERTIES OF TWO-PHASE ALLOYS
1. Introduction 1083
2. Models proposed to explain yield stress of dispersion-strengthened materials 1085
3. Work-hardening 1110
4. Creep 1116
5. Stress-rupture properties 1123
6. Fracture mode 1124
7. Other strength properties 1126
Acknowledgements 1126
References 1127

Chapter 19 RECOVERY AND RECRYSTALLIZATION
1. Classification of phenomena 1129
2. Recovery 1130
3. Primary recrystallization 1148
4. Grain growth and secondary recrystallization 1181
References 1193

Chapter 20 FRACTURE
1. Phenomenological considerations 1199
2. Brittle solids 1208
3. Semi-brittle solids 1213
4. Ductile solids 1227
5. Composite solids 1228
References 1230

Chapter 21 MAGNETIC PROPERTIES
1. Introduction 1233
2. Ferromagnetism and ferrimagnetism 1239
3. Anisotropy 1246
4. Particle magnetism and torque analysis 1249
5. Magnetic stress and inclusion analysis 1255
6. Magnetic annealing 1258
7. Anisotropic texture 1263
8. Thermomagnetic analysis 1266
References 1270

Chapter 22 PROPERTIES OF SUPERPURE METALS
1. Introduction 1273
2. Purification technique 1274
3. Purity determinations by means of analysis and electrical resistivity measurements 1279
4. Influence of impurities on mechanical properties 1287
5. Influence of impurities on phase transformation of iron 1290
6. Influence of impurities on the elimination of lattice defects 1292

7. Influence of impurities on the interface in iron 1301
References 1308

Subject Index 1313