Index

Primary emphasis in the index is on the mechanisms and theories of friction and wear. The many interconnecting paths of ideas and terminology expressed by the individual authors are recognized in an abundance of cross-references. Materials used in experiments or identified in accounts of experiences are mentioned when they are given special attention in text or illustrations. The symbol (F) following an entry signifies that information is presented in a figure; the symbol (T), in a table. —M.R.H.