

CONTENTS

	page
INTRODUCTION	x
TRACKING DOWN SPURIOUS BANDS IN INFRARED ANALYSIS	13
Chapter 1—OPERATION OF A SPECTROMETER	
1.1 GENERAL DESCRIPTION	18
1.1.1 Single-beam Spectrometers	20
1.1.2 Double-beam Spectrometers	20
1.1.3 Servo Systems	20
1.1.4 Recorder	21
1.2 FAULTS IN OPERATION	21
1.2.1 Optical	22
1.2.2 Mechanical	22
1.2.3 Electronic	23
1.2.4 Recording	23
1.3 CARE OF SPECTROMETERS	23
1.3.1 Mirrors	24
1.3.2 Gratings	24
1.3.3 Prisms, Windows, etc.	24
1.4 PERIODICAL CHECKS	25
1.4.1 Resolution	25
1.4.2 Stray Radiation	26
1.4.3 Photometric Accuracy	27
1.4.4 Wavelength Calibration	29
Chapter 2—SAMPLE HANDLING	
2.1 LIQUID SAMPLES	31
2.1.1 Sealed Cells	31
2.1.2 Demountable Cells	33
2.1.3 Variable Thickness Cells	33
2.1.4 Measurement of Cell Thickness	34
2.1.5 Microcells	35
2.1.6 Care and Maintenance of Cells	35
2.1.7 Disposable Cells	36
2.1.8 Solutions	39
2.2 SOLID FILMS	43
2.2.1 Methods of Producing Films	43
2.2.2 Removal of Film	44
2.2.3 Elimination of Fringes	44

Contents

Chapter 2—*contd.*

2.3	DISPERSIONS	45
	2.3.1 Christiansen Filter Effect	45
	2.3.2 Mulls	45
	2.3.3 Alkali Halide Discs	47
	2.3.4 Use of Frames	49
	2.3.5 Choice of Dispersion Medium	50
	2.3.6 Quantitative Analysis	50
2.4	GASEOUS SAMPLES	51
	2.4.1 Cells	51
	2.4.2 Qualitative Analysis	54
	2.4.3 Quantitative Analysis	55

Chapter 3—THE RECORDING OF A SPECTRUM

3.1	PRESENTATION	57
	3.1.1 General	57
	3.1.2 Light Losses other than Absorption	58
3.2	OPERATING PARAMETERS	58
	3.2.1 General	58
	3.2.2 Programmed Scanning	59
	3.2.3 Speed Suppression	59
	3.2.4 Choosing the Parameters	60
3.3	DIFFERENCE MEASUREMENTS	60
	3.3.1 General	60
	3.3.2 Ordinate Scale Expansion	62
	3.3.3 Automatic Gain or Slit Control	62
3.4	TRACE ANALYSIS	64
	3.4.1 General	64
	3.4.2 Trace Gas Analysis	64
	3.4.3 Derivative Recording	64
3.5	REFLECTION MEASUREMENTS	65
	3.5.1 Specular Reflectance	65
	3.5.2 Attenuated Total Reflectance	65

Chapter 4—THE CHOICE AND HANDLING OF INFRARED OPTICAL MATERIALS

4.1	SODIUM CHLORIDE	67
	4.1.1 General Characteristics	67
	4.1.2 Mechanical Working	68
	4.1.3 Polishing—Professional Method	68
	4.1.4 Polishing for Amateurs	69
4.2	POTASSIUM BROMIDE	70
4.3	SILVER CHLORIDE	71
4.4	CAESIUM IODIDE	71
4.5	CAESIUM BROMIDE	72
4.6	THALLIUM BROMIDE IODIDE	72
4.7	CALCIUM FLUORIDE	72
4.8	BARIUM FLUORIDE	72

Chapter 4— <i>contd.</i>		
4.9	DIAMOND	73
4.10	GERMANIUM	73
4.11	SILICON	73
4.12	SINTERED COMPACTS	74
4.13	PLASTICS	74
Chapter 5—METHODS OF OBTAINING SPECTRA AT HIGH AND LOW TEMPERATURES		
5.1	ABSORBANCE MEASUREMENTS	75
5.2	GENERAL DESIGN CONSIDERATIONS	76
5.3	HOT GAS CELLS	76
5.4	COLD GAS CELLS	80
5.5	HOT CELLS FOR LIQUIDS	80
5.6	HOT CELLS FOR SOLIDS	82
5.7	CELLS FOR USE WITH MOLTEN SALTS AND GLASSES	82
5.8	CELLS FOR LIQUIDS AND SOLIDS AT TEMPERATURES BETWEEN AMBIENT AND 77° K	84
5.9	CRYOSTATS FOR SPECTROSCOPY AT LIQUID HELIUM TEMPERATURES	88
5.10	TEMPERATURE MEASUREMENT	90
Chapter 6—CHROMATOGRAPHY		
6.1	ADSORPTION CHROMATOGRAPHY	92
	6.1.1 Liquid-solid	92
	(a) Column	92
	(b) Thin Layer	92
	6.1.2 Gas-solid	93
6.2	PARTITION CHROMATOGRAPHY	93
	6.2.1 Liquid-liquid	93
	(a) Column	93
	(b) Paper	93
	(c) Compound Separation, Location and Recovery	95
	(d) Contamination Control	95
	6.2.2 Gas-liquid	96
	(a) Column	96
	(b) Collection	97
6.3	SAMPLE PREPARATION FOR INFRARED ANALYSIS	98
	6.3.1 Melted Films	99
	6.3.2 Deposited Films	99
	6.3.3 Oil Mulls	100
	6.3.4 Solutions	100
	6.3.5 Alkali Halide Pellets	101
	(a) Micro Quantities	101
	(b) Freeze Drying	103
	(c) Contamination Control	103
	6.3.6 Vapours	104
6.4	INSTRUMENT OPERATION	104
6.5	FUTURE TRENDS	105

Chapter 7—AQUEOUS SOLUTIONS AND DISPERSIONS

7.1	INTRODUCTION	106
7.2	INSTRUMENTATION	107
7.3	INORGANIC COMPOUNDS	109
7.4	ORGANIC AND BIOLOGICAL COMPOUNDS	110

Chapter 8—NATURAL AND SYNTHETIC FIBRES

8.1	INTRODUCTION	112
8.2	TECHNIQUES WHICH DESTROY THE FIBRE FORM	112
	8.2.1 Potassium Bromide Discs	112
	8.2.2 Nujol Mulls	113
	8.2.3 Solvent Cast Films	113
	8.2.4 Hot-pressed Films	115
	8.2.5 Cold-pressed Discs	115
	8.2.6 Pyrolysis and Hydrolysis	116
8.3	TECHNIQUES WHICH RETAIN THE FIBRE FORM	116
	8.3.1 Microspectroscopy of a Single Fibre	116
	8.3.2 Grid or Pad of Fibres	116
8.4	SOURCES OF ERROR IN QUANTITATIVE MEASUREMENTS WITH FIBRE SAMPLES	118
	8.4.1 Errors in Microspectroscopy	118
	8.4.2 Errors Arising from the Fibre Shape	119
	8.4.3 Errors Arising from Gaps in the Grid	121
	8.4.4 Problems of the Overtone Region	121
	8.4.5 Measurements on Oriented Samples with Unpolarised Light	123
8.5	REVIEW ARTICLES	125

Chapter 9—INSOLUBLE POLYMERS AND RUBBERS

9.1	INTRODUCTION	126
9.2	PRELIMINARY SAMPLE TREATMENT AND EXAMINATION	128
9.3	PREPARATION OF FILMS	128
	9.3.1 The Thickness Required	128
	9.3.2 Microtomed Sections	130
	9.3.3 Pressing and Rolling Techniques—Films from Powders, Latices, etc.	131
	9.3.4 Polymer Gels	132
	9.3.5 Films—Methods for Changing the Thickness of Sheets, or Filaments	132
	9.3.6 Films—Cured after Formation	133
9.4	DISPERSION METHODS	133
9.5	CHEMICAL METHODS OF FORMATION OF A FILM	135
	9.5.1 Solubilisation	135
	9.5.2 Pyrolysis	135
9.6	REFLECTION METHODS	135
	9.6.1 Insoluble Coatings	136
	9.6.2 ATR Method	137

Chapter 10—ORIENTATION OF INORGANIC AND ORGANIC CRYSTALS

10.1	INTRODUCTION—POLARISED SPECTRA OF CRYSTALS	141
10.2	PRODUCTION OF POLARISED INFRARED RADIATION	142
10.3	MICROSPECTROSCOPY	143
10.4	SAMPLE PREPARATION	145
10.5	REFLECTION SPECTRA	146
10.6	SOME EXPERIMENTAL STUDIES ON CRYSTALS	146
10.7	CALCULATIONS FROM REFLECTION SPECTRA	150
	REFERENCES	156