

CONTENTS

| | |
|---|-----------|
| Chapter 1 Theory of Peak Measurement | 1 |
| 1 The Basic Measurements | 1 |
| 2 Experimental Validation | 4 |
| 3 Results Validation | 8 |
| 4 Performance Measurement and Accountability | 8 |
| 5 Chromatographic Peaks and the Gaussian Function | 9 |
| 6 The Exponentially Modified Gaussian Function | 17 |
| 7 Statistical Moments of a Chromatographic Peak | 20 |
| 8 Manual Peak Area Measurement | 25 |
| 9 Errors in Peak Area Measurement | 29 |
| 10 Accurate Representation of the Solute Profile | 31 |
| 11 Sources of Peak Measurement Error | 41 |
| 12 References | 66 |
| | |
| Chapter 2 Manual Measurement of Peaks | 69 |
| 1 Representation of the Detector Signal by Chart Recorder | 69 |
| 2 Measurement Strategies | 73 |
| 3 Measurements Based on a Peak Model | 74 |
| 4 Errors of Manual Measurement | 82 |
| 5 References | 86 |
| | |
| Chapter 3 Digital Integrators and Peak Measurement | 87 |
| 1 A Brief History of Integrators | 87 |
| 2 Current Integrator Status | 93 |
| 3 Digital Measurement of Peak Areas | 107 |
| 4 Filtering and Smoothing the Chromatographic Signal | 116 |
| 5 Location and Measurement of Peaks | 125 |
| 6 Baselines, A More Detailed Discussion | 142 |
| 7 Conclusions | 155 |
| 8 References | 155 |
| | |
| Subject Index | 157 |