

## CONTENTS

<b>I. Introduction</b>	<b>1</b>
<b>II. Mineral oils and related hydrocarbon mixtures</b>	<b>3</b>
1. Introduction and definitions	3
2. Ring analysis and carbon-type analysis of mineral oil fractions	4
3. Correlation of physical constants of mineral oil fractions	38
4. Analysis of branched hydrocarbon mixtures	57
5. Determination of mono- and di-aromatics in mineral oils	68
6. Sulphur compounds in mineral oils	72
<b>III. Application of graphical statistical methods in the determination of the composition of glasses and silicones</b>	<b>75</b>
1. Introduction	75
2. The thermal behaviour of potassium and sodium silicates	77
3. Temperature dependence of the kinematic viscosity of glasses	82
4. The structure of silicones	83
5. Temperature dependence of the kinematic viscosity of silicones	85
<b>IV. Analyses in the field of fatty oils</b>	<b>87</b>
1. Introduction	87
2. Transformation of fatty acid esters into saturated hydrocarbon mixtures	89
3. Direct graphical tracing of transformations of fatty oils	93
4. Graphical analysis of styrenated oils	98
<b>V. Composition of coal</b>	<b>99</b>
1. Demethanation	99
2. Dehydration	100
3. Decarboxylation	101
<b>VI. Graphical statistical methods for studying catalytic processes. Characterization of catalysts by parameters</b>	<b>103</b>
1. Introduction	103
2. Characterization of catalysts	104
3. Applications	105
4. Selection of catalysts	110
References	114
Subject Index	117