

## CONTENTS

1. Origin and Properties of X-rays	1
2. The Measurement of X-ray Intensity. X-ray Detectors	42
3. Absorptiometry with Polychromatic Beams	68
4. X-ray Spectra and X-ray Optics	98
5. Absorptiometry with Monochromatic Beams	128
6. The Determination of Film Thickness	146
7. X-ray Emission Spectrography. General	160
8. X-ray Emission Spectrography. At Low Intensities	210
9. Notes on Equipment. Representative Spectrographs	240
10. Reliability of X-ray Emission Spectrography	266
11. Special Topics	289
Appendix I. Critical Absorption Edges and Energies	307
II. The Approximate Intensities of X-ray Lines	309
III. Wavelengths of Characteristic X-ray Lines	310
IV. Values of the Mass Absorption Coefficients of the Elements in the Region from 0.1 A to 10 A	313
V. Relation of Wavelength to Diffraction Angle for Common Monochromators	318
VI. Bibliography of Element Determinations	328
VII. X-ray Safety	332
Author Index	333
Subject Index	339