

CONTENTS

Chapter 1 Properties of X-rays	3
Chapter 2 Geometry of Crystals	32
Chapter 3 Diffraction I: Directions of Diffracted Beams	81
Chapter 4 Diffraction II: Intensities of Diffracted Beams	107
EXPERIMENTAL METHODS	
Chapter 5 Laue Photographs	149
Chapter 6 Powder Photographs	161
Chapter 7 Diffractometer and Spectrometer Measurements	188
APPLICATIONS	
Chapter 8 Orientation and Quality of Single Crystals	233
Chapter 9 Structure of Polycrystalline Aggregates	281
Chapter 10 Determination of Crystal Structure	324
Chapter 11 Precise Parameter Measurements	350
Chapter 12 Phase-Diagram Determination	369
Chapter 13 Order-Disorder Transformations	383
Chapter 14 Chemical Analysis by X-ray Diffraction	397
Chapter 15 Chemical Analysis by X-ray Spectrometry	421
Chapter 16 Measurement of Residual Stress	447
Appendices	480
General References	529
Chapter References	534
Answers to Selected Problems	543
Index	547