

CONTENTS

National Fire Codes Introduction	3
Approved Equipment, References to other Standards, Units and Definitions	6
Cellulose Nitrate motion Picture Film, Storage and Handling of (No. 40)	40-1
Pyroxylin Plastic in Factories, Storage, Handling and Use of (No. 42)	42-1
Pyroxylin Plastic in Warehouses, Wholesale and Retail Stores (No. 43)	43-1
Combustible Fibres, Storage and Handling of (No. 44)	44-1
Outdoor Storage of Forest Products (No. 46)	46-1
Retail and Wholesale Lumber Storage Yards (No.47)	47-1
Magnesium Storage, Handling and Processing (No. 480)	48-1
Hazardous Chemicals Data (No 49M)	49M-1
Pulverized Fuel Systems, Installation and Operation of (No. 60)	60-1
Starch Factories, Prevention of Dust Explosions in (No. 61A)	61A-1
Terminal Grain Elevators, Prevention of Dust Explosions in (No 61B)	61B-1
Flour and Feed Mills, Prevention Dust Explosions in (No 61C)	61C-1
Pulverized Sugar and Cocoa, Prevention of Dust Explosions in (No. 62)	62-1
Dust Explosions in Industrial Plants, Fundamental Principles for Prevention of (No. 63)	63-1
Country Grain Elevators, Prevention of Dust Ignitions in (No. 64)	64-1
Aluminum Processing and Finishing (No.65)	65-1
Giude for Explosion Venting (No. 68)	68-1
Inerting for Fire and Explosion Prevention (No. 69)	69-1
Fur Storage, Fumigation and Cleaning (No. 81)	81-1
Dehydrators and Dryers for Agricultural Products (No. 93)	93-1
Titanium, Production, Processing, Handling and Storage of (No. 481)	481-1
Zirconium, Fire and Explosion Prevention in Plants Producing and Handling (No. 482M)	482M-1
Table of Materials Subject to Spontaneous Heating (No. 492)	492-1
Spontaneous Ignition of Coal and Other Mining Products (No.493)	493-1
Model State Fireworks Law (No. 494L)	494-1
Explosives and Blasting Agents, Manufacture, Transportation, Storage and Use of (No 495)	495-1
Aluminum Bronze Powder, Prevention of Dust Explosions in Manu facture (No. 651)	651-1
Magnesium Powder or Dust, Explosion and Fire Protection in Plants Production or Handling (No. 652)	652-1
Coal Preparation Plants, Prevention of Dust Explosions in (No. 653)	653-1
Plastics Industry, Prevention of Dust Explosions in the (No. 654)	654-1
Sulfur Fires and Explosions, Prevention of (No. 655)	655-1
Confectionery Manufacturing Plants, Prevention of Dust Explosions in (No. 657)	657-1
Suction and Venting in Grain Elevators, Control of Dust in (No.661)	661-1

Woodworking and Wood Flour Manufacturing Plants, Prevention of Dust Explosions in (No. 664)	664-1
Flammability of wearing Apparel, Classification of (No. 702)	702-1
Fire hazards of Masterials, Identification of (No. 704M)	704M-1
Laboratories Handling Radioactive Materials (No. 801)	801-1
Nuclear Reactors, Fire Protection for (No, 802)	802-1