

CONTENTS

INTRODUCTION	3
HEALTH HAZARDS	11
PROTECTION OF WORKERS	15
Ionising Radiations (Sealed Sources) Regulations 1961	16
GENERAL PRECAUTIONS	18
Adequate shielding	18
Planning and equipment	19
Monitoring	21
Breakage and leakage of sealed sources	22
Supervision and training	23
Tests of radiation exposure	24
Medical supervision	26
Personal protective equipment	27
SPECIAL PRECAUTIONS	27
X-radiography of castings and other articles and of welds	27
X-ray fluoroscopy	32
X-ray crystallography and X-ray spectroscopic analysis	34
Gamma radiography of castings and other articles and of welds	38
The use of radioactive static eliminators	46
The use of beta, gamma and X-ray thickness gauges	49
Radioactive tracer work and the handling of unsealed radioactive Materials	52
APPENDIX	55
REFERENCES	57