

CONTENTS

Preface

xvii

1	DEFINITION AND IMPORTANCE OF CORROSION	1
1.1	Definition of Corrosion	1
1.1.1	Corrosion Science and Corrosion Engineering	1
1.2	Importance of Corrosion	2
1.3	Risk Management	5
1.4	Causes of Corrosion	6
1.4.1	Change in Gibbs Free Energy	6
1.4.2	Pilling–Bedworth Ratio	6
	References	6
	General References	7
	Problems	7
2	ELECTROCHEMICAL MECHANISMS	9
2.1	The Dry-Cell Analogy and Faraday’s Law	9
2.2	Definition of Anode and Cathode	11
2.3	Types of Cells	13
2.4	Types of Corrosion Damage	15
	References	18
	General References	19
	Problems	19
3	THERMODYNAMICS: CORROSION TENDENCY AND ELECTRODE POTENTIALS	21
3.1	Change of Gibbs Free Energy	21
3.2	Measuring the Emf of a Cell	22
3.3	Calculating the Half-Cell Potential—The Nernst Equation	22
3.4	The Hydrogen Electrode and the Standard Hydrogen Scale	24
3.5	Convention of Signs and Calculation of Emf	25

3.6	Measurement of pH	28
3.7	The Oxygen Electrode and Differential Aeration Cell	28
3.8	The Emf and Galvanic Series	30
3.9	Liquid Junction Potentials	33
3.10	Reference Electrodes	34
3.10.1	Calomel Reference Electrode	35
3.10.2	Silver–Silver Chloride Reference Electrode	36
3.10.3	Saturated Copper–Copper Sulfate Reference Electrode	36
	References	37
	General References	38
	Problems	38
	Answers to Problems	40
4	THERMODYNAMICS: POURBAIX DIAGRAMS	43
4.1	Basis of Pourbaix Diagrams	43
4.2	Pourbaix Diagram for Water	44
4.3	Pourbaix Diagram for Iron	45
4.4	Pourbaix Diagram for Aluminum	47
4.5	Pourbaix Diagram for Magnesium	48
4.6	Limitations of Pourbaix Diagrams	49
	References	50
	General References	50
	Problems	50
	Answers to Problem	51
5	KINETICS: POLARIZATION AND CORROSION RATES	53
5.1	Polarization	53
5.2	The Polarized Cell	54
5.3	How Polarization Is Measured	56
5.3.1	Calculation of IR Drop in an Electrolyte	58
5.4	Causes of Polarization	58
5.5	Hydrogen Overpotential	63
5.6	Polarization Diagrams of Corroding Metals	66
5.7	Influence of Polarization on Corrosion Rate	68
5.8	Calculation of Corrosion Rates from Polarization Data	71
5.9	Anode–Cathode Area Ratio	73
5.10	Electrochemical Impedance Spectroscopy	75

5.11	Theory of Cathodic Protection	77
	References	79
	General References	80
	Problems	80
	Answers to Problems	82
6	PASSIVITY	83
6.1	Definition	83
6.2	Characteristics of Passivation and the Flade Potential	84
6.3	Behavior of Passivators	88
6.3.1	Passivation of Iron by HNO_3	89
6.4	Anodic Protection and Transpassivity	90
6.5	Theories of Passivity	92
6.5.1	More Stable Passive Films with Time	95
6.5.2	Action of Chloride Ions and Passive–Active Cells	96
6.6	Critical Pitting Potential	97
6.7	Critical Pitting Temperature	99
6.8	Passivity of Alloys	100
6.8.1	Nickel–Copper Alloys	103
6.8.2	Other Alloys	108
6.9	Effect of Cathodic Polarization and Catalysis	108
	References	109
	General References	111
	Problems	112
	Answers to Problems	113
7	IRON AND STEEL	115
7.1	Introduction	115
7.2	Aqueous Environments	116
7.2.1	Effect of Dissolved Oxygen	116
7.2.2	Effect of Temperature	120
7.2.3	Effect of pH	120
7.2.4	Effect of Galvanic Coupling	127
7.2.5	Effect of Velocity on Corrosion in Natural Waters	129
7.2.6	Effect of Dissolved Salts	131
7.3	Metallurgical Factors	138
7.3.1	Varieties of Iron and Steel	138
7.3.2	Effects of Composition	138

7.3.3	Effect of Heat Treatment	142
7.4	Steel Reinforcements in Concrete	143
	References	145
	General References	147
	Problems	147
	Answers to Problems	148

8 EFFECT OF STRESS 149

8.1	Cold Working	149
8.2	Stress-Corrosion Cracking	150
8.2.1	Iron and Steel	151
8.3	Mechanism of Stress-Corrosion Cracking of Steel and Other Metals	156
8.3.1	Electrochemical Dissolution	157
8.3.2	Film-Induced Cleavage	158
8.3.3	Adsorption-Induced Localized Slip	158
8.3.4	Stress Sorption	158
8.3.5	Initiation of Stress-Corrosion Cracking and Critical Potentials	161
8.3.6	Rate of Crack Growth (Fracture Mechanics)	162
8.4	Hydrogen Damage	166
8.4.1	Mechanism of Hydrogen Damage	167
8.4.2	Effect of Metal Flaws	170
8.5	Radiation Damage	172
8.6	Corrosion Fatigue	173
8.6.1	Critical Minimum Corrosion Rates	177
8.6.2	Remedial Measures	178
8.6.3	Mechanism of Corrosion Fatigue	179
8.7	Fretting Corrosion	180
8.7.1	Mechanism of Fretting Corrosion	182
8.7.2	Remedial Measures	184
	References	185
	General References	188
	Problems	190
	Answers to Problems	190

9 ATMOSPHERIC CORROSION 191

9.1	Introduction	191
9.2	Types of Atmospheres	192

9.3	Corrosion-Product Films	192
9.4	Factors Influencing Corrosivity of the Atmosphere	195
9.4.1	Particulate Matter	196
9.4.2	Gases in the Atmosphere	197
9.4.3	Moisture (Critical Humidity)	199
9.5	Remedial Measures	201
	References	202
	General References	203
	Problems	204

10 CORROSION IN SOILS 205

10.1	Introduction	205
10.2	Factors Affecting the Corrosivity of Soils	206
10.3	Bureau of Standards Tests	207
10.3.1	Pitting Characteristics	208
10.4	Stress-Corrosion Cracking	210
10.5	Remedial Measures	211
	References	212
	General References	212

11 OXIDATION 215

11.1	Introduction	215
11.2	Initial Stages	216
11.3	Thermodynamics of Oxidation: Free Energy–Temperature Diagram	218
11.4	Protective and Nonprotective Scales	218
11.4.1	Three Equations of Oxidation	220
11.5	Wagner Theory of Oxidation	223
11.6	Oxide Properties and Oxidation	224
11.7	Galvanic Effects and Electrolysis of Oxides	227
11.8	Hot Ash Corrosion	229
11.9	Hot Corrosion	229
11.10	Oxidation of Copper	230
11.10.1	Internal Oxidation	231
11.10.2	Reaction with Hydrogen (“Hydrogen Disease”)	231
11.11	Oxidation of Iron and Iron Alloys	232
11.12	Life Test for Oxidation-Resistant Wires	233
11.13	Oxidation-Resistant Alloys	234
11.13.1	Reactive Element Effect (REE)	234

11.13.2 Chromium–Iron Alloys	235
11.13.3 Chromium–Aluminum–Iron Alloys	236
11.13.4 Nickel and Nickel Alloys	236
11.13.5 Furnace Windings	237
References	237
General References	239
Problems	239
Answers to Problems	240

12 STRAY-CURRENT CORROSION 241

12.1 Introduction	241
12.2 Sources of Stray Currents	242
12.3 Quantitative Damage by Stray Currents	244
12.4 Detection of Stray Currents	245
12.5 Soil-Resistivity Measurement	246
12.6 Means for Reducing Stray-Current Corrosion	246
References	247
General References	247
Problems	247
Answers to Problems	249

13 CATHODIC PROTECTION 251

13.1 Introduction	251
13.2 Brief History	252
13.3 How Applied	253
13.3.1 Sacrificial Anodes	254
13.4 Combined Use with Coatings	255
13.5 Magnitude of Current Required	257
13.6 Anode Materials and Backfill	258
13.6.1 Overprotection	259
13.7 Criteria of Protection	260
13.7.1 Potential Measurements	260
13.7.2 Doubtful Criteria	262
13.7.3 <i>Position of Reference Electrode</i>	262
13.8 Economics of Cathodic Protection	263
13.9 Anodic Protection	263
References	265
General References	265

Problems	266
Answers to Problems	267

14 METALLIC COATINGS **269**

14.1	Methods of Application	269
14.2	Classification of Coatings	271
14.3	Specific Metal Coatings	272
14.3.1	Nickel Coatings	272
14.3.2	Lead Coatings	274
14.3.3	Zinc Coatings	274
14.3.4	Cadmium Coatings	276
14.3.5	Tin Coatings	277
14.3.6	Chromium-Plated Steel for Containers	279
14.3.7	Aluminum Coatings	280
	References	281
	General References	282

15 INORGANIC COATINGS **285**

15.1	Vitreous Enamels	285
15.2	Portland Cement Coatings	286
15.3	Chemical Conversion Coatings	286
	References	288
	General References	288

16 ORGANIC COATINGS **289**

16.1	Introduction	289
16.2	Paints	289
16.3	Requirements for Corrosion Protection	291
16.4	Metal Surface Preparation	293
16.4.1	Cleaning All Dirt, Oils, and Greases from the Surface	293
16.4.2	Complete Removal of Rust and Mill Scale	294
16.5	Applying Paint Coatings	295
16.5.1	Wash Primer	296
16.5.2	Painting of Aluminum and Zinc	296
16.6	Filiform Corrosion	296
16.6.1	Theory of Filiform Corrosion	298
16.7	Plastic Linings	299

References	300
General References	301
17 INHIBITORS AND PASSIVATORS	303
17.1 Introduction	303
17.2 Passivators	304
17.2.1 Mechanism of Passivation	304
17.2.2 Applications of Passivators	308
17.3 Pickling Inhibitors	310
17.3.1 Applications of Pickling Inhibitors	312
17.4 Slushing Compounds	313
17.5 Vapor-Phase Inhibitors	313
17.5.1 Inhibitor to Reduce Tarnishing of Copper	314
References	315
General References	316
18 TREATMENT OF WATER AND STEAM SYSTEMS	317
18.1 Deaeration and Deactivation	317
18.2 Hot- and Cold-Water Treatment	321
18.2.1 Cooling Waters	322
18.3 Boiler-Water Treatment	323
18.3.1 Boiler Corrosion	323
18.3.2 Boiler-Water Treatment for Corrosion Control	326
18.3.3 Mechanisms	328
References	330
General References	331
19 ALLOYING FOR CORROSION RESISTANCE; STAINLESS STEELS	333
19.1 Introduction	333
19.2 Stainless Steels	335
19.2.1 Brief History	336
19.2.2 Classes and Types	337
19.2.3 Intergranular Corrosion	343
19.2.4 Pitting and Crevice Corrosion	350
19.2.5 Stress-Corrosion Cracking and Hydrogen Cracking	354
19.2.6 Cracking of Sensitized Austenitic Alloys in Polythionic Acids	359

19.2.7	Galvanic Coupling and General Corrosion Resistance	361
	References	362
	General References	365
20	COPPER AND COPPER ALLOYS	367
20.1	Copper	367
20.1.1	Corrosion in Natural Waters	369
20.2	Copper Alloys	371
20.2.1	Copper–Zinc Alloys (Brasses)	371
20.2.2	Dealloying/Dezincification	372
20.2.3	Stress-Corrosion Cracking (Season Cracking)	374
20.2.4	Condenser Tube Alloys Including Copper–Nickel Alloys	378
	References	379
	General References	381
	Problems	381
	Answers to Problems	381
21	ALUMINUM AND ALUMINUM ALLOYS	383
21.1	Aluminum	383
21.1.1	Clad Alloys	384
21.1.2	Corrosion in Water and Steam	384
21.1.3	Effect of pH	387
21.1.4	Corrosion Characteristics	388
21.1.5	Galvanic Coupling	392
21.2	Aluminum Alloys	393
21.2.1	Stress-Corrosion Cracking	394
	References	396
	General References	397
22	MAGNESIUM AND MAGNESIUM ALLOYS	399
22.1	Introduction	399
22.2	Magnesium	399
22.3	Magnesium Alloys	400
22.3.1	Stress-Corrosion Cracking	402
22.3.2	Coatings	403
22.4	Summary	404

References	405
General References	405
23 NICKEL AND NICKEL ALLOYS	407
23.1 Introduction	407
23.2 Nickel	408
23.3 Nickel Alloys	411
23.3.1 General Behavior	411
23.3.2 Ni-Cu System: Alloy 400—70% Ni, 30% Cu	414
23.3.3 Ni-Cr-Fe System: Alloy 600—76% Ni, 16% Cr, 7% Fe	414
23.3.4 Ni-Mo System: Alloy B—60% Ni, 30% Mo, 5% Fe	415
23.3.5 Ni-Cr-Fe-Mo-Cu System: Alloy G—Ni, 22% Cr, 20% Fe, 6.5% Mo, 2% Cu	416
23.3.6 Ni-Cr-Mo System: Alloy C—54% Ni, 15% Cr, 16% Mo, 4% W, 5% Fe	416
23.3.7 Ni-Fe-Cr System: Alloy 825—Ni, 31% Fe, 22% Cr	417
References	417
General References	418
24 COBALT AND COBALT ALLOYS	419
24.1 Introduction	419
24.2 Cobalt Alloys	420
References	423
General References	423
25 TITANIUM	425
25.1 Titanium	425
25.2 Titanium Alloys	427
25.3 Pitting and Crevice Corrosion	429
25.4 Intergranular Corrosion and Stress-Corrosion Cracking	430
References	432
General References	434
Problem	434
26 ZIRCONIUM	435
26.1 Introduction	435
26.2 Zirconium Alloys	436

26.3 Behavior in Hot Water and Steam	437
References	439
General References	440

27 TANTALUM **441**

27.1 Introduction	441
27.2 Corrosion Behavior	441
References	443
General Reference	443

28 LEAD **445**

28.1 Introduction	445
28.2 Corrosion Behavior of Lead and Lead Alloys	446
28.2.1 Lead–Acid Battery	447
28.3 Summary	448
References	449
General References	449

29 APPENDIX **451**

29.1 Activity and Activity Coefficients of Strong Electrolytes	451
29.2 Derivation of Stern–Geary Equation for Calculating Corrosion Rates from Polarization Data Obtained at Low Current Densities	456
29.2.1 The General Equation	458
29.3 Derivation of Equation Expressing the Saturation Index of a Natural Water	461
29.4 Derivation of Potential Change along a Cathodically Protected Pipeline	467
29.5 Derivation of the Equation for Potential Drop along the Soil Surface Created by Current Entering or Leaving a Buried Pipe	469
29.6 Derivation of the Equation for Determining Resistivity of Soil by Four-Electrode Method	470
29.7 Derivation of the Equation Expressing Weight Loss by Fretting Corrosion	471
29.8 Conversion Factors	474
29.8.1 Additional Conversion Factors	475
29.8.2 Current Density Equivalent to a Corrosion Rate of 1 gmd	475

29.9 Standard Potentials	476
29.10 Notation and Abbreviations	476
References	478

Index	479
--------------	------------