620.14 FRA

CONTENTS

Introduction	1
CERAMICS	
Ceramic Fracture Features, Observations, Mechanisms, and Uses	5
Discussion	102
Marking on Crack Surfaces of Brittle Materials: A Suggested Unified Nomenclature	104
Discussion	107
Fracture Mist Region in a Soda-Lime-Silica Float Glass	110
Discussion	120
Fractography of Slow Fracture in Glass	121
Chemical Analysis of Fracture Surfaces	139
Discussion	155
Scanning Electron Microscopy Techniques and Their Application to Failure Analysis of	
Brittle Materials	157
Fractographic Analysis of Biaxial Failure in Ceramics	185
Fractography of Metalized Ceramics Subatrates	194
Analysis of Failures Associated with Intergranular Fracture	209
Topographic Examination of Fracture Surfaces in Fibrous-Cleavage Transition Behavior	234
Some New Fractographic Features in the Fatigue of High-Strength Aerospace Alloys	252
An Examination of Cleaning Techniques for Post-Failure Analysis	267
Use of "Marker Blocks" As An Aid in Quantitative Fractography in Full-Seale Aircraft Fatigue	;
Testing: A Case Study	285
Fractographic Observations of Fatigue Crack Growth in a High Strength Steel	309
Fractographic Analysis of the Primary Oil Pump Shaft Fracture from a Steam Turbine	328
Fractographic Analysis of a Steam Turbine Disk Failure	346
Failure Analysis of a Hydraulic Turbine Shaft	368
Fractography of Metal Matrix Composites	387
PANEL REPORTS	
Ceramic Fractography Research Needs	399
Suggestions for Research in Fractography and Failure Analysis of Ceramics	400
Future Research Needs in Ceramic Fractography and Failure Analysis	401
SUMMARY	
Summary	409
Index	413