

CONTENTS

	Page
Chapter I/ Solid Surfaces	1
Why Adhesives Are Needed	1
Transition Layers Rather Than Surfaces	3
Surface Roughness	3
Numerical Data on Surface Roughness	15
Surface Porosity	16
Variability Along the Surface	17
Variability Across the Surface	18
Gas Adsorption	22
Adsorption From Solutions	26
References	27
Chapter II/ Adhesive and Other Joints	29
Fastening Devices	29
Solid-to-Solid Adhesion	30
Classification of Adhints	34
Hooking Adhints	35
References	42
Chapter III/ Formation of Adhints	43
Cleaning of the Adherend Surfaces	43
Wetting	49
Measurement of Contact Angles	54
Hysteresis of Wetting	59
Rate of Wetting, Removal of Air	63
References	89
Chapter IV/ Tack	91
Text	91
References	118
Chapter V/ Setting	120
Weakness Caused by Setting	128
Flaws in the Bulk of The Adhesive	133
Time of Set	135
References	136
Chapter VI/ Final Strength of Adhints	137
Improbability of True Adhesional Failures	137
Older Theories	150
The Breaking Stress	153
References	162
Chapter VII/ Improper Adhints	164
Weak Boundary Layers	164
References	189
Chapter VIII/ Stresses in Proper Adhints	192
Frozen Stresses	192
Butt Joints	204
Block Joints	213
Lap Joints	215

Peeling	242
Work of Fracture	258
References	261
Chapter IX/ Experimental Strength of Adhins	264
Adhins of Different Types	265
Strength and Dimensions of an Adhint	273
Adhesives in Bulk and In Situ	289
Strength of Adhins and of Adhesives	293
Effect of The Adhesive Composition	299
Rate of Loading and of Rupture	303
Effect of Temperature	309
Effect of Environment	313
References	316
Chapter X/ Tests	319
Text	319
References	328
Chapter XI/ Summary for the Practical Man	330
Text	330
Author Index	337
Subject Index	345