

Contents

Editor's Note	ix
Preface	xi
Introduction	xiii

Part I. Theoretical Basis

1. Fatigue Diagrams	1
1.1 Wöhler tests	1
1.2 Types of cyclic stress	2
1.3 Load spectrum	4
1.4 $S-N$ curves, and an outline of the metal-physics aspects of fatigue	5
1.5 The equations of the $S-N$ curves	6
1.6 Determination of fatigue limit	16
1.6.1 "Staircase" method of determining fatigue limit	16
1.6.2 Rapid method of determining fatigue limit: the Locati method	18
1.7 Fatigue diagrams	21
1.7.1 Smith diagrams	21
1.7.2 Haigh diagrams	24
1.7.3 Moore-Kommers-Jasper diagrams	25
1.7.4 Use of data in literature	26
1.8 Fatigue fractures: their causes and appearance	26
1.8.1 Causes	26
1.8.2 Appearance	27
2. Fatigue Diagrams of Various Materials	32
2.1 Steel	32
2.2 Cast iron	37
2.3 Malleable cast iron	37
2.4 Light alloys	38
2.5 Non-ferrous metals	39
2.6 Plastics	39
3. Effect of Various Factors on Fatigue Strength	40
3.1 Surface finish	40
3.2 Shape and dimensions	42
3.3 Temperature	44
3.3.1 Elevated temperatures	44
(a) Steels	44
(b) Non-ferrous metals and light alloys	45
3.3.2 Low temperatures	46
3.4 Surface treatment	46
3.4.1 Surface hardening	46
3.4.2 Surface rolling	48