

CONTENTS

CHAPTER	PAGE
INTRODUCTION	13
CLASSIFICATION OF COPPER ALLOYS	15
II. GENERAL MACHINING PRACTICE	25
Tool Design—Rigidity—Cutting-Tool Materials	
GENERAL MACHINING PRACTICE (CONT.)	35
Speeds and Feeds—Cutting Fluids	
MISCELLANEOUS MACHINING OPERATIONS	
Turning—Shaping and Planing—Facing—Parting and Forming —Automatics—Knurling and Thread Rolling—Porous Bearings	
DRILLING—BORING—REAMING—SCREWING—TAPPING	55
VI. MILLING—SAWING—BROACHING—GRINDING	71
SELECTION OF COPPER ALLOYS FOR MACHINING PURPOSES	
STANDARD SPECIFICATIONS	104
APPENDICES	
I. Cutting Speed Table	105
II. Weight of Rod	107
III. Decimal Equivalents of an Inch	108
IV. Stress Conversion Table	109
BIBLIOGRAPHY	110
INDEX	112
C.D.A. PUBLICATIONS	