

Contents

| | PAGE |
|--|-----------|
| PREFACE TO THE SECOND EDITION | v |
| PREFACE TO THE FIRST EDITION | vi |
| SECTION I | |
| DRILLING | |
| CHAPTER I | |
| DRILLS AND DRILLING MACHINES. | 3 |
| Material and nature of work to be considered—Advantages of three- and four-lipped drills—Deep-hole drilling—Tungsten carbide-tipped drills—Drilling as a roughing operation—Maintaining holes centers—How twist drills are made. | |
| CHAPTER II | |
| DRILL POINTS AND TROUBLES | 7 |
| Twist drill details—Variety of drill points—Grinding drills—Lip clearance, points, angle, and web—Drill chipping—Causes of drill troubles—Use of multi-flute drills—Core drill application and treatment—Drill-point angles for different materials. | |
| CHAPTER III | |
| DRILL SHANKS, SPEEDS, AND FEEDS. | 18 |
| Nomenclature—Details of drill shanks—Plug gage for “slow” tapers—Ring gage for “slow” tapers—Self-holding tapers and key drive—Standard taper shank drills—Average feeds and cutting speeds—Decimal equivalents of twist-drill gage numbers—Straight shank drills. | |
| CHAPTER IV | |
| GENERAL DRILLING INFORMATION. | 31 |
| Power required for drilling—Diameters of drilled holes—Hardness of drills—Drilling brass—Drilling plastic materials—Lubricants for drilling—Drilling of moulded plastics—How wood should be drilled—The operation of counterboring. | |
| CHAPTER V | |
| DEEP-HOLE DRILLING. | 39 |
| Safe speeds and feeds—Methods followed in deep holes—The Revociper—Getting rid of chips—Oil-well tool work—Jig for deep | |

holes—Methods in small deep holes—Various ways of driving straight shank drills—High speed bench drill—Drilling very small holes.

CHAPTER VI

VARIOUS DRILLING OPERATIONS 50

Drilling glass crystals—Useful fixture for drilling machines—Chucks on drill tables—Vises and V blocks—Truing the drill spindle—Weight of metal removed in drilling—Drilling heads—Drill chart for use with balancing machine—Combined multiple drilling fixture and drill head—Construction of a multiple-gearred drilling head—Station-type drill in machines.

CHAPTER VII

TYPES OF DRILLING MACHINES. 63

Modern vertical-spindle machines—Modern speed and feed selectors—Using a radial in building lathes—Radial drilling operations—Radials under production—Convenience of a floor pit—Countersinking locomotive rod bushings—Five-direction drilling at once—Way-drilling machines—Hydraulic-feed drilling machine—Self-contained drilling units—Unit construction in drilling machines.

SECTION II

REAMING AND TAPPING

CHAPTER VIII

DESIGN, CONSTRUCTION, AND USE OF REAMERS. 77

Requirements in finishing holes—Maintaining reamer sizes—Rake or hook on reamers—The care of reamers—Selection of reamers—Shell-type reamers—Amount of stock to be removed—Salvage of solid reamers—Reaming of tapered holes—Machine reaming of taper holes—Bridge reamers—The combined drill and reamer—Speeds and feeds of reamers—Sharpening reamers—Backing off and honing—Machine sharpening of reamers.

CHAPTER IX

TAPS AND SCREW THREADS. 95

Definitions of taps and threads—Drilling for tapped holes—Effect of too large or too small drill—Tolerances on drilled holes—Basic thread dimensions and tap drill sizes—Selecting the right tap—Machine screw taps—Three and four fluted taps—Super crest taps—Modern die heads—Speeds of taps—Tapping Bakelite—Lubrication for taps and dies—Screw machine work—Lubrication for copper, aluminum, etc.—Stud fits in cast iron and in aluminum

CONTENTS

ix
PAGE

—Oil lubricants—Nut tapping by machine—Standard tolerances for screw threads—Measurement of taper taps—Tapping taper threads.

SECTION III

PLANERS AND SHAPERS

CHAPTER X

PLANERS, SHAPERS AND SLOTTERS. 109

Distinction in type of work—The slotter, a vertical shaper—Necessary foundation—Erecting methods—Standard leveling blocks—Levelling heavy tools—Testing planer-bed alignment—Various methods of testing ways, etc.—Checking equipment—Tests with surface gage—How cross rail is tested for level—Use of dial indicator and square on cross rail and side rail.

CHAPTER XI

CARE OF PLANERS 116

The skill of planer operator—Roughing and finishing cuts—Methods of clamping work—Clamps and step blocks—Uses of self-contained clamps—Handy jacks—Types of planer stops—Jack base and heads—Suggestions for setting work—Squaring plates—Use of aligning strips and jacks—Ways of holding thin work—Holding work in the vise—Holding round bars.

CHAPTER XII

PLANER TOOLS. 125

Heavy tool holders—Planer tool at work—V finishing tool—Double tools for slots—Finishing tools—Spring tool “goose neck” type—Broad-face finishing tools—Cutting rack teeth with a gear cutter on the planer.

CHAPTER XIII

METHODS OF DRIVING PLANERS. 131

Helical gearing in Gray planer—Hydraulic shaper-planer—Sellers planer drive—Planer speeds—Reversing motor drive—Application of belts—Recommended cutting speeds—Horsepower required for different size planers—Effect of flywheel on planer drive—Cuts and feeds—Table for calculating power required for various cuts—Roughing and finishing cuts—Carbide tools.

CHAPTER XIV

PLANERS AND THEIR WORK 140

Planing a big boring mill rail—Strip planing of press beds—Using rotating tool in slots—Multiple tool head for rail guides—Setting up awkward work—Form planing—Planing miller knee—How

overhung tools are supported—Radius planing methods—Use of magnetic chuck—The open-side planer at work—Planing helical lobes for pump—Railway planing operations—Shoe wedge and cross head operations—Crown brass finishing.

CHAPTER XV

SHAPERS. 153

Three kinds of shapers—Modern shaper construction—Cutting speeds on shapers—Shaper with swivelling table—Methods of driving shapers—Section of shaper drive—Comparative cam-velocity diagram for both strokes—Hydraulic shaper—Feeds and power movements.

CHAPTER XVI

SHAPER TOOLS AND WORK. 159

Shaping die openings—Pressure angle on tool at different heights—Small hole shaping—Knurling in the shaper—Small radius shaping—How keyways can be shaped in special work—Rigid tool holders and keyseating tools—Rolling name on round work—Stamping and knurling—Locomotive crosshead and driving-box fixtures—Shaping crown brasses—Shoe and wedge work on shaper—Rod brass fixtures.

CHAPTER XVII

THE SLOTTING MACHINE. 169

A typical machine—Heavy type slotter—Locomotive work on slotter—Locomotive frame slotter with three heads—Slotting crown brasses—Operations on a special cam—Details of tools—Method of slotting ends of connecting rods.

SECTION IV

MILLING

CHAPTER XVIII

PRIMARY MILLING OPERATIONS. 177

Application of the miller—The Universal machine—Speeds and feeds—Speeds affected by different materials—Performance of thin saws—Chip thickness—Self-contained work measurements—Formulas for surface speeds—Feed per tooth a basis of cutter capacity—Relation between cutter diameter and feed per minute and per tooth—General data on speeds and feeds—Constants for materials for different millers—High speed cutter rates—Formula for high-speed cutter feeds—Effect of progressive working conditions—Charts for speeds and feeds—Consideration of roughing and finishing operations—General suggestions.

CONTENTS

xi

| | PAGE |
|--|------|
| CHAPTER XIX | |
| GENERAL MILLING OPERATIONS | 193 |
| The dividing head or spiral head—Typical milling applications—Milling with single and gang cutters—Feed rates determined by smaller cutter in gang—Removal of metal—Lighter cuts may save time and material in some instances—Clamping work in rigid vise—Example of typical milling operations—Slot milling cuts—Various types of slots and channels—Milling deep grooves—Metal slitting—The cutting of thin materials—Hollow grinding of sides of saws—Methods of centering cutters. | |
| CHAPTER XX | |
| TYPES OF MILLING MACHINES | 206 |
| Universal, plain, and vertical milling machines (Cincinnati) with all parts named—Brown & Sharpe universal machine—Becker-type vertical miller—Van Norman machines and applications—Manufacturing millers—Lincoln type—Planer-type milling machines (Sellers)—Large milling work on planer-type machine—Newton rotary machines—The drum-type milling machine—Rotary work on drum-type machines. | |
| CHAPTER XXI | |
| PLANETARY MILLING MACHINES | 222 |
| Profiling machines—Profiling operations—Profile miller on die work—Die sinking—Bench milling machines—Slotting and gear cutting—Various gear jobs on bench miller—Cam cutting—Whitney hand miller—Typical miller work—Piston work on hand miller—Unit construction on milling machines—Standard miller spindle taper—Changing tools in modern milling-machine spindle—Quick change adapter. | |
| CHAPTER XXII | |
| UNIVERSAL INDEXING CENTERS | 241 |
| Trunnion type index head—Brown & Sharpe quadrant index head—Index plate and sector—Direct indexing—Selecting change gears—Formulas for gearing—Spacing for quarter degrees—Aliquot or fractional spacing—Differential indexing—Cincinnati dividing head—Cincinnati wide-range divider—Index table for wide range divider—Section through dividing-head spindle—Dividing prime numbers to 500—Two-part worm—Kearney & Trecker Hypoid dividing head—Wide range divider. | |
| CHAPTER XXIII | |
| MILLING-MACHINE ATTACHMENTS | 260 |
| Vises for miller table—Plain indexing centers—Gear indexing attachment—Vertical spindle attachments—Compound and uni- | |

versal milling attachments—Rotary and slot-milling attachments—Reciprocating slotter for miller—Rack milling attachments—Motor driven universal attachment—Using the universal miller—Universal head on die work—Fly cutter for forming tools—Milling screw machine cams—Milling spiral with Hypoid head—Notching clutch jaws—Thread cutting and hobbing—Gearing diagram for short leads—Circular milling.

CHAPTER XXIV

CUTTING HELICES ON THE MILLING MACHINE 278

Selecting change gears for indexing head—Formulas for figuring gearing—Angular setting of table—Development of helix angles—Table for plain and differential indexing—Fluting taps and reamers—Setting cutters and index canterers—Testing centering of cutter—Examples of milling in automotive work—Milling cylinder blocks—Using indexing fixture—Gang fixture for clutch pedals—Gashing bevel gears—Controlling milling cutter by cam—Railroad-shop milling—Driver-box work—Shoe and wedge operations—Milling crosshead shoes—Slab milling connecting rods—Milling rod ends—Forming airplane-motor rod end—Worm gear work.

SECTION V

MILLING CUTTERS

CHAPTER XXV

MILLING CUTTERS 311

Plain cutters—Terms used for cutter teeth, etc.—Helical, side-cutting, end mills, and face-milling cutters—Classification of cutters based on relief—Mounting cutters—How cutters are designated—Details of all standard cutters—Details of types of end mills—Formed gear cutters and sprocket mills—Hobs, and helical mills, shell mills, and other forms—Inserted-tooth-facing cutters—Intermittent teeth—Climb milling and cutting-up method—Keys, arbors, and collars—Cutter-arbor diameters.

CHAPTER XXVI

MILLING CUTTERS AND THEIR USES. 323

Staggered-tooth plain cutters—Metal-slitting saws—Rake of cutter teeth—Power required for milling—Power required for cast iron—Power for steel milling—Influence of rake—Slabbing cuts and power requirements—Influence of helix angle—Grinding of helical cutters—Rigid machines necessary.

CHAPTER XXVII

CUTTERS FOR MILLING LARGE PLAIN SURFACES. 335

Sweep milling and slab methods—Profile vs. formed-type milling

CONTENTS

xiii
Page

cutters—Sectional construction for wide formed cutters—Helical fluted formed cutters—End mills—Fine-tooth or coarse-tooth types—Helix angle and cut—End mill shanks—Speeds and feeds—Woodruff keyseat cutters—Helical cutters—Cutters for milling slots.

CHAPTER XXVIII

HIGH-SPEED AND OTHER MILLING CUTTERS 343

Hardening temperatures for high-speed cutters—Tungsten and tantalum carbide cutters—Stellite-blade cutters—Inserted-blade cutters—Proportions of cutters for inserted blades—Construction of inserted types of cutters—Details of blade-holding methods—Speeds for carbide cutters—Roughing and finishing rates—Characteristics of tungsten carbides—Suggestions for using new alloy steels.

CHAPTER XXIX

CARE OF MILLING CUTTERS 351

Keeping cutters sharp—Maintenance of formed milling cutters—Sharpening profile-type cutters—Mounting cutters in the sharpening machine—How grinding wheel should run—Clearance angles—Suggestions for cutter teeth—Selecting proper wheels—Grinding cemented-carbide milling cutters—Set-up for various classes of carbide mills—Mounting cup wheels—Checking cutter in fixture—Grinding outside diameter and faces of teeth—Inserted-tooth face mills—Sharpening inserted-tooth cutters—Heel clearances—Use of dial indicator—Checking periphery, etc.—Engraving cutter details—British engraving cutters—Heavy-slab milling cutter—Channeling locomotive connecting rods—Milling pump impeller—Fluting large helical mill—Unusual gang of cutters—Special undercutting mill.

SECTION VI BROACHING

CHAPTER XXX

GENERAL INFORMATION ABOUT BROACHING 367

Simple pull broach—Proportions of broach teeth and spacing—Detail of finishing tooth—Shallow teeth on small broaches—Notched broach teeth to break chips—Coolants for different metals—Preserving original form of tooth—Chip per tooth—Broaching speed—Clearance or rake—Number of teeth in contact—Minimum depth of tooth.

| | PAGE |
|--|------------|
| CHAPTER XXXI | |
| COMMERCIAL BROACHING | 371 |
| Types of broaching machines—Hydraulic designs—Broaching round holes—Connecting-rod work—Division of chip per tooth—Push broach for bronze bushing—Broaching square holes—Dimensions of square holes (chart)—Charts of 4-, 6-, and 10-spline dimensions and fits—Broaching rectangular holes—Short broaches—Fixtures, etc., for work—Set of rectangular-hole broaches—Die for holes near edge—Form of keyseater—Spline broaching—Holders for pull broaches—Broaching helical keyways—Design of broaching tools—Sharpening broaches—Broaching open-end wrenches. | |
| CHAPTER XXXII | |
| EXTERNAL OR SURFACE BROACHING | 395 |
| Early user of surface broaching—What surface broaching is—Advantages—Maximum efficiency of cutting edges obtained—Wide field covered by external broaching—Accuracy of surface broaching—Design factors—Effect of material—Examples of broaching—Continuous broaching—Work holders for continuous broaching—Rotary machine—Curved broaches—Summary of broaching practice—Connecting-rod work fixtures—Broaching half bore and face on rods, and caps—Broaching sides of bolt bosses—Fixture for surfacing flat irons—Steering knuckle work—Horizontal machine for broaching cylinder blocks—Cost and data of broaching—Automobile parts broaching details. | |
| INDEX | 419 |
| WARTIME DATA SUPPLEMENT | 433 |
| Deep-hole Drills—Drills and Reamers for Antitank Rifles—Recommended Drill Points—Milling Crank Chucks—Line-engine Cylinder Head—Machining Propeller Blades—Milling Helical Clutch Jaws—Multiple Fixtures Save Time—Contour Milling and Die Sinking—Profiling Machines—Six-point Locking Plates—Making Drop-forging Dies—High-speed Milling Attachments—Malleable-iron Cutter Bodies—Hyper-Milling—Milling Cutters with Plastic Bodies—Feeds and Speeds for Milling with Carbides—Broaching Machines—Broaching Connecting Rods—Splining a Propeller Hub—Broaching a Tank Lever. | |
| INDEX TO WARTIME DATA SUPPLEMENT | 475 |