

Contents

Introduction	1
<i>i</i> Regulations Governing Airborne Pollutants	1
<i>i.i</i> U.K. Legislation	1
<i>i.ii</i> Legislation in the United States	3
<i>ii</i> Maximum Recommended Concentrations of Airborne Pollutants	3
<i>ii.i</i> U.K. Recommendations	3
<i>ii.ii</i> Foreign Recommendations	5
<i>iii</i> A Systematic Approach to Airborne Pollution Monitoring	6
<i>iii.i</i> The Physical State of Pollutants	6
<i>iii.ii</i> The Selection of Sampling Areas	8
<i>iii.iii</i> Interpretation of Results	10
<i>iii.iv</i> Recommending Remedial Action	12
<i>iv</i> References	13

PART I: THE WELDING INDUSTRY

1 Airborne Pollutants in Welding	17
1.1 The Emission of Welding Fume into the External Environment	17
1.1.1 Quantities of Welding Fume Emitted	17
1.1.2 The Mode of Emission	18
1.1.3 Effects of Emissions	18
1.2 Typical Particulate Fume and Gaseous Pollutants to be Encountered in Different Welding Processes	19
1.2.1 Manual Metal Arc Welding	19
1.2.2 Gas Shielded Welding	21
1.2.3 Mode of Formation of Pollutant Gases	22
1.2.4 Flame Processes	22
1.2.5 Other Processes	23
1.2.6 The Workpiece: Paints, Primers, Coatings, and Solvents	23
1.3 References	24
2 Sampling of Welding Workshop Atmospheres	28
2.1 General Considerations	28
2.2 Breathing-zone Sampling	29
2.2.1 Location of the Breathing Zone	29
2.2.2 Sampling for Particulate Fume	30
2.2.3 Sampling for Pollutant Gases	40
2.2.4 Strategy and Errors in Breathing-zone Sampling	47

2.3	Background Sampling	49
2.3.1	Siting of Background Samples for Comparison with Occupational Hygiene Standards	50
2.3.2	Background Sampling for Ventilation Engineering Purposes	51
2.3.3	Equipment for Background Sampling	54
2.4	Sampling the Amount of Airborne Pollutants Generated per Unit Consumable	57
2.4.1	Development of a Fume Box for Measuring Particulate Fume	57
2.4.2	Alternative Fume Box Techniques	58
2.4.3	The Swedish Fume Box Technique	59
2.5	Community Fume Measurements	66
2.6	References	66
3	Analysis of Welding Fumes and Pollutant Gases	69
3.1	Introduction	69
3.2	Gravimetric Analysis of Fume	69
3.3	Different Techniques of Fume Analysis	71
3.3.1	Atomic Absorption Spectrophotometry	73
3.3.2	Flame Emission Spectroscopy	75
3.3.3	Colour Methods	76
3.3.4	Ion Specific Electrode Technique	77
3.3.5	Gravimetric Methods	77
3.3.6	Inert Gas Fusion for Oxygen	78
3.4	X-Ray Fluorescence	79
3.5	X-Ray Diffraction	80
3.6	Particle Size Measurements	81
3.7	Modern Spectroscopic Techniques	82
3.8	Pollutant Gases	84
3.8.1	Organic Gases	84
3.8.2	Ozone	85
3.8.3	Oxides of Nitrogen	87
3.8.4	Carbon Monoxide	89
3.8.5	Carbon Dioxide	91
3.8.6	Oxygen	91
3.9	References	92
 PART II: THE SURFACE COATINGS INDUSTRY		
4	Origin of Airborne Pollutants in the Surface Coatings Industry	97
4.1	Airborne Pollutants Associated with Surface Coatings Components	97
4.1.1	Definition of Terms	97
4.1.2	Airborne Pollution Hazards Associated with the Manufacture and Use of Binders	99

4.1.3 Airborne Pollution Hazards Associated with the Use of Solvents	106
4.1.4 Airborne Pollution Hazards Associated with the Use of Pigments	108
4.1.5 Airborne Pollution Hazards Associated with the Use of Additives	112
4.2 Airborne Pollution Hazards Associated with the Manufacture of Surface Coatings	114
4.3 Airborne Pollution Hazards Associated with the Use of Surface Coatings	119
4.3.1 Airborne Pollution Hazards during Substrate Preparation	119
4.3.2 Airborne Pollution Hazards during Surface Coatings Application	122
4.4 Summary	126
4.5 References	126
5 Collection and Analysis of Gaseous Atmospheric Pollutants in the Surface Coatings Industry	130
5.1 Solvents	131
5.2 Thermally Induced Emissions	136
5.3 Isocyanates	140
5.4 Vinyl Monomers	142
5.5 Miscellaneous Volatile Pollutants	144
5.6 Summary	148
5.7 References	149
6 Collection and Analysis of Particulate Atmospheric Pollutants in the Surface Coatings Industry	151
6.1 Sample Collection Methods	152
6.1.1 Dustfall Collection	152
6.1.2 Impingers	152
6.1.3 Filters	157
6.2 Analysis of Soluble Organic Particulates	158
6.2.1 Solvent Extraction	158
6.2.2 Chromatographic Separation	159
6.2.3 Qualitative and Quantitative Analysis	161
6.2.4 Specific Analytical Methods	163
6.3 Analysis of Insoluble Organic Particulates	164
6.4 Analysis of Soluble Inorganic Particulates	165
6.4.1 Definition	165
6.4.2 Extraction Techniques	165
6.5 Determination of Total Inorganic Particulates	166
6.5.1 Determination of Acid and Alkali Mists	166
6.5.2 Qualitative Elemental Analysis	167
6.5.3 Quantitative Elemental Analysis	169

6.5.4 Determination of Silicon-based Materials	169
6.6 References	172
7 Future Trends Relating to Sampling and Analysis in the Welding and Surface Coatings Industries	175
7.1 Future Technical Developments	175
7.2 Future Trends in Aspects of Pollutant Regulation	176
Index	179