

## CONTENT

	Page
Preface	ix
Part One : INTRODUCTION TO STATISTICAL QUALITY CONTROL	
1. Using statistical quality control	1
2. Background to the procedures	6
Part Two : SQC PROCEDURES	
Guide to the procedures	22
Procedure 1 Estimating the quality standard by testing attribute data for homogeneity : uniform Sample size : traditional method	25
Procedure 2 Estimating the quality standard by testing attribute data for homogeneity : uniform Sample size	32
Procedure 3 Estimating the quality standard by testing attribute data for homogeneity : variable Sample size	47
Procedure 4 Setting up and operating a number defective control chart	56
Procedure 5 Setting up and operating a control chart for defects per unit	62
Procedure 6 Testing a run of attribute data for conformity with standard	73
Procedure 7 Comparison of two quality standards : attributes	79
Procedure 8 Setting up and operating cusum plans when quality is assessed by counting defective	85
Procedure 9 Estimating within-sample variability : traditional method	89
Procedure 10 Estimating within-sample variability : alternative method	97
Procedure 11 Test of measurement data for homogeneity between samples : traditional method	104
Procedure 12 Test of measurement data for homogeneity between samples : preferred method	110
Procedure 13 Control charts for means and ranges	118
Procedure 14 Control charts with a wandering mean	123
Procedure 15 Comparison of a mean range with a standard	138
Procedure 16 Comparison of the mean of means with a standard	143
Procedure 17 Cusum methods for measurement	146
Procedure 18 Cusum charts for measurement	150
Procedure 19 Setting up a new process	154
Part Three : TABLES	
Table 1 Control limits for Poisson distribution	162
Table 2 control limits for $X^2$	164
Table 3 Confidence interval for Poisson distribution	166
Table 4 Control limits for sample ranges	167
Table 5 Control limits for (maximum range) / (minimum range)	168
Table 6 Control limits for sample means	170
Table 7 Limits for the ratio (range of means) / (standard range)	171
Table 8 Limits for the ratio (range of means) / (standard range)	172
Table 9 Control limits for (actual mean range) / (standard mean range)	173
List of Symbols	175
Index	177