

Contents

1	Successful Development and Production of Injection Molded Parts	1
1.1	Development of Injection Molded Plastic Products	2
1.2	The Design Process	4
1.3	Product Specifications (Data Collection and Product Specifications)	7
1.4	An Overview of the Four Building Blocks of an Injection Molded Plastic Part	14
1.4.1	Material	14
1.4.2	Product Design	17
1.4.3	Mold Design and Machining	19
1.4.4	Process.	20
1.5	Integration of Product Development Through Computer-Aided Engineering.	21
1.6	Summary of the Characteristics, Advantages, and Disadvantages of Plastics.	22
1.6.1	Advantages of Plastics	22
1.6.2	Disadvantages of Plastics.	25
2	Thermoplastics in Injection Molding.	27
2.1	Polymer Structure.	27
2.1.1	Thermoplastic Materials	28
2.1.2	Amorphous Thermoplastic Polymers	29
2.1.3	Semicrystalline Thermoplastic Polymers.	29
2.1.4	Thermoset.	30
2.2	Melt Rheology: Polymer Flow During Injection Molding	30
2.2.1	Non-Newtonian Flow	30
2.2.2	Temperature Effects on Viscosity	32
2.2.3	Laminar Flow	33
2.2.4	Fountain Flow	33
2.2.5	Velocity and Shear Variations Across a Flow Channel	34
2.2.6	Common Viscosity Models	36
2.2.7	Molecular Weight Distribution Effect on Viscosity.	37
2.3	Shrinkage of Plastic Materials	38
2.3.1	Volumetric Shrinkage	38
2.3.2	Volumetric Shrinkage of Semicrystalline Polymers.	39
2.3.3	Mold Cavity Dimensions.	41
2.4	Mechanical Properties.	42
2.4.1	Definitions	42
2.4.2	Modulus.	43

2.4.3	Viscoelastic Characteristics of Plastic Materials	46
2.4.4	Deriving the Modulus for Plastic Materials	48
2.4.5	Other Basic Mechanical Properties and Testing Techniques	51
2.4.6	Other Useful Properties for Design	52
2.4.7	Sources of Error in Material Data	53
2.5	CAE Analyst Material Guidelines	53
	References	55
3	Injection Molding	56
3.1	The Process: An Overview	56
3.2	Injection Molding Parameters	58
3.3	Mold Filling	59
3.4	Assumptions at Start of Filling	61
3.5	Process Physics	62
3.6	Packing/Hold Stage	63
3.7	Cooling	64
3.8	Plastification and Melt Temperature Control	68
3.9	Ejection	68
3.10	Development and Distribution of Melt Pressures	69
3.11	Development and Distribution of Forces on the Molding Machine	70
3.12	Relationship of Actual Injection Parameters to Injection Molding Analysis	71
4	Part Design Guidelines for Injection Molded Plastic Parts	73
4.1	Designing the Primary Wall	74
4.1.1	Maintain a Constant Wall Thickness	74
4.1.2	Minimize Wall Thickness	75
4.1.3	Shape of the Wall	76
4.1.4	Surface Finish	77
4.1.5	Ribs, Gussets, and Bosses	77
4.1.6	Corners, Fillets, and Radii	82
4.1.7	Taper and Draft Angles	83
4.1.8	Undercuts and Holes	83
4.1.9	Cores	87
4.1.10	Avoid Picture Frame Features	88
4.1.11	Integral Hinges	89
4.2	Sample Part Design	90
5	Mold Design	94
5.1	Mold Assembly	94
5.2	Mold Classification Based on the Melt Delivery (Runner) Design	96
5.2.1	Cold Runner Molds	97
5.2.2	Hot Runner Molds	100
5.3	Runner Design	115
5.3.1	Cold Runner Design	117
5.3.2	Runner Balancing in Geometrically Balanced Runners (Cold and Hot Runners)	118

5.4	Gate Design	128
5.4.1	Gate Types	128
5.4.2	Positioning Gates	136
5.5	Structural Design of a Mold for Long Life and Rigidity	138
5.5.1	Mold Material Selection	138
5.5.2	Fatigue	139
5.5.3	Deflection of Side Walls	140
5.5.4	Core Deflection	140
5.5.5	Deflection of Support Plates	141
5.6	Mold Cooling	143
5.6.1	Practical Considerations	144
5.6.2	Thermal Expansion	146
5.6.3	Parallel vs. Series Cooling Line Networks	146
5.6.4	Baffles and Bubblers	149
5.7	Mold Ejection Systems	150
5.7.1	Basic Ejection Problems	150
5.7.2	Means of Ejection	153
5.7.3	Ejection Considerations	155
5.7.4	Ejection Design	157
5.8	Vent Design	162
	References	164
6	Mold Filling and Its Effect on the Product and Material	165
6.1	Plastic Flow	165
6.1.1	Melt Flow in the Part-Forming Mold Cavity	165
6.1.2	Pressure Development During Molding	166
6.1.3	Thermal Insulation Provided by the Frozen Layer	171
6.1.4	Effects of Mold Filling Rate and Mold Filling Pressure	171
6.2	Post-Filling or Packing Phase	173
6.2.1	Thermal Shrinkage as Plastic Cools	173
6.2.2	Compensation Flow to Offset Thermal Shrinkage	174
6.2.3	Consequences of Low Flow Rate During the Compensation Phase	175
6.2.4	Pressure Distribution During the Compensation Phase	175
6.2.5	Gate Freeze-Off	176
6.3	Cooling After Gate Freeze-Off	177
6.4	Flow Effects on Shrinkage	178
6.4.1	Shear-Induced Orientation	178
6.4.2	Transient Flow-Induced Orientation	179
6.4.3	Extensional Flow-Induced Orientation	181
6.4.4	Shrinkage of Fiber-Reinforced Materials	182
6.4.5	Shrinkage of Particulate-Filled Materials	184
6.5	Warpage and Residual Stresses	184
6.5.1	Effect of Shrinkage on Warpage and Residual Stresses	184
6.5.2	Cooling Effects on Shrinkage and Warpage	187
6.5.3	Residual Stress	187
6.5.4	Annealing a Molded Part	188
6.6	Processing Effects on Part Quality	188

6.6.1	Mechanical Properties	188
6.6.2	Weld Lines	192
6.7	Defects Introduced by the Process and Mold Design	194
6.7.1	Sinks and Voids	194
6.7.2	Jetting	195
6.7.3	“Flow” Marks	196
6.7.4	Air Traps	196
6.7.5	Burning	197
	References	197
7	Design and Process Strategies	198
7.1	Maintain Uniform Wall Thicknesses in a Part.	198
7.2	Use Common Design Guidelines for Injection Molded Plastic Parts with Caution.	201
7.3	Establish a Simple Strategic Flow Pattern Within a Cavity.	202
7.4	Balance Filling Throughout a Mold.	206
7.4.1	Gating Position(s) Within a Cavity	206
7.4.2	Multicavity Molds	210
7.5	Provide for Uniform Temperatures (Mold and Melt).	212
7.6	Eliminate, Strategically Place, or Condition Welds.	213
7.7	Avoiding Flow Hesitation.	214
7.8	Managing Frictional Heating of the Melt	215
7.9	Minimize Runner Volume in Cold Runners.	215
7.10	Avoid Excessive Shear Rates.	216
7.11	Avoid Excessive, and Provide for Uniform, Shear Stresses.	217
	References	218
8	Prototyping.	219
8.1	When to Prototype	219
8.2	Prototyping Methods.	220
8.2.1	Computer-Aided Design and Engineering	221
8.2.2	Machining from Rod or Bar Stock	222
8.2.3	Sterolithography.	223
8.2.4	Casting from Liquid Resins	224
8.2.5	Thermoforming	224
8.2.6	Injection Molding.	225
9	Introduction to Computer-Aided Engineering	228
9.1	Overview of CAE Technologies and Their Application	228
9.1.1	Background.	228
9.2	Pitfalls in Successful Application of Molding Simulation	230
9.3	Solution Techniques and Assumptions Effecting Accuracy	231
9.3.1	Common Simplifications and Related Errors.	234
9.3.2	Iterative Solution Techniques	238
9.4	2-D Analysis	241
9.4.1	Feasibility Studies (Strip Files).	241
9.4.2	Runner Analysis.	243

9.5	Mid-Plane 2½D Shell Analysis	245
9.6	Dual Domain™ Modeling and Analysis	247
9.7	Pitfalls from Modeling	247
9.8	Pitfalls from Material Data.	250
9.9	Pitfalls from Process Relationships	253
9.10	Non-Technical Aspects	255
9.10.1	Who Should Perform Analysis?.	255
9.10.2	Company Environment and Politics	256
9.10.3	Training	256
9.10.4	Program Execution	256
9.10.5	Interpretation of Results.	257
9.10.6	Communication	257
10	The Process of Performing CAE Analysis	259
10.1	An Overview of the Need for Injection Molding Analysis.	259
10.1.1	Stage 1: Product Development and the Product Designer.	259
10.1.2	Stage 2: Mold Design	262
10.1.3	Stage 3: Processor	262
10.2	An Outline of Procedures for Performing Injection Molding Simulation	265
10.3	Use Experimental Design with CAE to Optimize the Design and Process.	274
11	Characterization of Thermoplastic Materials for CAE	276
11.1	Characterization of Properties for Simulation	276
11.2	Sensitivity Study	276
11.2.1	Process Conditions	279
11.2.2	Simulation Results	280
11.2.3	Interpretation	281
11.2.4	Summary.	284
11.3	Laboratory vs. Production	285
11.4	Rheological Testing to Determine Melt Viscosity.	285
11.4.1	ASTM D 3835, Rheological Properties of Thermoplastics with a Capillary Rheometer	286
11.5	Thermal Characterization.	287
11.5.1	Thermal Conductivity	287
11.5.2	Specific Heat	287
11.5.3	Density and PVT Relationships.	288
11.5.4	Transition Temperature	290
11.6	Structural Properties	291
11.7	Mechanical Properties	291
12	Geometry Modeling for Injection Molding Analysis	293
12.1	Two-Dimensional Analysis.	294
12.2	Finite Element Shell Models (2½ Dimensional)	297
12.2.1	Guidelines for Mesh Density	297
12.2.2	Considerations of Model Detail.	302
12.2.3	Mesh Density for Filling and Packing Analysis	303

12.2.4	Mesh Needs for Cooling Analysis	303
12.2.5	Shrinkage and Warpage Analysis	303
12.3	Three-Dimensional Models Converted to $2\frac{1}{2}$ Dimensional Models for Shell Analysis	304
12.4	Three-Dimensional Analysis	304
13	Filling and Packing Analysis	306
13.1	Theory and Assumptions	306
13.1.1	Fluid Dynamics and Laminar Flow	306
13.1.2	Fountain Flow	306
13.1.3	Symmetry About the Midplane Is Assumed for Preliminary Flow Approximations	307
13.1.4	Temperature Gradient Between Mold Wall and Center	308
13.1.5	Specific Volume ($v \sim 1/p$), as a Function of Temperature and Pressure	309
13.1.6	Specific Heat (C_p) as a Function of Temperature	310
13.1.7	Thermal Conductivity (k) as a Function of Transformation	311
13.1.8	Transition and No-Flow Temperatures	312
13.1.9	The Melt Viscosity of a Specific Plastic Compound Is a Function of Temperature, Pressure, and Shear Rate.	312
13.2	Multilaminate Solution	313
13.3	Process Optimization	314
13.3.1	What Should Be Optimized?	314
13.3.2	Relationships to Part Quality	318
	Reference	324
14	Mold Cooling Analysis; CAE and the Boundary Element Method	325
14.1	Uniform Cooling and Its Effect on Warpage	326
14.2	Cooling Processing Optimization	327
14.3	Modeling Issues	332
15	Shrinkage and Warpage Analysis	335
15.1	Causes of Warpage	335
15.1.1	Differential Shrinkage Through the Part Thickness	336
15.1.2	Differential Area Shrinkage; Two-Dimensional Shrinkage	338
15.1.3	Differential Shrinkage Produced by Orientation Effects	339
15.2	Warpage Stability and Prediction	339
15.2.1	Small Deflection Analysis	340
15.2.2	Buckling Analysis	341
15.2.3	Large Deflection Analysis	341
15.3	Warpage Diagnosis	342
15.3.1	Diagnosis of Differential Shrinkage Through the Part Thickness	343
15.3.2	Diagnosis of Differential Area Shrinkage	344
15.3.3	Diagnosis of Orientation-Induced Differential Shrinkage	348
15.4	Residual Stress	348
15.4.1	Residual Stress Development	348

15.4.2	Short and Long Term Effects	349
15.4.3	Stress Relaxation	349
15.5	Shrinkage Prediction for Tight Tolerance Products	349
15.5.1	Isotropic Shrinkage versus Anisotropic Shrinkage	349
15.5.2	Volumetric versus Linear Shrinkage	350
15.6	Interpretation and Application.	350
15.6.1	Warpage Results Interpretation	351
15.6.2	Warpage Diagnosis—Determining the Causes	354
15.6.3	Minimizing Warpage—One Approach	354
Index.	357