

CONTENTS

		Page
Chapter I		
Atomic Arrangements in Metals		
1.	The Atom	1
2.	The Interaction Between X Rays and Atoms	4
3.	The Observed Crystal Structures	13
4.	Crystalline Textures	17
5.	Crystallographic Notation	20
Chapter II		
The Periodic Chart		
6.	The Valence Electrons in Atoms	23
7.	The Electromotive Series	28
Chapter III		
Substitutional and Interstitial Alloys		
8.	The Phase Diagram	30
9.	Substitutional Alloys	33
10.	Interstitial Alloys	37
Chapter IV		
The Physical Form of Alloys		
11.	The Thermodynamical Principles Governing Equilibrium	42
12.	Transition From one Stable Phase to Another	48
13.	The External Form of Crystalline materials	53
14.	Recrystallization After Plastic Deformation	56
15.	The Specific Heats of Solids	57
Chapter V		
The Elastic Properties of Crystals		
16.	Stress and Strain	63
Chapter VI		
The Plastic Properties of Single Crystals		
17.	The Stress-Strain Curve	70
18.	The Slip Process	73
19.	The Change in Energy and The Distortion Accompanying cold-work	78
20.	Recrystallization and Resoftening	81
21.	The Influence of Temperature on the critical Shearing Stress	83
22.	Hypothetical Mechanism of the Slip Process	85
23.	Twinning	101
Chapter VII		
The Plastic Properties of Polycrystalline Media		
24.	Introduction	106
25.	Grain-Boundary Influence	107
26.	Slip in Polycrystals	113
27.	Technical Hardness	119
28.	The Behavior of Metals at High Pressures	120
Chapter VIII		
The Plastic Properties of Alloys		
29.	Introduction	123

30.	Homogeneous Solid Solutions	123
31.	Heterogeneous Alloys	128
Chapter IX		
Creep and Secondary Plastic Effects		
32.	Creep in Single Crystals	133
33.	Creep in Polycrystals	141
34.	Creep Recovery	144
35.	The Bauschinger Effect	146
36.	The Elastic Aftereffect	149
37.	The Dependence of the Stress-Strain Curve on the Rate of Flow	149
Chapter X		
Internal Friction		
38.	Introduction	152
39.	Internal Friction in Single Crystals	153
40.	The Internal Friction of Polycrystals	158
Chapter XI		
Rupture and Fatigue		
41.	Rupture in Single Crystals	164
42.	Rupture in Polycrystals	169
43.	Fatigue	172
Chapter XII		
Diffusion in Metals		
44.	Introduction	174
45.	Principal Faces Concerning Diffusion	177
46.	The Mechanism of Diffusion in Metals	183
47.	Diffusion in Nonmetals	185
48.	The Mechanism of Diffusion in Salts	191
Chapter XIII		
The Solubility of Gases in Metals		
49.	Introduction	192
50.	The Mechanism of Diffusion of Gases in Metals	200
Chapter XIV		
The Properties of Iron-Carbon Alloys		
51.	Introduction	201
52.	Pure Iron	201
53.	The Influence of Carbon on the Equilibrium Properties of Iron	202
54.	The Transformation of Austenite in Plain Carbon Steel	204
55.	The Properties of the Products of Transformation of Austenite	209
56.	The Influence of Alloying Elements	218
Chapter XV		
Introduction to the Concepts of Modern Physics		
57.	Introduction	230
58.	The Electron	231
59.	Other Types of Charged Radiation	234
60.	Composition of the Atoms	234
61.	The Theory of Light	235
62.	Influence of the Quantum theory of Light on Atomic Ideas	237
63.	Bohr's Theory of the Hydrogen Atom	239
64.	Electron Spin	240
65.	The Pauli Principle	241
66.	Summary	241
67.	The Wave Theory of Matter	242

Chapter XVI		
The Development of the Electron Theory of Metals		
68.	The Solid Types	246
69.	The Drude-Lorentz Theory of metals	247
70.	Early Theories of the Other Types of Solids	250
71.	Sommerfeld Theory of Metals	251
Chapter XVII		
The Band Theory of Solids		
72.	Introduction	257
73.	The Forbidden Regions of Energy	259
74.	The Monatomic Solids	265
75.	Ionic Solids	276
76.	Semi-conductors	277
Chapter XVIII		
The Cohesion of Solids		
77.	Survey	281
Chapter XIX		
Alloys		
78.	Introduction	284
79.	Substitutional Alloys	284
80.	Interstitial Alloys	291
Chapter XX		
The Magnetic Properties of Metals		
81.	Introduction	292
82.	Paramagnetism and Diamagnetism in Metals	294
83.	Ferromagnetism in Pure Metals	296
84.	Ferromagnetism of Alloys	307
85.	Influence of Magnetization on the Expansion Coefficient	310
Chapter XXI		
The Electrical Conductivity of Metals		
86.	Introduction	312
87.	The Thermal Dependence of Resistance	313
88.	The Influence of Impurities and Alloying Agents on the Resistance	315
89.	The Resistance of the Transition Metals	319
90.	The Influence of Cold-Work on Electrical Resistance	320
	Name Index	323
	Subject Index	327