

CONTENTS

	Page	
Chapter 1 The Atom		
1.1	General Structure of the Atom	1
1.2	Electrons	3
1.3	Motion of the Electron	5
1.4	The Exclusion Principle	5
1.5	Energy Levels Within the Atom	6
1.6	Energy-Level Diagrams	7
1.7	Degeneracy of Energy Levels	10
1.8	Shells of Electrons	11
1.9	Chemical Valence	12
1.10	The Periodic Table	15
1.11	Multiple Valences	24
1.12	Free Energy	25
1.13	Spontaneous Changes	26
1.14	Chemical Activity	28
1.15	Activity Series for the Nonmetals	30
Chapter 2 Crystallography		
2.1	Metal Crystals	32
2.2	Space lattices in General	33
2.3	The Fourteen Possible Space Lattices	34
2.4	The Possibility of Additional Space Lattices	37
2.5	Crystallographic Notation	38
2.6	Reference Axes	39
2.7	The Seven Crystal Systems	41
2.8	Intercepts	43
2.9	Miller Indices	43
2.10	Sets and Families of Planes	45
2.11	Indices of Direction	47
2.12	Miller-Bravais Indices	51
2.13	Hexagonal Indices of Direction	53
Chapter 3 Crystal Structures		
3.1	Solids, Liquids, and Gases	56
3.2	Crystalline vs. Amorphous Solids	58
3.3	Crystal Lattices	60
3.4	Important Planes and Directions	62
3.5	Bonding Forces in Crystals	64
3.6	Molecular Crystals	65
3.7	Ionic Crystals	67
3.8	Intermetallic Compounds of the Ionic Type	71
3.9	Valence Crystals	73
3.10	The 8 Minus N Rule	76
3.11	Valence-Molecular Crystals	77
3.12	Metallic Crystals	79
3.13	The Metallic Bond	80
3.14	Metallics vs. Ionic and Covalent Bonding	82
3.15	The Structures of Metallic Crystals	83
3.16	The Close-Packed Hexagonal (C.P. Hex.) Structure	84
3.17	Characteristics of the Close-Packed Hexagonal Structure	87
3.18	Examples of Close-packed hexagonal Crystals	89
3.19	The Face-Centered Cubic (F.C.C.) Structure	90

3.20	The body-Centered Cubic (B.C.C.) Structure	93
3.21	Other Crystal Structures	94
3.22	Rationalization of Observed Crystal Structures	96
3.23	Electron Concentration	98

Chapter 4 Polymorphism

4.1	Polymorphic Transformations	100
4.2	Examples of Polymorphism	101
4.3	The Theoretical Basis for Polymorphism	102
4.4	Bonding Forces and Polymorphism	105
4.5	Hysteresis and Activation Energies	107
4.6	Transition Structures	110
4.7	The Martensite Transformation	112

Chapter 5 Crystal Imperfections

5.1	Elastic Distortion	115
5.2	Free Metal Surfaces	116
5.3	Surface Energy	117
5.4	Freezing of a Pure Metal	119
5.5	Grain Boundaries	121
5.6	Residual Affinity; Heterogeneous Alloys	124
5.7	Grain Growth	125
5.8	Spheroidization	127
5.9	Amorphous Metal; the Beilby Layer	130
5.10	Vacant Lattice Points; Diffusion	134
5.11	Defect Lattices	137
5.12	Dislocations	138
5.13	Mosaic Structure	141
5.14	Lineage Structure	143
5.15	Alloy Types	144
5.16	Crystal Distortion by Foreign Atoms	147
5.17	Determination of Solubility Limits	149
5.18	Interstitial Solid Solutions	151
5.19	Interstitial Compounds	153
5.20	Substitutional Solid Solutions	154
5.21	Relative Valence Effect	155
5.22	Electron Concentration vs. Extent of Solubility	156
5.23	Ordered Substitutional Solid Solutions	158
5.24	The physical Basis of Ordering	159
5.25	Long-Range and Short-Range Order	161
5.26	Imperfectly Ordered Solid Solution	163
5.27	Ordered Solid Solutions vs. Compounds	164
5.28	Order in Interstitial Solid Solutions	165

Chapter 6 Electrical and Magnetic Properties of Metals

6.1	Electrical Conduction	167
6.2	The Electron Cloud in Conductors	167
6.3	The necessity for Excitation	168
6.4	Electrical Conductors	169
6.5	Electrical Insulators	171
6.6	Semi-conductors	172
6.7	Photoconductors	172
6.8	The Band Theory in General	172
6.9	Electrical Resistance	173
6.10	Magnetism	176
6.11	Diamagnetism	176
6.12	Paramagnetism	177
6.13	Ferromagnetism	179
6.14	Magnetic Applications	181
6.15	Magnetic Materials	182

Chapter 7 Deformation of Metals

7.1	Toughness	184
7.2	Elastic vs. Plastic Deformation	186
7.3	Elastic Deformation	187
7.4	Importance of the Elastic Modulus	188
7.5	The Stress-Strain Curve	191
7.6	Instantaneous Stress vs. Strain	193
7.7	Simultaneous Elastic and Permanent Deformation	196
7.8	Springback	198
7.9	Type of Loading for Permanent Deformation	198
7.10	Resolution of Forces	201
7.11	Effect of Type of Bond on the Possibility of Slip	202
7.12	Slip Planes and Slip Directions	204
7.13	Slip in Close-packed Hexagonal Crystals	205
7.14	Behavior of a Zinc single Crystal in Tension	207
7.15	Slip in Face-Centered cubic Crystals	209
7.16	Slip in Body-Centered Cubic Crystals	210
7.17	Slip in Other Crystal Structures	211
7.18	Progress of Slip in a single Crystal	211
7.19	Force Required to Produce Slip	215
7.20	Slip by Movement of a Dislocation	217
7.21	Shearing Force to Move a Dislocation	219
7.22	Origin of Initial Slip	221
7.23	Cessation of Slip on an Active Slip Plane	223
7.24	Slip-Interference Theories of Strain Hardening	224
7.25	Dislocation Theory of Strain Hardening	226
7.26	Stress Field of a Dislocation	227
7.27	Interactions Among Dislocations	228
7.28	Development of a Dislocation lattice	229
7.29	incidental Effects of the Dislocation Lattice	230
7.30	Mechanical Twinning	232
7.31	The Mechanism of Twinning	234
7.32	The Importance of Twinning	236
7.33	Microscopic Appearance of Twins	237
7.34	Distinction Between Twin Bands and Slip Bands	240
7.35	Deformation of Polycrystalline Aggregates	242
7.36	The influence of Grain Boundaries	243
7.37	Effect of Alloying on Permanent Deformation	246

Chapter 8 The Effects of Permanent Deformation

8.1	Strain Hardening (Work Hardening)	249
8.2	Industrial Importance of Strain Hardening	255
8.3	Change in Shape of Individual Crystals	258
8.4	Banding and Flow Lines (Mechanical Fiberling)	260
8.5	Mechanical Effects of Banding	263
8.6	Orange-Peel Structure	265
8.7	Deformation Bands (Strain Markings)	266
8.8	Homogeneous Crystal Rotation	269
8.9	Preferred Orientation (Crystallographic Fiberling)	273
8.10	Industrial Importance of Preferred Orientation	275
8.11	Strain Hardening from Preferred Orientation	280
8.12	Energy Changes from Mechanical Deformation	281
8.13	Macrostressses (Heyn Stressses)	282
8.14	Microstressses	283
8.15	Bauschinger Effect	284
8.16	Elastic Aftereffect (Elastic Hysteresis)	286
8.17	Damping	287
8.18	Other Structure-Sensitive Properties	289
8.19	Structure-Insensitive Properties	291

Chapter 9 The Effects of Elevated Temperature

9.1	Diffusion	293
9.2	Grain Growth	295
9.3	Factors Favoring Grain Growth	296
9.4	Temperature, Time and Grain Size	299
9.5	Effect of Intergranular Films on Grain Growth	301
9.6	Recovery (Resoftening)	303
9.7	Low-Temperature Stress Relief; the Light Anneal	304
9.8	Recrystallization	305
9.9	Nucleation	306
9.10	Crystal Growth	310
9.11	The Full Anneal ; Recrystallized Grain Size	311
9.12	Development of Coarse Recrystallized Grain Size	312
9.13	Microstructure After Recrystallization	317
9.14	Annealing Textures	318
9.15	Annealing Twins	321
9.16	Hot vs. Cold Mechanical Working	321
9.17	Advantages of Hot Working	323
9.18	Disadvantages of hot Working	327
9.19	Force Required to Produce Permanent Deformation	331
9.20	Effect of Duration or Rate of Loading	333
9.21	Hot pressing	337
9.22	Creep	338
9.23	The Creep Curve	339
9.24	Effect of Magnitude of Load Upon the Creep Curve	340
9.25	Creep Strength, Creep Life, and Creep Limit	341
9.26	Effect of Temperature upon the creep Curve	342
9.27	Mechanism of Permanent Deformation During Creep	344
9.28	Selection of Metals for Creep Service	248

Chapter 10 Fracture

10.1	Type of Force Required to Produce Cracking	353
10.2	Shear Fractures	355
10.3	Energy Relations in Cracking; Inherent Strength of Crystals	358
10.4	Fracture Strengths of Polycrystalline metals	359
10.5	Location of Cracks	368
10.6	Appearance of Fracture Surfaces	369
10.7	Permanent Deformation During Fracture	370
10.8	Polyaxial Stresses	372
10.9	Notch Sensitivity	377
10.10	Conclusions Concerning Fractures	379
10.11	Fatigue Failure (Detail Fracture)	381
10.12	Formation and Extension of Fatigue Cracks	382
10.13	Appearance of Fatigue-Fracture Surfaces	384
10.14	Type of Loading to produce Fatigue Cracking	385
10.15	Prevention of Fatigue Failures	387
10.16	Fatigue Testing	398
10.17	Fatigue Testing Machines	400
10.18	Surface Finish	403
10.19	Size Effect	403
10.20	Corrosion-Fatigue Testing	405
10.21	Usefulness of Fatigue Testing	406
	Index	407