

CONTENTS

	Page
Introduction	1
CHAPTER 1	
A – Introductory Chemistry and Physics	3
B – Internal Structure of the Atom	14
CHAPTER 2	
A – Production of Metals	28
B – Nonferrous Metals	43
CHAPTER 3	
A – Iron and its Reduction from Ore in the blast Furnace	59
B – Blast Furnace Technology	76
CHAPTER 4	
A – Steel Production	91
B – Steel Production	114
CHAPTER 5	
A – The Ingot	128
B – Solidification of Ingots	137
CHAPTER 6	
A – Mechanical Properties of Metals	144
B – Mechanical Properties of Metals	159
CHAPTER 7	
A – Mechanical Shaping of Metals	174
B – Mechanical Shaping of Metals	196
CHAPTER 8	
A – Solidification of Alloys	216
B – Advanced Studies of Solidification of Metals	230
CHAPTER 9	
A – Equilibrium Phase Diagrams	243
B – Equilibrium Phase Diagrams	259
CHAPTER 10	
A – Slip Interference	266
B – Strength of Metals	281
CHAPTER 11	
A – The Iron-Carbon Diagram	291
B – The Iron-Carbon Diagram	299
CHAPTER 12	
A – Iron-Carbon Diagram Continued : Solid to Solid Transformations	302
B – Iron-Carbon Diagram Continued : Solid to Solid Transformations	316
CHAPTER 13	

CHAPTER 14	
A – TTT-Curves	324
B – TTT-Curves	333
CHAPTER 15	
A – Hardenability of Steels	341
B – Hardenability of Steels	347
CHAPTER 16	
A – Low Alloy Steel	353
B – Low Alloy Steel	362
CHAPTER 17	
A – Case hardening	372
B – Case Hardening	384
CHAPTER 18	
A – Heat Treatments	400
B – Heat Treatments	409
CHAPTER 19	
A – Stainless Steels	413
B – Stainless Steels	431
CHAPTER 20	
A – Tool Steels	442
B – Tool Steels	457
CHAPTER 21	
Cast Iron	470
CHAPTER 22	
A – Precipitation Hardening	496
B – Precipitation Phenomena	507
CHAPTER 23	
A – The Light Metals	518
B – The Light Metals	530
CHAPTER 24	
A – Copper and Copper Alloys	538
B – Mechanical Working, Heat Treatment and Corrosion resistance of Copper Alloys	556
CHAPTER 25	
A – Nickel and Nickel Alloys, Lead and Tin, Noble Metals	569
B – The Noble Metals	596
CHAPTER 26	
A – Metal Coatings	605
B – Powder Metallurgy	617
CHAPTER 27	
A – Casting	631
B – Welding, Brazing and Soldering	644
CHAPTER 28	
A – The Effect of High and Low Temperatures on Metals	658
B – The Effect of High and Low Temperatures on Metals	666
Appendix	673