

## **CONTENTS**

CHAPTER 1. ACCURACY—INTERCHANGEABILITY—GAUGING	PAGE
Conditions and Synthesis of Accuracy—Interchangeability and Limit Systems—Newall and B.S. Systems—Selective Assembly Gauging—Limit Gauges—Indicating Gauges—Special and First Operation Gauges  1	
CHAPTER 2. MEASUREMENT AND PRECISION WORK	
Slip Gauges—Comparator—Vernier Height Gauge—Marking Out— Vernier Micrometer—Examples of Measurement—Sine Bar— Angular Testing—Use of Rollers—Tapers—Projection	25
Chapter 3. Machine Tools	
Standard and Special Purpose Machines—Elements of Construction— Bed—Spindle—Speeds—Work Holding—Tool Attachment— Feeding—Tool Lubrication—Rigidity—Surface Machine-Tool Accuracy—Alignments—Testing  Formation— .	56
CHAPTER 4. FURTHER WORK ON THE LATHE	
Promotion of Accuracy—Examples—Taper Turning Attachment— Effect of Tool Height—Eccentric Turning—Form Turning—Collet Chuck—Multi-Start Screws—Leadscrew Accuracy—Quantity Production Methods—Square Tool Box—Leaving for Grinding— Boring on Saddle—Button Boring—Slotting .	95
Chapter 5. Milling	
Horizontal Machine—Cutter Support—Types of Cutters—Teeth—Helical—Relieved—End and Face Mills—Rotation—Feed—Choice of Cutter and Set-up—Care of Machine—Examples of Plain Milling—Fixtures—Slotting Attachment	123
Chapter 6. Milling (continued)	
Dividing Head—Simple and Angular Indexing—Work Holding—Alignment—Examples of Work—Settings for Cutting Side, Taper and Clutch Teeth—Gear Cutting—Rack Cutting Attachment—Vertical Milling—Machine—Vertical Head—Equipment for Vertical Work—Examples—Jig Boring on Vertical Machine	155
CHAPTER 7. SHAPING, PLANING AND SLOTTING	
Hydraulic Shaper—Drive—Circuit Diagrams—Examples of Work— Use of Dividing Head—Planer—Table Drive—Electric Control— Tools and Support—Work Setting—Examples—SlottingMachine Whitworth Motion—Slotter Tools—Examples of Work	

INDEX .

CHAPTER 8. DRILLING AND BORING	
Standard and Special Drills—Chucks—Quick Change Holders— Machines—Vertical—Radial—Sensitive—General Purpose Drill- ing—Examples—Drill Jigs—Design—Pacing—Counterboring— Deep Drilling—Horizontal Boring—Tools, Cutters and Bars— Facing—Setting up—Examples—Boring Fixtures—Vertical Boring Mill	217
Chapter 9. Grinding	
Scope of Process—Wheel—Abrasive, Artificial and Natural—Manufacture—Bond—Types of Bond—Grit and Grade—Wheel Manufacture — Structure — Shape — Classification — Selection — Wheel Mounting—Truing and Dressing—Speeds—Faults—Hand Grinding—Tools—Lathe Grinding Attachments—Cylindrical Grinding—Speed and Peed—Machine and its Construction—Steadies—Vibration—Operation of Machine—Taper Grinding .	251
Chapter 10. Grinding (continued)	
Internal Grinding — Machine — Internal Spindles — Wheels — Examples of Work — Surface Grinding — Methods — Disc and Ring Wheels — Magnetic Chuck — Types of Surface Machines — Hydraulic Driving — Examples of Surface Grinding — Tool and Cutter Grinder — Setting and Sharpening Various Cutters — Cutting off by Abrasive Wheel — Oilstones — Grinding Wheel Recommendations	286
APPENDIX 1.—NEWALSYSTEM OF LIMITS	321
APPENDIX 2.—BROWIND SHARPE TAPERS	322
APPENDIX 3.—B.S. LIMIT SYSTEM. DETAILS OF SHAFTS	324
APPENDIX 4.—B.S. LIMIT SYSTEM. SELECTED HOLE AND SHAFT RELATIONSHIPS	325
APPENDIX 5.—BRITISH TANDARD SPECIFICATIONS OF INTEREST TO THE WORKSHOP ENGINEER	326