

# Contents

<b>1</b>	<b>Fundamental metallographic concepts</b>	<b>1</b>
1.1	The transformation and crystal structures of iron	1
1.2	The iron–carbon equilibrium diagram	4
1.2.1	Heating	5
1.2.2	Cooling	6
1.3	Time–temperature–transformation	6
1.3.1	Heating	7
1.3.2	Cooling	13
1.3.3	Formation of pearlite	13
1.3.4	Formation of bainite	14
1.3.5	Formation of martensite	15
1.3.6	Retained austenite	18
1.3.7	TTT diagrams	20
1.4	Decomposition of martensite and retained austenite on tempering	20
1.5	Diffusion	23
1.5.1	The nature of diffusion	23
1.5.2	Factors that influence the rate of diffusion	24
1.5.3	Calculation of diffusion distance	25
1.6	Dislocations	29
1.7	Grain size	32
1.7.1	Grain boundaries	32
1.7.2	Methods of determining grain size	34
1.7.3	Examples of grain size determinations	38
<b>2</b>	<b>Materials testing</b>	<b>42</b>
2.1	The hardness test	42
2.1.1	The Brinell test	42

## CONTENTS

2.1.2	The Vickers test	43
2.1.3	The Knoop test	44
2.1.4	The Rockwell test	44
2.1.5	The Scleroscope test	47
2.1.6	Conversion tables for various scales of hardness	49
2.2	The tensile test	51
2.2.1	Comparison between mechanical properties obtained according to different specifications	53
2.3	The impact test	53
2.4	The torsion impact test	57
2.5	The fatigue test	58
2.5.1	Fatigue in general	58
2.5.2	Test procedure	60
2.5.3	Different types of fatigue fractures	62
2.5.4	Goodman diagram	64
2.5.5	Endurance limit—ultimate tensile strength	65
2.5.6	Surface finish	66
2.5.7	Influence of change of section	69
2.5.8	Ways of increasing the endurance limit	69
2.6	The creep test	69
2.7	Brittle and ductile fractures	72
2.8	Fracture toughness	76
2.8.1	The implication of fracture toughness	80

## 3 Alloying elements in steel 82

3.1	Solids	82
3.1.1	Austenite-forming elements	82
3.1.2	Ferrite-forming elements	83
3.1.3	Multi-alloyed steels	84
3.1.4	Carbide-forming elements	85
3.1.5	Carbide stabilizers	85
3.1.6	Nitride-forming elements	86
3.1.7	Effect on ferrite hardness	87
3.1.8	Effect on grain growth	88
3.1.9	Effect on the eutectoid point	89
3.1.10	Effect on the temperature of martensite formation	90
3.1.11	Effect on the formation of pearlite and bainite during the isothermal transformation	93
3.1.12	Effect on resistance to tempering	102
3.2	Gases	106
3.2.1	Hydrogen	106
3.2.2	Nitrogen	110
3.2.3	Oxygen	113
3.3	New steelmaking processes	116
3.3.1	Vacuum remelting	116
3.3.2	Electroslag refining	117

3.3.3	Vacuum degassing	120
3.3.4	The Bofors method of sulphur removal	121
3.3.5	Effect of sulphur on the properties of steel	121

## 4 Hardenability 127

4.1	General remarks	127
4.2	The Grossmann hardenability test	130
4.2.1	Calculation of $D_i$ -values from chemical composition	132
4.3	The Jominy end-quench hardenability test	137
4.3.1	Calculation of Jominy curves from the chemical composition	140
4.3.2	Practical applications of Jominy curves	141
4.4	Practical application of the TTT and the CCT diagrams	151
4.5	Practical application of hardenability	161
4.5.1	High hardenability	161
4.5.2	Low hardenability	163
4.6	The influence of the depth of hardening on the stress pattern	169

## 5 Heat treatment—general 177

5.1	Annealing	177
5.1.1	Annealing for maximum softness or spheroidizing anneal	177
5.1.2	Recrystallization annealing	184
5.1.3	Stress-relief annealing	184
5.1.4	Isothermal annealing	188
5.1.5	Quench annealing	188
5.1.6	Homogenizing annealing	191
5.1.7	Hydrogen annealing	191
5.1.8	Hydrogen expulsion	191
5.2	Normalizing	191
5.3	Hardening	194
5.3.1	Heating media	194
5.3.2	Rate of heating	202
5.3.3	Hardening temperature	206
5.3.4	Holding time at temperature	209
5.3.5	Methods of cooling	212
5.3.6	Quenching media	219
5.3.7	Quenching equipment	230
5.4	Tempering	233
5.4.1	Heating to temperature	234
5.4.2	Rate of heating	234
5.4.3	Holding time	240
5.4.4	Double tempering	244
5.4.5	Temper brittleness	246

## CONTENTS

5.5	Transformation of retained austenite	249
5.6	Precipitation hardening	253
5.7	Straightening	257
5.8	Machining allowances	258

## 6 Heat treatment—special

261

6.1	Hardening and tempering of tool steels	261
6.1.1	Carbon steels and vanadium-alloyed steels	261
6.1.2	Low-alloy cold-work steels	266
6.1.3	Low-alloy cold-work and hot-work steels	273
6.1.4	High-alloy cold-work steels	276
6.1.5	Hot-work steels	290
6.1.6	High-speed steels	313
6.2	Quenching and tempering of constructional steels	319
6.2.1	Definitions	319
6.2.2	Plain carbon steels	320
6.2.3	Alloy steels	324
6.2.4	Stainless steels	330
6.2.5	Spring steels	333
6.2.6	High-strength steels	335
6.2.7	Hadfield steel	339
6.3	Case hardening	339
6.3.1	Definitions	339
6.3.2	Grades of steel	342
6.3.3	Methods of carburizing	345
6.3.4	Influence of heat treatment and steel composition on case depth, surface hardness and core hardness	359
6.3.5	Recommendations for case hardening	370
6.3.6	Case hardening of tool steels	371
6.3.7	Protecting against carburization (selective carburizing)	372
6.3.8	Choice of case-hardening depth	374
6.4	Nitriding	377
6.4.1	Methods of nitriding	379
6.4.2	Comparison between gas and salt-bath nitriding	387
6.4.3	Nitridability	395
6.4.4	Determination of depth of nitriding	406
6.4.5	Nitriding different types of steel	407
6.4.6	Properties of nitrided steels	418
6.5	Carbonitriding	427
6.5.1	Definition	427
6.5.2	Theoretical background	427
6.5.3	Conclusions	432
6.6	Induction hardening	432
6.6.1	Fundamental principles	432
6.6.2	Steel grades for induction hardening	435
6.6.3	Equipment for induction hardening	435

6.6.4	Working coils and fixtures	436
6.6.5	Procedure during induction hardening	437
6.6.6	The influence of various factors on hardness and depth of hardening	440
6.6.7	Examples of induction-hardened machine components	447
6.6.8	Advantages and disadvantages of induction hardening	450
6.7	Flame hardening	451
6.7.1	Methods of hardening	451
6.7.2	Hardness and depth of hardening	454
6.7.3	Examples of flame-hardened machine components and tools	458
<b>7</b>	<b>Dimensional changes during hardening and tempering</b>	<b>466</b>
7.1	Dimensional changes during hardening	466
7.1.1	Thermal stresses	466
7.1.2	Transformation stresses	467
7.2	Dimensional changes during tempering	472
7.2.1	Changes in volume	472
7.2.2	Changes in stress conditions	473
7.3	Examples of dimensional changes during the hardening and tempering of tool steels	474
7.3.1	Plain carbon steels	475
7.3.2	Low-alloy steels	476
7.3.3	High-alloy cold-work steels	490
7.3.4	Hot-work steels	496
7.3.5	High-speed steels	502
7.4	Dimensional changes during case hardening	506
7.5	Dimensional changes during nitriding	514
7.6	Ageing	520
7.7	Designing for heat treatment	523
<b>8</b>	<b>Tables</b>	<b>528</b>
8.1	Some steel standard specifications and comparable Bofors and Uddeholm (UHB) steels	528
Table 8.1	American Steel Standard Specifications	529
Table 8.2	British Steel Standard Specifications	529
Table 8.3	German Steel Standard Specifications	530
Table 8.4	Swedish Steel Standard Specifications	531
Table 8.5	Afnor Designations (French)	532
Table 8.6	ASSAB Designations (Associated Swedish Steels AB)	533
8.2	Weight tables for steel bars	534
Table 8.7	Round and Square Bars. Metric Units	534
Table 8.8	Hexagonal and Octagonal Bars. Metric Units	535
Table 8.9	Flat Bars, 10 to 40 mm. Metric Units	535

## CONTENTS

	Table 8.10	Flat Bars, 45 to 130 mm. Metric Units	536
	Table 8.11	Flat Bars, 140 to 350 mm. Metric Units	537
	Table 8.12	Round and Square Bars. Inch Units	538
	Table 8.13	Hexagonal and Octagonal Bars. Inch Units	539
	Table 8.14	Flat Bars, Width $\frac{3}{8}$ to $\frac{1}{2}$ in. Inch Units	539
	Table 8.15	Flat Bars, Width $1\frac{1}{8}$ to 5 in. Inch Units	540
	Table 8.16	Flat Bars, Width $5\frac{1}{2}$ to 15 in. Inch Units	541
8.3	Conversion tables for temperature		542
	Table 8.17	Conversion Table for °Celsius (Centigrade) and °Fahrenheit	542
8.4	Conversion table for size		546
	Table 8.18	Inches to Millimetres	546
	Table 8.19	Decimals of Inches to Millimetres	548
8.5	Conversion tables for weight (mass)		549
	Table 8.20	Pounds to Kilogrammes	549
	Table 8.21	British Units to Kilogrammes	550
8.6	Conversion table for stress (pressure)		551
	Table 8.22	Tons per square inch to Kiloponds per square millimetre	551
	Table 8.23	Tons per square inch to Newtons per square millimetre	552
	Table 8.24	Kiloponds per square millimetre to Newtons per square millimetre	553
	Table 8.25	Pounds per square inch to Kiloponds per square millimetre	554
8.7	Conversion tables for energy		555
	Table 8.26	Kilopond metres to Footpounds	555
	Table 8.27	Footpounds to Kilopond metres	556
	Table 8.28	Kilopond metres to Joules	557
	Table 8.29	Footpounds to Joules	558
8.8	Conversion table for fracture toughness units		558
	Table 8.30	Fracture Toughness Units	558
8.9	Conversions for some common units		559
	Table 8.31	Common SI Units to British Units	559
	Table 8.32	Common Non-SI Units to British Units	560
	Table 8.33	Non-SI Metric Units to SI Units	561
8.10	Elements		562
	Table 8.34	Atomic Number and Atomic Weight	562