

Contents

	Page
Foreword -----	III
Preface -----	IV
Editor's note -----	V
Expression of Uncertainties	
Expression of the uncertainties of calibrations-----	3
A tabular guide to commonly used terms and expressions-----	3
Temperature Scales	
The thermodynamic temperature scale, its definition and realization-----	7
The International Practical Temperature Scale of 1948, text revision of 1960-----	17
The realization and use of the International Practical Temperature Scale of 1948-----	26
Establishment of a temperature scale for the calibration of thermometers between 14° and 83° K-----	33
National Bureau of Standards provisional scale of 1955. Corrections for use in low-temperature platinum resistance thermometry-----	56
Acoustical thermometer and the National Bureau of Standards pro- visional temperature scale 2–20 (1965)-----	57
The "1958 He ⁴ scale of temperatures"-----	70
The 1962 He ³ scale of temperatures-----	89
Cerous magnesium nitrate: A magnetic temperature scale 0.002–2 OK-----	99
Resistance Thermometry	
Precision resistance thermometry and fixed points-----	121
Notes to supplement resistance thermometer reports-----	149
Constants of the interpolation formula for platinum resistance thermom- eters-----	159
A study of stability of high temperature platinum resistance thermom- eters-----	163
Interpolation of platinum resistance thermometers, 10° to 273.15 °K-----	169
Calibration of germanium resistors at low temperatures (2–20° Kelvin)-----	178
Reproducibility of germanium resistance thermometers at 4.2 °K-----	188
Germanium resistance thermometry in the range 2.1° to 5.0 °K-----	198
Thermoelectric Thermometry	
Thermoelectric thermometry-----	213
Methods of testing thermocouples and thermocouple materials-----	233
Temperatures of thermocouple reference junctions in an ice bath-----	256
Stability of base-metal thermocouples in air from 800° to 2,200 °F-----	263
Reference tables for the Pt-30 percent Rh versus Pt-6 percent Rh thermo- couple-----	290
Reference tables for 40 percent iridium-60 percent rhodium versus irid- ium thermocouples-----	307
A furnace for thermocouple calibrations to 2,200 °C-----	313
Low temperature thermocouples—I. Gold-cobalt or constantan versus copper or 'normal' silver-----	319
Liquid-in-Glass Thermometry	
Calibration of liquid-in-glass thermometers-----	333

Optical Pyrometry

	Page
Theory and methods of optical pyrometry-----	361
The NBS photoelectric pyrometer and its use in realizing the International Practical Temperature Scale above 1063 °C-----	391
Radiance temperature at 6550 Å of the graphite arc-----	404

Spectroscopic Thermometry

Spectral absorption method for determining population "temperatures" in hot gases-----	407
Measurement of electron density and temperature in dense plasmas by application of line broadening theory-----	416
Arc source for high temperature gas studies-----	421
Arc measurement of some argon transition probabilities-----	424
The use of an analog computer in side-on arc spectroscopy-----	439

Selected Bibliography January 1953 to December 1965

Bibliography of temperature measurement January 1953 to June 1960-----	447
Bibliography of temperature measurement July 1960 to December 1965-----	462
Subject index-----	511
Author index-----	513
SI physical units (inside back cover)	