

GENERAL GUIDELINES ON SAMPLING**CAC/GL 50-2004****TABLE OF CONTENTS**

TABLE OF CONTENTS	1
PREAMBLE	3
SECTION I. PURPOSE OF CODEX GUIDELINES ON SAMPLING	5
1.1 PURPOSE	5
1.2 TARGET AUDIENCE OF THE GUIDELINES	5
1.3 USERS OF SAMPLING PLANS RECOMMENDED BY THE GUIDELINES	5
1.4 SCOPE OF THE GUIDELINES	6
1.5 RELATIONSHIP OF THE GUIDELINES WITH THE ISO GENERAL STANDARDS	8
SECTION 2. MAIN NOTIONS OF SAMPLING	8
2.1 INTRODUCTION	8
2.1.1 <i>Presentation of the section</i>	8
2.1.2 <i>General</i>	9
2.2 COMMONLY USED TERMS AND NOTIONS.....	10
2.2.1 <i>Lot</i>	10
2.2.2 <i>Consignment</i>	10
2.2.3 <i>Sample (representative sample)</i>	10
2.2.4 <i>Sampling</i>	11
2.2.5 <i>Total estimation error</i>	11
2.2.6 <i>Sampling error</i>	11
<i>Item or increment of individualisable goods</i>	11
2.2.8 <i>Sampling plan</i>	11
2.2.9 <i>The Characteristic</i>	12
2.2.10 <i>Homogeneity</i>	12
2.2.11 <i>Defects (Nonconformities) and Critical Nonconformities</i>	12
2.2.12 <i>Operating Characteristic Curve</i>	13
2.2.13 <i>Producers' risk and consumers' risk</i>	13
2.2.14 <i>The Acceptable Quality Level (AQL) and Limiting Quality (LQ) Level</i>	14
2.2.15 <i>Responsible Authority</i>	15
2.2.16 <i>Inspection Levels and Switching Rules</i>	15
2.2.17 <i>Acceptance Number</i>	15
<i>Lot Size and Sample Size</i>	15
2.3 SAMPLING PROCEDURES	16
2.3.2 <i>Employment of Sampling Officers</i>	16
2.3.3 <i>Material to be Sampled</i>	16
<i>Representative sampling</i>	16
2.3.5 <i>Preparation of samples</i>	17
<i>Packaging and Transmission of Laboratory Samples</i>	18
2.3.7 <i>Sampling reports</i>	18
2.4 ESTIMATION ERRORS.....	18
2.5 TYPES OF SINGLE SAMPLING PLANS.....	19
2.5.1 <i>Single sampling plans for inspections of percent non-conforming items</i>	19
2.5.2 <i>Zero Acceptance Number Sampling Plans</i>	28
2.5.3 <i>Sampling plans for inspection of critical nonconformities</i>	28
2.6 COST OF SAMPLING	29
SECTION 3: THE SELECTION OF SAMPLING PLANS FOR SINGLE OR ISOLATED LOTS MOVING IN INTERNATIONAL TRADE	29
3.1 SAMPLING PROCEDURES FOR INSPECTION BY ATTRIBUTES: SAMPLING PLANS INDEXED BY LIMITING QUALITY (LQ) FOR ISOLATED LOT INSPECTION	29

3.1.1	<i>Procedure A: Producer and consumer regard lot in isolation</i>	30
3.1.2	<i>Procedure B: Producer regards lot as one of a continuing series: Consumer regards lot in isolation</i>	30
3.2	TWO AND THREE CLASS ATTRIBUTES PLANS FOR MICROBIOLOGICAL ASSESSMENTS (SEE REFERENCE 6.1)	31
3.2.1	<i>Two-class Attributes Plans</i>	31
3.2.2	<i>Three-class Attributes Plans</i>	32
	<i>The Application of Two and Three-class Attributes Plans</i>	33
3.3	SINGLE SAMPLING PLANS FOR AVERAGE CONTROL (STANDARD DEVIATION UNKNOWN).....	34
SECTION 4. THE SELECTION OF SAMPLING PLANS FOR A CONTINUOUS SERIES OF LOTS FROM A SINGLE SOURCE		35
4.1	PRESENTATION OF SECTION 4	35
4.2	SINGLE SAMPLING PLANS RECOMMENDED FOR INSPECTION OF DEFECTIVE PERCENTAGE BY ATTRIBUTES (FROM ISO 2859-1: 1989).....	38
4.2.1	<i>General</i>	38
4.2.2	<i>Recommended plans by attributes</i>	39
4.3	SINGLE SAMPLING PLANS FOR INSPECTION BY VARIABLES FOR PER CENT NONCONFORMING.....	45
4.3.1	<i>General</i>	45
4.3.2	<i>Recommended sampling plans by variables: s method</i>	46
	TABLE 14: VARIABLE SAMPLING PLANS WITH UNKNOWN STANDARD DEVIATION	47
4.3.3	<i>Recommended sampling plans by variables: σ-method</i>	53
	TABLE 17. VARIABLE SAMPLING PLANS WITH KNOWN STANDARD DEVIATION	54
4.3.4	<i>Rules and procedures of switching between inspection levels</i>	63
4.4	SINGLE SAMPLING PLANS FOR AVERAGE CONTROL	63
4.4.1	<i>Unknown standard deviation</i>	63
4.4.2	<i>Known standard deviation</i>	65
SECTION 5. THE SELECTION OF SAMPLING PLANS FOR THE INSPECTION BY VARIABLES OF BULK MATERIALS: KNOWN STANDARD DEVIATION		66
5.1	GENERAL	66
5.2	STANDARDISED SAMPLING PROCEDURES FOR THE INSPECTION OF INDIVIDUAL LOTS	67
SECTION 6. REFERENCES		69