

Index

A

Accuracy, 8, 166

 flow rate, 279

 gradient, 279

 photometric, 273

 wavelength, 270

Action limit lines, 288

Analysis of variance see ANOVA

ANOVA, 67

 computational scheme

 one-way ANOVA, 68

 two way-ANOVA, 69

models, 68

uses

 certification of materials, 126

 comparison of more than two means, 69

 interlaboratory-study, 306

 lack-of-fit test for linearity, 138

 method performance study, 307

 standard deviation in quality control, 289

Analytical error, 85

Analytical result, *see also* predicted value, 20, 85

Assigned value, 312, 313

B

Balance, requirements according to USP, 284

Bias, 7

Blank, blank method, 203, 207, 209

Blank control chart, 290

Box and whisker plot, 44

C

Calibration

 conditions, 81

 function

 linear, 83

 graph, 85

quadratic 103

 simplified linear, 100

Certified reference material, 305

Chi-square, table of critical values, 348

Chromatogram, performance parameters, 241

Cochran test, 56, 307

 table of critical values, 351

Coefficient of variation (CV), 307

Confidence interval, 19

 and quality, 22

 definition, 19

 for mean values, 20

linear regression

 intercept, 85

 predicted value, 86

 slope, 86

quadratic

 predicted value, 105

 simplified linear

 predicted value, 101

 slope, 100

Constant systematic errors, 166

 check for, 175

Control charts, 287

 and measurement uncertainty, 334

 CuSum charts, 298

 Shewhart charts, 288

 out-of-control rules, 289

 range chart, 290

Correlation analysis, 79

Correlation coefficient, 79

Covariance, 189

Critical value, 20, 207

 table according to

 Cochran test, 351

 David test, 350

 Dixon test, 349

 Grubbs test, 348

- trend test, 352
- table of
 - F*-distribution, 346, 347
 - t-distribution, 346
 - χ^2 - distribution, 348
- CuSum charts, *see* control charts

- D**
- David test, *see* normal distribution
- Dead volume, 280
- Decision limit, 39
- Degrees of freedom, 16
 - ANOVA, 68
 - linear regression, 86
 - simplified linear regression, 100
- Design, ANOVA, 70
- Detection, limit of, 206
 - calculation, 209, 210
 - by a quick method, 211
- Distributions, 10
 - standardized normal, 11
 - t*-, 11, 20
- Dixon test, 43
 - table of critical value, 349

- E**
- Error, 1
 - α - (Type I) 38, 39, 207, 208
 - β - (Type II) 39, 208
 - analytical, 85
 - calibration, 84
 - constant systematic error, 166, 175, 189
 - gross, 9
 - propagation of, 26
 - proportional systematic, 167, 176, 179, 188
 - random, 7, 10
 - systematic, 7, 190
- Expanded uncertainty, 325

- F**
- F*-test
 - ANOVA, 69, 71
 - comparison of two standard deviations, 51
 - table of critical value
 - for $P = 95\%$, 346
 - for $P = 99\%$, 347
- Factor, 70
- Flow rate accuracy, 279
- Frequency, 10

- G**
- Gaussian
 - distribution, 11
 - law of error propagation, 26

- H**
- Headspace gas chromatography (HS-GC)
 - method development, 251
 - multiple (MHE), 254
 - validation, 253
- Histogram, 10
- Homogeneity of variances, 155
 - ANOVA, 69
 - regression function, 155
 - test for, *see* *F*-test
- HPLC instrument, performance verification, 279

- I**
- Independent variable, 81
- Instrumental precision, 118
- Interactive (ANOVA)
- Intercept, 84
 - calculation, 84
 - standard deviation of, 85
- Intermediate precision, 122
- Interquartile range, 44
 - and box plot, 45

- L**
- Least significant difference (LSD), 69
- Least square estimation, 83
- Least square regression, *see* linear regression
- Limit of detection, *see* detection, limit of
- Limit of quantification, *see* quantification, limit of
- Linear regression, 91
- Linearity, 132, 279
 - and stray light, 272
 - of calibration lines, 132
 - of the injected volume, 279
- test for
 - lack-of-fit test by ANOVA, 138
 - Mandel test, 136
 - quality coefficient, 132
 - significance of the quadratic regression coefficient, 143
 - visual inspection, 134
- Lower action limit LAL, 288
- Lower warning limit LWL, 288

- M**
- MAD, 44, 313
- MAD_E, 313

- Mandel test, 136
Mean, mean value, 11, 12
 comparison of, 59, 67
 standard deviation of, 17
Mean absolute deviation, 44
Mean control chart, 290, 334
Mean squares (ANOVA), 140
Measurement uncertainty, 8, 319
 cause and effect diagram, 321
 combined uncertainty, 322
 definition of, 320
 expanded uncertainty, 320
 identifying of uncertainty sources, 321
Nordtest procedure, 333
quantifying uncertainty, 322
spreadsheet method for calculation, 325
steps in specifying measurand, 321
type A/B, 320
- Median, 12
- Method development, 241
 for chromatographic methods, 241
 for headspace gas chromatography, 251
 for MHE, 254
- Method performance, 306
- Multiple headspace extraction MHE, 254
- N**
- Neumann test, *see* trend test by Neumann
Normal distribution, 10
 rapid test for, 40
- O**
- One-sided hypothesis test, 38
- Outliers, 9
 and box plot, 45
 tests for
 Dixon, 43
 Hampel, 43
 Grubbs, 43
- Out-of-control situation, 289
- P**
- Peak symmetry, 242
Pearson criterion, 20
Performance verification of
 balances, 284
 HPLC instruments, 279
 column temperature, 280
 detector, 280
 injector, 279
 pump, 279
UV-Vis spectrometers, 270
 photometric accuracy, 273
resolution, 272
- stray light, 271
wavelength accuracy, 270
- Photometric accuracy, *see* accuracy, photometric
- Pooled standard deviation, 59
- Precision, 7, 39, 118
 and bias, 8
 of the instrument, 119
 of the analytical procedure, 121
 limit values of the, 122
- Predicted value, 86
 error of, 86
- Proficiency testing, 312
- Propagation of uncertainty, law of, 324
- Proportional systematic error, 167
 check for, 176, 179
- Q**
- Quadratic regression, 103
 model, 103
 parameters, calculation of, 103
- Quality control, 22, 287
 action/warning limits, 288
 and confidence interval, 22
 CuSum charts, 298
 Shewhart charts, 288
- Quantification, limit of, 208, 211
- Quantiles, 51
- Quartiles, 44
 and box plots, 44
- R**
- Random errors, 7, 10
- Range, *see* working range a
- Range chart, 290
- Regression, *see* linear or quadratic regression
- Relative standard deviation, 17
- Repeatability, 121
- Reproducibility, 122
- Residuals, calculation of, 84
- Resolution, 242, 272
- Retention factor, 241
- Ruggedness/robustness, 218
- S**
- Selectivity factor, 242
- Shewhart charts, 288
- Significance level, 38
 confidence interval for mean value, 38
- Standard addition method, 202
- Standard addition procedure for trueness test, 196
- Standard deviation, 16
 calculation of, 12, 16, 17

Standard deviation (*cont.*)

- comparison of
 - two, 51
 - more than two, 56
- of the slope, 86
- of the intercept, 85
- residual, 84, 100

Standard operation procedure SOP, 118

Standard uncertainty, 320, 322, 324

Stocked samples, 172, 179, 203

Stray light, 271

Sum of squares, calculation of, 16, 79, 104

T

t-Test, 59

Trend

- test by Neumann, 40

Test statistics

- Cochran test, *see* Cochran test
- Grubbs outlier *t*-test, *see* Grubbs test
- Dixon outlier test, *see* Dixon test
- F*-test, *see* *F*-test
- t*-test, *see* *t*-test

Tools, performance verification of, 269

Triangular distribution, 323

Trueness, tests for, 166

- mean value *t*-test, 167
- method comparison, 184
- recovery rate, 169
- recovery rate of stocked samples, 172

recovery function, 174

standard addition procedure, 179

True value, 8, 60, 167, 169

Two-tailed test α , 20, 38

Type I error, *see* error, α -/Type I

Type II error Type I error, *see* error, β -/Type II

U

Uncertainty *see* measurement uncertainty

Upper action limit UAL, 288, 290

Upper warning limit UWL, 288, 290

V

V-mask, 299

Validation of method performance, 117

guidelines for, 117

Validation parameters, 118

precision, 118

Variance, 11, 17

analysis of, *see* ANOVA

visual inspection of residuals, 135

W

Weighted linear least square regression, 160

Weighting factor, 160

Working range, 108

Z

Z-score, 312