

CONTENTS

PART 1	Theory of Multiple-Beam Interferometry Experimental Techniques Special Refinements	
<i>Chapter</i> 1	Interference with Multiple-Beams	3
2	Instrumentation	30
3	Fringes of Equal Chromatic Order	42
4	Crossed Fringes	54
5	Thickness of Thin Films	62
 PART 2	 Topographies of Crystal Faces	
6	Topographies of Diamond Faces	71
7	Quartz Crystals	83
8	Some Crystal Growths	93
9	Etched Diamonds	107
 PART 3	 Special Techniques	
10	Special Techniques	119
 PART 4	 Crystal Cleavages Etching of Crystals Modulated Interference Fringes	
11	Studies on Crystal Cleavages	137
12	Matched Cleavages	147
13	Etching of Cleavages	153
14	Modulated Multiple-Beam Fringes	162
 PART 5	 Crystal Oscillators	
15	The Oscillations of Quartz Crystals	167

PART 6	Studies of Surface Deformations	
	Metals	
	Indentations on Metals	
	Percussion of Diamond	
<i>Chapter</i> 16	Some Studies on Metals	183
17	Indentation Hardness-Testing of Metals	195
18	Indentations on Single Crystals	208
19	Induction of Percussion Ring-Cracks on Diamond	219
PART 7	Studies of Impacts on Metals	
	Diamond Abrasion Resistance; Polish; Sawing	
	Wear of Glazier's Diamonds	
20	Some Surface Distortion Effects	239
21	Directional Abrasion Resistance on Diamond	257
22	Polish and Sawing of Diamond	267
23	The Wear of Glazier's Diamonds	272
PART 8		
<i>Appendix</i>	Fringes of Equal Tangential Inclination	288
<i>Addendum</i>	High Resolution Fringes	288
<i>Bibliography</i>		291
<i>Index</i>		295