

Contents

CHAPTER 1 THERMODYNAMICS	
1.1 Introduction	1
1.2 Energy Conservation, State Functions, and the First Law	3
1.3 The Second Law	4
1.4 Entropy, Temperature, and the Third Law	9
1.5 Free Energies: The Thermodynamic Potentials	11
Definitions	13
Bibliography	14
Problems	14
CHAPTER 2 EQUILIBRIUM IN MULTICOMPONENT SYSTEMS	17
2.1 Introduction	17
2.2 Single-Component Systems: Allotropy	19
2.3 Composition as a Variable	23
2.4 Rules of Solid Solubility	31
2.5 The Lever Rule	33
2.6 The Phase Rule: Free Energy Reconsidered	36
Definitions	39
Bibliography	39
Problems	40
CHAPTER 3 THERMODYNAMICS OF SURFACES	46
3.1 Introduction	46
3.2 Characteristics of Surfaces	47

3.3	Units of Surface Tension and Surface Energy	48
3.4	Magnitude of Surface Energy: Metallic and Covalent Materials	49
3.5	Magnitude of Surface Energy: Ionic Materials	52
3.6	Measurement of Surface Energy	54
3.7	Adsorption	56
3.8	Further Remarks on Solid Surfaces Definitions	59
	Bibliography	59
	Problems	59

CHAPTER 4 RATES OF REACTIONS

62

4.1	Introduction	62
4.2	The Arrhenius Equation	63
4.3	Activation Energy	64
4.4	Thermodynamics of Kinetics	67
4.5	Modification of Reaction Rates Definitions	69
	Bibliography	71
	Problems	71

CHAPTER 5 DIFFUSION

75

5.1	Introduction	75
5.2	Thermodynamics of Diffusion	76
5.3	Mathematical Analysis of Diffusion	77
5.4	Experimental Measurement of Diffusion	81
5.5	Types of Diffusion	82
5.6	Atomic Mechanisms of Volume Diffusion	84
5.7	Diffusion and Defects: The Hartley-Kirkendall Effect	86
5.8	Vacancy Equilibrium in Crystals	88
5.9	Diffusion and Defects: Oxides and Ionic Crystals	89
5.10	Diffusion in Amorphous and Vitreous Solids	91

Diffusion Couples and the Phase Diagram	91
Definitions	93
Bibliography	95
Problems	95

CHAPTER 6 PHASE CHANGES 98

6.1 Introduction and Kinetics	98
6.2 Homogeneous Nucleation	99
6.3 Heterogeneous Nucleation	104
6.4 Growth of the New Phase and Phase Change Kinetics	106
Definitions	108
Bibliography	109
Problems	109

CHAPTER 7 STRUCTURAL CHANGE

7.1 Introduction	112
7.2 Solidification	113
7.3 Recrystallization	117
7.4 Precipitation Hardening	121
7.5 The Heat Treatment of Steel	123
Definitions	128
Bibliography	129
Problems	129

CHAPTER 8 SINTERING 132

8.1 Introduction	132
8.2 Properties of Fine Powders	133
8.3 Preparation for Sintering	135
8.4 Results of the Sintering Operation	137
8.5 Mechanisms of Sintering—Single-Phase Materials	137
8.6 Mechanisms of Sintering—Multiphase Materials	141
8.7 Experimental Observations	143
Definitions	143

Bibliography	144
Problems	144

CHAPTER 9 OXIDATION	146
---------------------	-----

9.1 Introduction	146
9.2 The Driving Force for Oxidation	147
9.3 Surface Films	148
9.4 Mechanisms of Film Growth	149
9.5 Rate of Film Growth	151
9.6 Protective Oxides	152
9.7 Special Effects of Oxidation	153
Definitions	156
Bibliography	156
Problems	156

CHAPTER 10 AQUEOUS CORROSION	159
------------------------------	-----

10.1 Introduction	159
10.2 Electrochemistry	160
10.3 The Electromotive Series	162
10.4 Concentration and Cell Potential	163
10.5 The Cathode Reaction, Polarization, and Surface Films	164
10.6 The Galvanic Series	166
10.7 Aqueous Corrosion	166
10.8 The Corrosion Rate, Polarization, and Passivity	170
10.9 Corrosion Control	175
Definitions	176
Bibliography	176
Problems	177

APPENDIX A	179
------------	-----

APPENDIX B	187
------------	-----

APPENDIX C	206
------------	-----

INDEX	213
-------	-----