

## **CONTENTS**

<b>PREFACE</b>	xvii
<b>ACKNOWLEDGMENTS</b>	xxiii
<b>CUMULATIVE LISTING OF VOLUMES IN SERIES</b>	xxv
<b>CHAPTER 1 INTRODUCTION</b>	1
1.1. Photothermal Spectroscopy	1
1.2. Basic Processes in Photothermal Spectroscopy	3
1.3. Photothermal Spectroscopy Methods	7
1.4. Application of Photothermal Spectroscopy	13
1.5. Illustrative History of Photothermal Spectroscopy	14
1.5.1. Nature of the Photothermal Effect	14
1.5.2. Photoacoustic Spectroscopy	16
1.5.3. Photothermal Lens Spectroscopy	19
1.5.4. Photothermal Interferometry	25
1.5.5. Two-Laser photothermal Lens Spectroscopy	29
1.5.6. Photothermal Deflection, Refraction, and Diffraction	32
1.5.7. Photothermal Radiometry	39
1.5.8. Historic Summary	41
1.6. Some Important Features of Photothermal Spectroscopy	42
References	45
<b>CHAPTER 2 ABSORPTION, ENERGY TRANSFER, AND EXCITED-STATE RELAXATION</b>	49
2.1. Factors Affecting Optical Adsorption	49
2.2. Optical Excitation	57

2.2.1. Kinetic Treatment of Optical Transitions	58
2.2.2. Nonradiative Transitions	66
2.3. Excited-State Relaxation	70
2.3.1. Rotational and Vibrational Relaxation	72
2.3.2. Electronic States and Transitions	79
2.3.3. Electronic-State Relaxation	82
2.4. Relaxation Kinetics	89
2.5. Nonlinear Absorption	93
2.5.1. Multiphoton Absorption	95
2.5.2. Optical Saturation of Two-Level Transitions	97
2.5.3. Optical Bleaching	100
2.5.4. Response Times During Optical Bleaching	103
2.5.5. Optical Bleaching of Organic Dyes	105
2.5.6. Relaxation for Impulse Excitation	108
2.5.7. Multiple-Photon Absorption	109
2.6. Absorbed Energy	112
References	117

### **CHAPTER 3 HYDRODYNAMIC RELAXATION: HEAT TRANSFER AND ACOUSTICS**

3.1. Local Equilibrium	
3.2. Thermodynamic and Optical Parameters in Photothermal Spectroscopy	121
3.2.1. Enthalpy and Temperature	121
3.2.2. Energy and Dynamic Change	124
3.3. Conservation Equations	125
3.4. Hydrodynamic Equations	132
3.5. Hydrodynamic Response to Photothermal Excitation	136
3.5.1. Solving the Hydrodynamic Equations	136
3.5.2. Thermal Diffusion Mode	139
3.5.3. Fourier–Laplace Solutions for the Thermal Diffusion Equation	141
3.5.4. Propagating Mode	144

3.5.5. Summary of Hydrodynamic Mode Solutions	146
3.6. Density Response to Impulse Excitation	147
3.6.1. One-Dimensional Case	148
3.6.2. Two-Dimensional Cylindrically Symmetric Example	152
3.6.3. Coupled Solutions	161
3.7. Solutions Including Mass Diffusion	162
3.8. Effect of Hydrodynamic Relaxation on Temperature	169
3.9. Thermodynamic Fluctuation	170
3.10. Noise-Equivalent Density Fluctuation	173
3.11. Summary	178
Appendix 3A: Thermodynamic Parameter Calculation	179
Appendix 3B: Propagating Mode Impulse Response for Polar Coordinates in Infinite Media	180
References	183
<b>CHAPTER 4 OPTICAL PRINCIPLES FOR PHOTOTHERMAL SPECTROSCOPY</b>	<b>185</b>
4.1. Light Propagation	186
4.1.1. Maxwell's Equations	186
4.1.2. Plane Waves in Vacuum	187
4.1.3. Polarization	189
4.1.4. Plane Wave Propagation in Dielectric Media	190
4.1.5. Refractive Index	191
4.1.6. Relating Macroscopic Dielectric Constant to Molecular Parameters	192
4.1.7. Refractive Index at Optical Frequencies	194
4.1.8. Polarizability	196
4.1.9. Quantum Mechanical Polarizability	199
4.2. Fundamental Modes in Homogeneous Media	201
4.2.1. TEM <sub>00</sub> Mode	202

4.2.2. Irradiance of Gaussian Beams	205
4.2.3. Higher-Order Gaussian Modes	205
4.3. Spatial Transformation of Rays by Optical Elements	209
4.3.1. Paraxial Ray Tracing	209
4.3.2. Ray Propagation in Isotropic Media	211
4.3.3. Ray Propagation Through a Lens and Lenslike Media	212
4.4. Transformation of Gaussian Modes	216
4.4.1. Gaussian Mode Propagation in Isotropic Media	218
4.4.2. Focusing Gaussian Beams	220
4.5. Paraxial Diffraction Theory	223
4.5.1. Fresnel Diffraction	223
4.5.2. Fraunhofer Diffraction	227
4.5.3. Diffraction Elements	227
4.5.4. Fourier Transform Properties of Apertures	228
4.5.5. One- and Two-Dimensional Fourier Transforms	230
4.5.6. Diffraction Properties of the Ideal Thin Lens	232
4.5.7. Fourier Transform Properties of the Lens	234
4.5.8. Imaging with Lenses	235
4.5.9. Diffraction Transforms with Coherent and Incoherent Light	238
4.5.10. Finite-Diameter Lens Aperture Effects	240
4.5.11. Lens Pupil and Optical Transfer Functions	243
4.6. Diffraction of Gaussian Beams	246
4.6.1. Free-Space Propagation of Gaussian Beams	246
4.6.2. Focusing Gaussian Beams	248
4.6.3. Lens Transform Properties with Gaussian Beams	250
4.6.4. Gaussian Beam Attenuation	250

CONTENTS	xi
4.6.5. Effects of Spatial Noise	252
<b>4.7. Diffraction Gratings</b>	<b>255</b>
4.7.1. Thin-Amplitude-Transmission Gratings	257
4.7.2. Thin-Phase-Transmission Gratings	260
4.7.3. Thick Gratings	261
References	265
<b>CHAPTER 5 TEMPERATURE CHANGE AND OPTICAL ELEMENTS IN HOMOGENEOUS SAMPLES</b>	
5.1. Temperature Change from Gaussian Excitation Sources	268
5.1.1. Thermal Diffusion Approximation	268
5.1.2. Gaussian Laser Excitation of Optically Thin Samples	270
5.1.3. Short-Pulse Laser Excitation	272
5.1.4. Continuous Laser Excitation	274
5.1.4.1. Laser Heating	274
5.1.4.2. On-Axis Temperature Change	275
5.1.4.3. Postexcitation Cooling	276
5.1.5. Chopped Laser Excitation	280
5.1.6. On-Axis Temperature Change for Periodic Excitation	283
5.1.7. Thermal Gratings	285
5.2. Thermodynamic Parameters	289
5.2.1. Thermodynamic Parameters Affecting Temperature	289
5.2.2. Convection Heat Transfer	295
5.3. Optical Elements	296
5.3.1. Phase Shift and Optical Pathlength Difference	297
5.3.2. Deflection Angle	299
5.3.3. Thermal Lens Focal Length	300
5.3.4. Grating Strength	303
5.4. Temperature-Dependent Refractive Index Change	
5.4.1. Density and Temperature Dependence of Refractive Index	

5.4.2. Population Dependence on Refractive Index	312
5.4.3. Soret Effect	314
5.4.4. Other Factors Affecting Refractive Index	316
5.5. Limitations	317
5.5.1. Excitation Beam Waist Radius Changes	317
5.5.2. Effects of Scattering and Optically Thick Samples	318
5.5.3. Finite-Extent Sample Effects	321
5.5.4. Accounting for Finite Cell Radius	323
References	328
<b>CHAPTER 6 PHOTOTHERMAL SPECTROSCOPY IN HOMOGENEOUS SAMPLES</b>	<b>331</b>
6.1. Photothermal Interferometry	331
6.2. Photothermal Deflection	338
6.2.1. Deflection Angle for Pulsed Laser Excitation	338
6.2.1.1. Collinear Probe Geometry	338
6.2.1.2. Crossed-Beam Probe Geometry	341
6.2.2. Deflection Angle for Continuous and Chopped Laser Excitation	342
6.2.2.1. Continuous Excitation with Parallel-Probe Geometry	342
6.2.2.2. Continuous Excitation with Crossed-Probe Geometry	344
6.2.2.3. Chopped Excitation with Parallel Probe	346
6.2.3. Deflection Angle Detection	349
6.2.3.1. Probe Laser Beam Waist Effect	350
6.2.3.2. Straightedge Apparatus	351
6.2.3.3. Position-Sensing Detectors	352
6.2.3.4. Other Methods to Detect Deflection Angle	354
6.2.3.5. Differential Deflection Angle	357
6.3. Thermal Lens Focal Length	359
6.3.1. Pulsed Excitation Thermal Lens Focal Length	359

CONTENTS	xiii
6.3.1.1. Time-Dependent Focal Length	359
6.3.1.2. Sample Pathlength Limitations	360
6.3.1.3. Crossed-Beam Arrangement	363
6.3.2. Continuous and Chopped Excitation	364
Thermal Lens Focal Length	364
6.3.2.1. Continuous Excitation	364
6.3.2.2. Sample Pathlength Limitations	365
6.3.2.3. Crossed-Beam Geometry	365
6.3.2.4. Chopped Excitation	367
6.3.3. Focal Length for Periodic Excitation	368
6.4. Detecting the Thermal Lens	371
6.4.1. Signal for Symmetric Lens	371
6.4.2. Signal for Different $x$ and $y$ Focal Lengths	
6.4.3. Lock-in Amplifier or Pulse-Height-Detected Signal	376
6.4.4. Signal Development with Large Apertures	
6.4.5. Signal Development Based on Image Analysis and Other Optical Filters	381
6.5. Types fo Photothermal Lens Apparatus	384
6.5.1. Single-Laser Apparatus	385
6.5.2. Differential Single-Laser Apparatus	387
6.5.3. Two-Laser Apparatus	388
6.6. Two-Laser Photothermal Lens Spectroscopy	397
6.6.1. Excitation Wavelength Dependence in Two-Laser Photothermal Spectroscopy	398
6.7. Differential Two-Laser Apparatuses	399
6.8. Diffractial Effects	402
6.8.1. Probe Laser Diffraction Effects for Pulsed Excitation	
6.8.2. Probe Laser Diffraction Effects for Continuous Excitation	
6.8.3. Diffraction Effects for Single-Laser Photothermal Lens	415
6.8.4. Effect of Diffraction on the Thermal Lens Enhancement Factor	416
References	418

<b>CHAPTER 7 ANALYTICAL MEASUREMENT AND DATA PROCESSING CONSIDERATIONS</b>	<b>421</b>
7.1. Sensitivity of Photothermal Spectroscopy	422
7.1.1. Thermal Lens-Enhancement Factors	422
7.1.2. Relative Sensitivity of the Photothermal Lens and Deflection Spectroscopies	
7.1.3. Relating Photothermal Signals to Absorbance and Enhancement	431
7.1.4. Intrinsic Enhancement of Two-Laser Methods	432
7.1.5. Enhancement Limitations	435
7.2. Considerations for Trace Analysis	437
7.3. Optical Instrumentation for Analysis	439
7.3.1. Differential Measurement	439
7.3.2. Spectroscopic Measurement	441
7.3.3. Fiber Optics	442
7.4. Processing Photothermal Signals	447
7.4.1. Analog Signal Processing	452
7.4.2. Digital Signal Processing	454
7.5. Photothermal Data Processing	460
7.5.1. Calibration	460
7.5.2. Excitation Irradiance Curves	463
7.5.3. Limits of Detection and Quantitation	464
7.6. Tracking Down and Reducing Noise	465
References	467
<b>CHAPTER 8 ANALYTICAL APPLICATIONS</b>	<b>471</b>
8.1. Areas of Analytical Application	471
8.2. Photothermal Spectroscopy Analysis of Stationary Homogeneous Samples	473
8.2.1. Measurement Techniques	473
8.2.2. Applications	476
8.2.2.1. Gas Phase	476
8.2.2.2. Liquid Phase	486
8.2.3. Novel Cross-Beam Apparatus for Photothermal Lens Spectroscopy	

## CONTENTS

8.3. Photothermal Spectroscopy Detection in Chromatography	488
8.3.1. Temperature Change in Flowing Samples	489
8.3.2. Deflection Angles and Inverse Focal Lengths in Flowing Samples	492
8.3.2.1. Isotropic and Turbulent Flow	492
8.3.2.2. Laminar Flow	494
8.3.3. Applications	499
8.3.3.1. Gas Chromatography and Flowing Gas Analysis	499
8.3.3.2. Liquid Phase	506
8.4. Excitation and Relaxation Kinetics	508
8.4.1. Relaxation Kinetics and Quantum Yield Studies	509
8.4.2. Photodynamic Irradiance-Dependent Signal Studies	521
8.4.3. Optical Bleaching in Organic Dye Molecules	522
8.4.4. Optical Bleaching Effects in Pulsed Laser Photothermal Spectroscopy	529
References	531
<b>CHAPTER 9 PHOTOTHERMAL SPECTROSCOPY OF HETEROGENEOUS SAMPLES</b>	<b>535</b>
9.1. Types of Heterogeneity	536
9.2. Apparatus for Photothermal Deflection	537
9.3. Surface Absorption	538
9.3.1. Thermal Diffusion at Surfaces	538
9.3.2. Temperature Change from Pulsed Excitation	539
9.3.3. Temperature Change from Continuous Excitation	
9.3.4. Temperature Change from Periodic Excitation	
9.4. Thermal Diffusion in Volume-Absorbing Samples	544
9.4.1. Volume Temperature Change for Pulsed Excitation	

9.4.2. Periodic Excitation of Volume Absorbers	545
9.5. Temperature Change in Layered Samples	546
9.5.1. Periodic Excitation of Layered Samples	549
9.5.2. Pulsed Excitation of Thick-Layered Samples	552
9.6. Surface Point Source	554
9.7. Gaussian Beam Excitation of Surfaces	559
9.8. Excitation of Layered Samples with Gaussian Beams	561
9.9. Deflection Angles with Oscillating Gaussian Excitation	565
9.10. Photothermal Reflection	568
9.11. Experiment Design for Photothermal Deflection	568
9.12. Applications to Chemical Analysis	572
9.12.1. Bulk Properties	572
9.12.2. Applications to Gel and Thin-Layer Chromatography	573
9.12.3. Other Applications to Chemical and Biological Sample Analysis	575
References	577
<b>INDEX</b>	<b>581</b>