

Contents

Foreword	XV
Preface	1
1. Some questions on the application of (spectro)photometric methods	3
1.1. The position of photometric methods in trace analysis	3
1.2. Further possibilities of application and development of photometric reagents	7
References	10
2. Planning, elaboration and control of analytical methods	12
2.1. Clarification of the demands to be made of the method	12
2.2. Choice of the reagent, or the coloured compound on which the determination is based	14
2.2.1. Characterization of photometric reagents	14
2.2.2. Classification of photometric methods according to the nature of the absorbing component	20
2.3. Planning and elaboration of photometric methods	22
2.3.1. Introduction	22
2.3.2. Establishment of the sensitivity attainable with the chosen reagent	24
2.3.3. Establishment of optimum conditions for photometric determination	26
2.4. Types of disturbing effects and possibilities for their elimination	31
2.4.1. Classification of disturbing effects	31
2.4.2. Means of elimination of the disturbing effect	32
2.4.3. Separation from disturbing substances	35

2.5. Compilation of the analytical procedure	38
References	41
3. Methods suitable for separation of interferences, and concentration possibilities	43
3.1. Precipitation separation	44
3.2. Ion-exchange. Chromatographic procedures	52
3.3. Extraction	58
3.3.1. Mechanism of extraction. The most important extraction systems	59
3.3.2. Factors influencing extraction	60
3.3.3. Washing of organic phase. Re-extraction	67
3.3.4. Undesired phenomena in the extraction	68
3.3.5. Non-traditional extraction systems	69
3.4. Distillation methods	70
3.5. Electrochemical methods	72
3.6. Comparison of separation methods	74
References	76
4. preparation of samples for analysis	80
4.1. Sampling	80
4.2. Storage of samples	83
4.3. Sample processing and pretreatment	84
4.4. Pretreatment of samples of high organic matter content	85
4.5. Digestion of rocks and ores	96
4.5.1. Acidic treatment of samples	97
4.5.2. Digestion by fusion	101
4.5.3. Other means of digestion	105
4.6. Dissolution of metals, alloys and certain metal compounds .	106
4.7. Phaseanalysis	108
4.7.1. Soil examinations	109
4.7.2. Analysis of ores and ore-processing products	110
4.7.3. Phase analysis in metallurgy	111
References	113
5. The most important factors influencing the accuracy of determination . Error sources	117

5.1. Losses in the analysis	117
5.2. Contamination during the analysis	122
5.2.1. Contamination during sampling, processing and storage	123
5.2.2. Contamination during analytical operation	125
5.3. Errors in the solution equilibria. Standard solution and reagents	129
5.3.1. Errors arising from an incorrect knowledge of concentration	129
5.3.2. Errors arising from incorrect compositions of reagents	130
5.3.3. Errors arising from disturbance of the solution equilibria	131
5.4. Control of the suitability of the final solution for determination	137
5.5. Control of the accuracy of the methods with standard samples	140
References	141
6. Determination of the individual elements	144
Introduction	144
6.1. Alkali metals	145
References	146
6.2. Aluminium	146
References	150
6.3. Antimony	151
References	154
6.4. Arsenic	155
References	158
6.5. Barium and strontium	159
References	160
6.6. Beryllium	161
References	163
6.7. Bismuth	164
References	167
6.8. Boron	167
References	172
6.9. Cadmium	172
References	174
6.10. Calcium	174
References	178
6.11. Chloride	178

References	180
6.12. Chromium	180
References	184
6.13. Cobalt	184
References	189
6.14. Copper	189
References	195
6.15. Fluorine	196
References	200
6.16. Gallium	201
References	205
6.17. Germanium	205
References	208
6.18. Indium	209
References	213
6.19. Iron	213
References	218
6.20. Lanthanides and yttrium	219
References	234
6.21. Lead	235
References	239
6.22. Magnesium	240
References	243
6.23. Manganese	244
References	248
6.24. Mercury	248
References	251
6.25. Molybdenum and tungsten	251
References	258
6.26. Nickel	259
References	262
6.27. Niobium	263
References	267
6.28. Nitrogen compounds	268
References	272
6.29. Noble metals (silver, gold, platinum metals)	273

References	277
6.30. Phosphorus	278
References	283
6.31. Rhenium	284
References	286
6.32. Scandium	287
References	289
6.33. Selenium	290
References	294
6.34. Silicon	294
References	299
6.35. Sulphur compounds	299
References	303
6.36. Tellurium	304
References	307
6.37. Thallium	308
References	310
6.38. Thorium	310
References	314
6.39. Tin	315
References	318
6.40. Titanium	319
References	324
6.41. Uranium	324
References	333
6.42. Vanadium	334
References	338
6.43. Zinc	338
References	342
6.44. Zirconium	343
References	345
Appendix	347
Subject index.	399