

CONTENTS

Introduction	3
Section 1. Points to check for standardising conditions	5
Section 2. Notes on procedure	11
Section 3. Notes on selection of staff for colour measurement	12
Section 4. Notes on the production of uniform samples	12
Section 5. Procedure for converting a Lovibond Schofield Tintometer in to a standard B.D.H. pattern Lovibond Tintometer and vice versa	13
Section 6. The Wesson Colorimeter	14