

CONTENTS

CHAPTER 1 INTRODUCTION	1
I. Trace Analysis	1
CHAPTER 2 BASIC ASPECTS OF QUANTITATIVE ULTRATRACE ANALYSIS	12
I. Literature on Ultratrace Analysis	14
II. The Blank	15
III. Accuracy and Precision	18
IV. Standards	20
V. Stability of Dilute Solutions	27
VI. Measuring Small Volumes of Solutions	33
VII. Summary	42
CHAPTER 3 THE LABORATORY	46
I. Airborne Contamination	46
II. Clean Analytical Laboratories	50
CHAPTER 4 MATERIALS FOR CONTAINERS AND APPARATUS	69
I. Storage of Chemicals	69
II. Leaching	71
III. Selection of Materials	75
IV. Cleaning Procedures	92
CHAPTER 5 PURIFICATION OF REAGENTS	98
I. Methods of Purification	99
II. Gases	137
CHAPTER 6 CONTAMINATION CONTROL DURING ROUTINE ANALYTICAL OPERATIONS	151
I. Sampling	151
II. Heating and Drying	155
III. Fusion	157
IV. Ashing	164
V. Decomposition and Dissolution	165
VI. Concentration of Trace Elements	173
VII. Stirring	184
VIII. Filtration	185

CHAPTER 7 SELECTED METHODS FOR DETERMINING ULTRATRACE ELEMENTS IN REAGENTS AND MATERIALS	193
I. Neutron Activation Analysis (NAA)	193
II. Radioisotope Dilution (RID)	215
III. Stable Isotope Dilution (SID)	220
IV. X-Ray Fluorescence Spectroscopy	225
V. Spark Source Mass Spectrometry	234
VI. Emission Spectroscopy (ES)	236
VII. Atomic Absorption (AAS) and Atomic Fluorescence Spectroscopy (AFS)	239
VIII. Summary	241
APPENDIX	247
I. Abbreviations, Definitions, and Symbols	247
II. Storage Conditions for Minimum Loss of Trace Elements	248
III. Suppliers of Specialty Products for the Analytical Laboratory	249
INDEX	253