

Vapor Pressure Measurements

BY R. COOPER AND D. R. STRANKS, DEPARTMENT OF CHEMISTRY,
UNIVERSITY OF MELBOURNE, AUSTRALIA

Contents

I. Introduction.....	2
II. Temperature Control.....	3
III. Reactive and Corrosive Compounds—Volatile Compounds (0.1–760 mm Hg)	4
A. Methods.....	4
1. Manometers with Corrosion-Resistant Fluids.....	5
2. Buffer Manometers.....	5
3. Spiral Gages.....	6
4. Bourdon Gages and Pressure Multipliers.....	9
5. Bellows Manometers.....	12
6. Boiling Point Methods.....	19
7. Recommendations.....	21
IV. Compounds of Low Volatility: Pressure Range 10^{-4} – 10^{-6} mm Hg.....	22
A. Dynamic Methods.....	22
1. Transpiration (Gas Saturation) Methods.....	22
2. Knudsen Effusion Techniques.....	28
3. Langmuir Rate of Evaporation Methods.....	36
B. Static Methods.....	39
1. Vibrating Quartz Gages.....	39
2. Thermistor Manometers.....	43
C. Mass Spectrometric Methods.....	46
1. Dynamic Methods.....	49
2. Static Methods.....	52
D. Recommendation.....	54
V. The Measurement of Very Low Gas Pressures (less than 10^{-6} mm Hg) (Radiotracer Techniques).....	54
A. Static Methods.....	55
B. Dynamic Methods.....	59
1. Transpiration or Gas Saturation.....	59
2. Langmuir's Free Evaporation Method.....	60
3. Knudsen Effusion Methods.....	61
4. Isotope Exchange Method.....	70
5. Isotope Effects.....	71
C. Recommendation.....	74
VI. Molecular Weight Determinations.....	75
A. Methods for Determining the Molecular Weights of Vapors.....	76

1. Mass Spectrometry	76
2. Molecular Beam Methods.	77
3. Vapor Density Measurements.	78
VII. Thermodynamic Calculations from Vapor Pressure Data.	78
A. Second Law Treatment.	79
B. Third Law Treatment.	79
References.	80