

## CONTENTS

## PART ONE. CRITICAL PHENOMENA AND PHASE TRANSFORMATIONS OF THE SECOND KIND

Thermodynamics of Mesophases	3
Fluctuations and Thermodynamic Stability of Systems in the Region of Critical and Hypercritical Transformations	15
Phase Transformations of the Second Kind	21
Effect of Certain Additions on the Physico-Chemical Properties of Barium Titanate Single Crystals at Phase Transformation Points and in the Ferroelectric Region	33
Study of the Velocity of Propagation of Ultrasound in Triglycine Selenate in the Curie Temperature Region	39
Study of X-Ray Scattering in Crystals of Some Ferroelectrics in the Region of the Curie Temperature	43

## PART TWO. SOLID STATE TRANSFORMATIONS

Thermal Effects of the Transformations of Metals and Semiconductors in the Solid and Liquid States	49
Variation of the Segregation Coefficient of Impurities in Germanium with Concentration	57
Study of Heterogeneous Equilibrium during the Crystallization of Germanium from Melts Containing Elements of the Donor and Acceptor Types	61
Growth of Germanium Crystals from a Melt Containing a Considerable Amount of Impurity	69
Method of Decorating the Structure of Silicon Bars by Fusing a Very Thin Surface Layer	75
Certain Characteristics of the Growth of Single Crystals of Compounds in the AIII Bv Group	77
Laws of Polymorphic Transformations of Elements in Connection with Their Electronic Structures	83
Growth of a Single Crystal from the Solid Phase during a Polymorphic Transformation of n-Dichloro Benzene	95
Phase Transformations in Naphthalene Crystals	101
Role of Structural Impurities in Phase Transformations in Solids	105
Some Question on the Kinetics of Phase Transformations	113