

Contents

Preface	xvii
Chapter 1. Atomic Bonding and Crystal Structure	1
<i>Introduction</i>	1
1-1. <i>Structure of Materials</i>	1
<i>Bonding in Solids</i>	3
1-2. <i>Ionic Bonding</i>	4
1-3. <i>Covalent Bonding</i>	7
Molecular orbitals	7
Polymer structures	10
<i>Crystal Symmetry</i>	14
1-4. <i>Molecular and Crystal Point Groups</i>	14
1-5. <i>Metallic Structures</i>	19
1-6. <i>Ionic and Covalent Structures</i>	22
<i>Quantitative Operations with Crystal Structures</i>	25
1-7. <i>Directions and Planes in Crystal Structures</i>	25
1-8. <i>Stereographic Projection</i>	30
<i>Diffraction Studies of Crystal Structures</i>	34
1-9. <i>Diffraction Equations</i>	36
1-10. <i>X-ray Diffraction</i>	42
1-11. <i>Electron Diffraction</i>	49
1-12. <i>Neutron Diffraction</i>	50
Problems	52
References	56

Chapter 2. Phase Diagrams	59
<i>Interpretation of Phase Diagrams</i>	60
2-1. Systems, Components, and Phases	60
2-2. One-component Systems	61
The Phase rule	62
Polymorphism and metastability	63
2-3. Two-component systems	63
Solid-solution Systems	64
Eutectic Systems	66
2-4. Phases in Organic Polymers	69
<i>Thermodynamic Basis of Phase Diagrams</i>	72
2-5. Introductory Example	72
2-6. Stable Phases in a One-component System	76
2-7. Calculation of a Simple Eutectic Diagram	79
2-8. Thermodynamics of Solutions	81
2-9. Calculation of an Ideal Solid-solution Diagram	83
<i>Derivation of Phase Diagrams from Free-energy Curves</i>	85
2-10. Ideal-solution Behavior	85
2-11. Nonideal Behavior	86
Sources of free-energy data	86
Critical points and spinodal decomposition	88
The monotectic reaction	90
The peritectic reaction	92
Reactions between solids of different types	94
<i>Nonequilibrium Aspects of Phase Diagrams; Solid-state Reactions</i>	97
2-12. <i>Nonequilibrium</i> Solidification	97
2-13. Metastability in Solid-state Reactions	100
<i>Multicomponent Systems</i>	102
2-14. Methods of Representation and Analysis	104
2-15. <i>Liquidus</i> Projections	107
Problems	109
References	114

Chapter 3. Microstructures and Stereometric Microscopy	115
<i>Microscopy</i>	115
3-1. Preparation of the Specimen	115
3-2. The Light Microscope	117
3-3. Identification of Phases	120
3-4. Electron Microscopes	122
Replica electron microscopy	123
Scanning electron microscope	124
Thermionic-emission microscope	124
<i>Morphology of Microstructures</i>	124
3-5. Classification of Microstructures	126
3-6. Concepts from Topology	129
3-7. Stereometric Microscopy	131
 Problems	 136
 References	 140
 Chapter 4. Imperfections in Crystals	 143
<i>Thermal Vibrations</i>	143
4-1. Lattice Vibrations	144
4-2. The Nature of Phonons	146
<i>Point Defects</i>	148
4-3. Equilibrium Concentration of Vacancies in Metals	148
4-4. Sources and Sinks for Vacancies in Metals	151
4-5. Point Defects in Nonmetallic Crystals	154
Pure silicon and doping	154
Pure MX-type compounds	158
<i>The Nature of Dislocations</i>	165
4-6. Diffraction Studies of Lattice Defects	165
4-7. Stacking Faults	167
4-8. Dislocation Lines and Burgers Vectors	170

<i>Dislocation Reactions</i>	174
4-9. <i>Forces on Dislocations</i>	174
4-10. <i>Motion of Dislocations</i>	178
4-11. <i>Interaction of Dislocations</i>	179
4-12. <i>Dislocation Arrays</i>	183
<i>Imperfections in Organic Polymers</i>	187
Problems	189
References	193
 Chapter 5. Phases and Interfaces in Material Systems	 195
<i>Noncrystalline Phases</i>	195
5-1. <i>Gases and Liquids</i>	195
5-2. <i>Glasses</i>	197
Metallic glasses	199
Oxide glasses	201
Glassy polymers	204
<i>Crystalline Phases</i>	208
5-3. <i>Simple Phases</i>	208
Surfaces	208
Internal boundaries	212
5-4. <i>Solid Solutions</i>	216
Factors limiting solid solubility	218
Departures from randomness	221
Strength of solid solutions	225
5-5. <i>Intermediate Phases</i>	228
Types of intermediate phases	228
Structure of important phases	230
<i>Two-phase Systems</i>	232
5-6. <i>Equilibrium of a Condensed Phase with its Vapor</i>	233
5-7. <i>Equilibrium between Solid and Liquid Phases</i>	234
5-8. <i>Multiphase Solids</i>	239

Problems	242
References	245
 Chapter 6. Transport in Materials	 247
<i>Introductory Examples of Diffusion</i>	247
6-1. <i>Fick's First Law</i>	248
6-2. <i>Fick's Second Law</i>	251
<i>Influence of Defects on Diffusion</i>	257
6-3. <i>Self-diffusion</i>	257
6-4. <i>Tracer Diffusion</i>	263
6-5. <i>Chemical Diffusion</i>	264
Interdiffusion coefficient, $\tilde{D}$	265
Intrinsic diffusion coefficient, D_1	265
Doping of Silicon	269
6-6. <i>Alternatives to Volume Diffusion</i>	272
Short-circuit diffusion	273
Sintering processes	275
<i>Other Transport Phenomena</i>	277
6-7. <i>General Transport Equation</i>	278
Electrotransport of carbon in iron	284
Thermodiffusion in pure gold	285
6-8. <i>Two-phase Diffusion</i>	287
6-9. <i>Multicomponent Diffusion</i>	289
 Problems	 292
References	295
 Chapter 7. Phase Transformations	 297
<i>Vapor→Solid Transformations</i>	297
7-1. <i>Condensation-euaporation Equilibrium</i>	298

7-2. Vaporization	300
7-3. Condensation	301
Liquid—Solid Transformations	307
7-4. Nucleation	307
7-5. Growth of Pure Substances	310
7-6. Growth from Liquid Solutions	315
Formation of a solid solution	315
Zone melting	319
Formation of a two-phase solid	323
Transformations in Solids	328
7-7. Formal Theories of Transformation	329
Nucleation	329
Growth	333
Description of overall transformation	336
Crystallization in organic polymers	338
7-8. Transformations to Stable Phases	341
Isothermal transformations in steel	341
Cellular precipitation	344
Spinodal decomposition	344
Order-disorder transformations	347
7-9. Transformations to Transition Phases	349
Precipitation reactions	349
Martensitic reactions	353
Problems	358
References	360
 Chapter 8. Annealing Processes in Materials	 363
Initial State of Material	363
8-1. Cold-worked Materials	363
8-2. Other Metastable States	369
Recovery	370
8-3. Nature of the Recovery Process	370
8-4. Behavior of Dislocations During Recovery	372

<i>Recrystallization</i>	375
8-5. <i>Recrystallization of Inorganic Materials</i>	375
8-6. <i>Recrystallization</i> of Organic Polymers	383
<i>Grain Growth</i>	386
8-7. <i>Migration of Grain Boundaries</i>	386
8-8. <i>Grain Encounters</i>	389
8-9. <i>Impediments to Grain Growth</i>	391
Problems	393
References	397
 Chapter 9. Deformation of Materials	 399
<i>Introduction</i>	399
9-1. <i>Stress</i>	400
9-2. <i>Strain</i>	402
<i>Elastic Deformation</i>	404
9-3. <i>Hooke's Law</i>	404
9-4. <i>Variation of Elastic Constants</i>	407
9-5. <i>Anelasticity</i>	411
9-6. <i>Elastomeric</i> Deformation	413
<i>Plastic Deformation</i>	414
9-7. <i>Atomic Displacements Over Multiple Lattice Spacings</i>	414
Crystal slip	415
Chain mobility	419
9-8. <i>Atomic Displacements Over Fractional Lattice Spacings</i>	421
Twinning	421
Local rotation of lattice	422
Displacements at high temperatures	422
<i>Technical Aspects of Plastic Flow</i>	422
9-9. <i>Equations for Plastic Flow</i>	424
9-10. <i>Yielding and Strain Hardening</i>	425
9-11. <i>Test Methods and Applications</i>	429
9-12. <i>Strengthening Mechanisms</i>	435

<i>Viscoelasticity</i>	441
9-13. <i>Viscoelastic Deformation</i>	441
9-14. <i>Models of Viscoelastic Behavior</i>	444
Problems	446
References	450
 Chapter 10. Fracture of Materials	 453
<i>Introduction</i>	453
10-1. <i>Characteristics of Tensile Fracture</i>	453
Brittle fracture	454
Ductile fracture	456
Influence of slip on fracture	458
Creep fracture	460
10-2. <i>Theoretical Strength</i>	462
<i>Factors Determining Fracture Behavior</i>	465
10-3. <i>Effect of Flaws</i>	465
10-4. <i>Role of Plastic Deformation in Fracture</i>	467
Crack propagation	468
Crack initiation	468
10-5. <i>Fracture of High-strength Materials</i>	473
<i>Effects of Environment and Repeated Loading</i>	477
10-6. <i>Environmental Effects</i>	477
Liquid-metal embrittlement	478
Hydrogen embrittlement	478
Stress-corrosion cracking	479
10-7. <i>Fatigue</i>	481
 Problems	 484
References	486

Chapter 11. Deterioration of Materials **489**

<i>Chemical Reactions of Polymers and of Ceramics</i>	489
11-1. <i>Reactions of Components</i>	490
11-2. <i>Breaking of Polymer Chains</i>	492
11-3. <i>Dissolution and Swelling</i>	495
<i>Electrochemical Fundamentals</i>	496
11-4. <i>Equilibrium Aspects</i>	498
Single-electrode reactions	499
Potential-pH diagrams	502
11-5. <i>Kinetic Aspects</i>	505
<i>Electrochemical Corrosion</i>	508
11-6. <i>Anodic and Cathodic Reactions</i>	508
11-7. <i>Surface Layers and Passivity</i>	513
11-8. <i>The Eight Types of Corrosion</i>	515
11-9. <i>Dissolution Processes</i>	517
<i>Oxidation of Metals and Alloys</i>	519
11-10. <i>Oxidation of Metals</i>	519
11-11. <i>Oxidation of Alloys</i>	524
<i>Protection of Materials</i>	524
11-12. <i>Protection of Iron</i>	525

Problems **528****References** **531****Chapter 12. Electronic Structure and Physical Properties** **533**

<i>Electron Theory of Solids</i>	533
12-1. <i>Free-electron Theory</i>	536
12-2. <i>Brillouin Zones and Energy Bands</i>	537
<i>Electrical and Thermal Properties</i>	540
12-3. <i>Electrical Conductivity</i>	540
Metallic conduction	541
Materials with filled bands	545
Superconductivity	547

12-4. <i>Thermal Properties</i>	551
Specific heat	551
Thermal conductivity	552
Thermoelectric effects	552
12-5. <i>Dielectric Properties</i>	556
Dielectric materials	556
Ferroelectric materials	560
<i>Magnetic Properties</i>	562
12-6. <i>Types of Magnetism</i>	562
Diamagnetism and Paramagnetism	563
Ferromagnetism	565
Ferrimagnetism	569
12-7. <i>Magnetic Materials</i>	571
Magnetically soft materials	571
Magnetically hard materials	572
<i>Optical Properties</i>	573
12-8. <i>Electromagnetic Waves in Materials</i>	573
12-9. <i>Optical Materials</i>	576
 Problems	 579
 References	 582
 Index	 584