

---

# Contents

---

	<i>Preface</i>	xi
<b>1 Engineering materials</b>		<b>1</b>
	1.1 Introduction	1
	1.2 The requirements	1
	1.3 The materials	2
	1.4 Structure of materials	5
	1.5 Processes	11
	1.6 The materials society	12
<b>2 Properties of materials</b>		<b>13</b>
	2.1 Introduction	13
	2.2 Properties	13
	2.3 Costs	18
	2.4 Data sources	19
<b>3 Mechanical testing</b>		<b>22</b>
	3.1 Introduction	22
	3.2 The tensile test	22
	3.3 Hardness tests	27
	3.4 Impact tests	33
	3.5 Creep	36
	3.6 Fatigue	37
	3.7 Other mechanical tests	39
	3.8 Factor of safety	42
<b>4 The crystal structure of metals</b>		<b>43</b>
	4.1 Introduction	43
	4.2 From gas to solid	43
	4.3 Metal crystals	44
	4.4 Impurities in cast metals	48
	4.5 The influence of cooling rates on crystal size	49
<b>5 Casting process</b>		<b>52</b>
	5.1 Introduction	52
	5.2 Ingot casting	52
	5.3 Sand-casting	53
	5.4 Die-casting	54
	5.5 Centrifugal casting	56
	5.6 Investment-casting	57
	5.7 Full-mould process	59
	5.8 Semi-solid metal processing	60
	5.9 The choice of casting process	60
<b>6 Mechanical deformation of metals</b>		<b>62</b>
	6.1 Introduction	62
	6.2 Slip	62

---

6.3	Annealing	66
6.4	Cold-working process	68
6.5	Hot-working processes	70
6.6	Grain flow and fibre	71
6.7	Metallurgical furnaces	74
<b>7</b>	<b>The mechanical shaping of metals</b>	<b>76</b>
7.1	Introduction	76
7.2	Hot-working processes	76
7.3	Cold-working processes	79
7.4	Powder metallurgy	86
7.5	Machining metals	88
<b>8</b>	<b>Alloys</b>	<b>92</b>
8.1	Introduction	92
8.2	Eutectics	93
8.3	Solid solutions	94
8.4	Intermetallic compounds	99
8.5	Summary: alloys	100
<b>9</b>	<b>Equilibrium diagrams</b>	<b>102</b>
9.1	Introduction	102
9.2	Obtaining equilibrium diagrams	102
9.3	Types of equilibrium diagram	105
9.4	Precipitation from a solid solution	113
9.5	Ternary equilibrium diagrams	116
<b>10</b>	<b>Practical microscopy</b>	<b>118</b>
10.1	Introduction	118
10.2	Selecting and mounting a specimen	118
10.3	Grinding and polishing the specimen	120
10.4	Etching the specimen	123
10.5	The metallurgical microscope	124
10.6	The electron microscope	127
<b>11</b>	<b>Iron and steel</b>	<b>129</b>
11.1	Introduction	129
11.2	Smelting	129
11.3	Steel-making	131
11.4	Composition of steel	133
11.5	The structure of plain-carbon steels	134
11.6	Heat-treatment of steel	139
11.7	Brittle fracture in steels	144
<b>12</b>	<b>The heat-treatment of plain-carbon steels</b>	<b>146</b>
12.1	Introduction	146
12.2	Principles of hardening	146
12.3	The hardening process	152
12.4	Tempering	153
12.5	Isothermal heat-treatments	154
12.6	Hardenability	156
12.7	The Jominy test	158
12.8	Hardenability	159
12.9	Heat treatment furnaces	160

---

<b>13 Alloy steels</b>	<b>161</b>
13.1 Introduction	161
13.2 Constructional steels	162
13.3 Tool and die steels	167
13.4 Stainless steels	171
13.5 Heat-resisting steels	174
13.6 Magnet alloys	174
13.7 The principal effects of the main alloying elements	176
<b>14 The surface hardening of steels</b>	<b>178</b>
14.1 Introduction	178
14.2 Case-hardening	178
14.3 Heat-treatment after carburising	181
14.4 Case-hardening steels	183
14.5 Nitriding	183
14.6 Ionitriding	186
14.7 Flame-hardening	186
14.8 Induction-hardening	187
14.9 Summary of surface-hardening processes	188
<b>15 Cast iron</b>	<b>189</b>
15.1 Introduction	189
15.2 Composition of cast irons	189
15.3 The influence of cooling rate on the properties of a cast iron	192
15.4 'Growth' in cast irons	193
15.5 Ordinary cast irons	194
15.6 High-duty cast irons	195
15.7 Malleable cast irons	196
15.8 Alloy cast irons	198
15.9 Which iron?	199
<b>16 Copper and its alloys</b>	<b>200</b>
16.1 Introduction	200
16.2 The extraction of copper	200
16.3 Properties of copper	201
16.4 Coppers and alloys	201
16.5 The brasses	203
16.6 Tin bronzes	206
16.7 Aluminium bronzes	210
16.8 Copper–nickel alloys	212
16.9 Other copper alloys	212
<b>17 Aluminium and its alloys</b>	<b>215</b>
17.1 Introduction	215
17.2 Extraction of aluminium	215
17.3 Properties of aluminium	216
17.4 Aluminium alloys	217
17.5 Wrought alloys which are not heat-treated	219
17.6 Cast alloys which are not heat-treated	220
17.7 Wrought alloys which are heat-treated	222
17.8 Cast alloys which are heat-treated	227
<b>18 Other non-ferrous metals and alloys</b>	<b>229</b>
18.1 Introduction	229
18.2 Nickel and its alloys	229

---

18.3	Titanium and its alloys	233
18.4	Magnesium-base alloys	236
18.5	Zinc-base alloys	236
18.6	Bearing metals	238
18.7	Other metals	241
<b>19</b>	<b>Plastics materials and rubbers</b>	<b>245</b>
19.1	Introduction	245
19.2	Types of plastics	245
19.3	Thermoplastics	247
19.4	Thermoplastic materials	250
19.5	Thermosets	262
19.6	Thermoset materials	262
19.7	Elastomers	268
19.8	Recycling of polymers	272
<b>20</b>	<b>Properties of plastics</b>	<b>274</b>
20.1	Introduction	274
20.2	Crystal and glass states	274
20.3	Mechanical properties	276
20.4	Additives	282
20.5	Shaping plastics	284
20.6	Machining polymers	287
<b>21</b>	<b>Ceramics</b>	<b>289</b>
21.1	Introduction	289
21.2	Silicate-based ceramics	289
21.3	Asbestos	292
21.4	Clay products	294
21.5	Engineering ceramics	295
21.6	Properties of ceramics	299
21.7	Cement	302
21.8	Semiconductors	304
<b>22</b>	<b>Glasses</b>	<b>307</b>
22.1	Introduction	307
22.2	Composition and structure of glass	307
22.3	Glass-transition temperature	309
22.4	Glass manufacture	310
22.5	The properties of glass	311
22.6	Glasses and their uses	312
22.7	Metallic glasses	313
<b>23</b>	<b>Composite materials</b>	<b>315</b>
23.1	Introduction	315
23.2	Particle-hardened composites	315
23.3	Dispersion-hardened materials	316
23.4	Mortar and concrete	318
23.5	Tarmacadam	319
<b>24</b>	<b>Fibre-reinforced composite materials</b>	<b>321</b>
24.1	Introduction	321
24.2	Unidirectional composites	323

---

24.3	Fibres	324
24.4	Matrix materials	326
24.5	Mechanical properties	328
24.6	Fibre-composite manufacture	329
24.7	Uses of fibre-reinforced composites	331
24.8	Reinforced wood	332
24.9	Reinforced concrete	334
<b>25</b>	<b>Methods of joining materials</b>	<b>336</b>
25.1	Introduction	336
25.2	Adhesives	336
25.3	Soldering and brazing	338
25.4	Welding	340
25.5	Arc-welding processes	340
25.6	Electric resistance welding	344
25.7	Thermo-chemical welding	346
25.8	Radiation welding	347
25.9	Solid-state welding	348
25.10	Structure of welds	349
25.11	Welding of plastics	349
<b>26</b>	<b>Causes of failure</b>	<b>352</b>
26.1	Introduction	352
26.2	Causes of failure	352
26.3	Non-destructive testing	356
26.4	Degradation of metals by oxidation	361
26.5	Degradation of metals by electrolytic corrosion	362
26.6	The protection of metal surfaces	369
26.7	Stability of plastics	371
26.8	Preservation of timber	374
26.9	Service life	375
<b>27</b>	<b>Choice of materials and processes</b>	<b>377</b>
27.1	Introduction	377
27.2	Selection of materials	379
27.3	Service requirements	379
27.4	Choice of shaping process	390
27.5	Developments in materials	392
	<i>Appendix: Properties of engineering metals</i>	395
	<i>Index</i>	397