

## CONTENTS

		Page
<b>Chapter 1</b>	<b>Basic Principles for Electric Machine Analysis</b>	<b>1</b>
1.1	Introduction	1
1.2	Magnetically Coupled Circuits	1
1.3	Electromechanical Energy Conversion	13
1.4	Machine Windings and Air – Gap MMF	36
1.5	Winding Inductances and Voltage Equations	48
1.6	References	59
1.7	Problems	59
<b>Chapter2</b>	<b>Theory of Direct - Current Machines</b>	<b>67</b>
2.1	Introduction	67
2.2	Elementary Direct-Current Machine	68
2.3	Voltage and Torque Equations in Machine Variables	73
2.4	Basic Types of Direct-Current machines	75
2.5	Block Diagrams of direct-Current machines	84
2.6	Dynamic Characteristics of Shunt Motor-Supplied form a Constant Voltage sources	87
2.7	Solid - State Converters for Direct – Current Drive Systems	98
2.8	Steady State and Dynamic Characteristics of a Shunt Motor Supplied from a Solid – State Converter	101
2.9	Linearized Machine Equations	112
2.10	Multiple – Field Windings	114
2.11	Speed Control	116
2.12	Amplidyne	128
2.13	References	130
2.14	Problems	130
<b>Chapter3</b>	<b>Reference – Frame Theory</b>	<b>133</b>
3.1	Introduction	133
3.2	Background	134
3.3	Equations of Transformation – Change of Variables	135
3.4	Stationary Circuit Variables Transformed to the Arbitrary References Frame	140
3.5	Commonly Used Reference Frames	147
3.6	Transformation between Reference Frames	148
3.7	Transformation of a Balanced Set	150
3.8	Balanced Steady State Phasor Relationships	151
3.9	Balanced Steady State Voltage Equations	154
3.10	Variables Observed from Several Frames of Reference	157
3.11	References	160
3.12	Problems	161
<b>Chapter4</b>	<b>Theory of Symmetrical Induction Machines</b>	<b>164</b>
4.1	Introduction	164
4.2	Voltage Equations in Machine Variables	165
4.3	Torque Equation in Machine Variables	169
4.4	Equations of Transformation for Rotor Circuits	170
4.5	Voltage Equations in Arbitrary Reference – Frame Variables	172
4.6	Torque Equation in Arbitrary Reference – Frame Variables	178
4.7	Commonly Used Reference Frames	178
4.8	Per Unit System	179
4.9	Analysis of Steady State Operation	181

4.10	Free Acceleration Characteristics	189
4.11	Free Acceleration Characteristics Viewed from Various Reference Frames	197
4.12	Dynamic Performance During Sudden Changes in Load Torque	203
4.13	Dynamic Performance During a Three-Phase Fault at the Machine Terminals	206
4.14	References	208
4.15	Problems	209
<b>Chapter 5</b>	<b>Theory of Synchronous Machines</b>	<b>211</b>
5.1	Introduction	211
5.2	Voltage Equations in Machine Variables	212
5.3	Torque Equation in Machine Variables	217
5.4	Stator Voltage Equations in Arbitrary Reference-Frame Variables	218
5.5	Voltage Equations in Rotor Reference-Frame Variables-Park's Equations	220
5.6	Torque Equation in Substitute Variables	227
5.7	Rotor Angle and Angle between Rotors	228
5.8	Per Unit System	229
5.9	Analysis of Steady State Operation	230
5.10	Dynamic Performance during a Sudden Change in Input Torque	240
5.11	Dynamic Performance during a Three-Phase Fault at the Machine Terminals	245
5.12	Approximate Transient Torque Versus rotor Angle Characteristics	249
5.13	Comparison of Actual and Approximate Transient Torque-Angle Characteristics during a Sudden Change in Input Torque-First Swing Transient Stability Limit	252
5.14	Comparison of Actual and Approximate Transient Torque-Angle Characteristics during a Three-Phase Fault at the Terminals-Critical Clearing Time	259
5.15	Equal-Area Criterion	263
5.16	References	267
5.17	Problems	267
<b>Chapter 6</b>	<b>Operational Impedances and Time Constants of Synchronous Machines</b>	<b>271</b>
6.1	Introduction	271
6.2	Park's Equations in Operational Form	272
6.3	Operational Impedances and $G(p)$ for a Synchronous Machine with Four Rotor Windings	273
6.4	Standard Synchronous Machine Reactances	276
6.5	Standard Synchronous Machine Time Constants	278
6.6	Derived Synchronous Machine Time Constants	279
6.7	Parameters from Short - Circuit Characteristics	282
6.8	Parameters from Frequency – Response Characteristics	289
6.9	References	295
6.10	Problems	296
<b>Chapter 7</b>	<b>Linearized Equations of Induction and Synchronous Machines</b>	<b>298</b>
7.1	Introduction	298
7.2	Machine Equations to be Linearized	298
7.3	Linearization of Machine Equations	301
7.4	Small – Displacement Stability – Eigenvalues	312
7.5	Eigenvalues of Typical Induction Machines	313
7.6	Eigenvalues of Typical Synchronous Machines	316
7.7	Transfer Function Formulation	319
7.8	Reference	324
7.9	Problems	324

<b>Chapter8</b>	<b>Reduced – Order Equations of Induction and Synchronous Machines</b>	<b>325</b>
8.1	Introduction	325
8.2	Reduced – Order Equations	326
8.3	Induction Machine Large – Excursion Behavior Predicted by Reduced – Order Equations	333
8.4	Synchronous Machine Large-Excursion Behavior Predicted by Reduced – Order Equations	340
8.5	Linearized Reduced – Order Equations	344
8.6	Induction Machine Eigenvalues Predicted by Linearized Reduced – Order Equations	352
8.7	Synchronous Machine Eigenvalues Predicted by Linearized reduced – Order Equations	353
8.8	Transfer Function Formulation	354
8.9	Closing Comments and Guidelines	358
8.10	References	358
8.11	Problems	359
<b>Chapter9</b>	<b>Unbalanced Operation of Symmetrical Induction Machines</b>	<b>360</b>
9.1	Introduction	360
9.2	Symmetrical Component Theory	361
9.3	Symmetrical Component Analysis of Unbalanced Stator Voltages	362
9.4	Reference-Frame Theory Applied to the Analysis of Unbalanced Conditions	364
9.5	Analysis of Steady State Operation with Unbalanced Stator Conditions	373
9.6	Typical Unbalanced Stator Conditions	377
9.7	Analysis of Steady State Operation with Unbalanced Rotor Conditions	385
9.8	Unbalanced Rotor Resistors	388
9.9	Method of Multiple Reference Frames	391
9.10	References	393
9.11	Problems	393
<b>Chapter 10</b>	<b>Asynchronous and Unbalanced Operation of Synchronous Machines</b>	<b>395</b>
10.1	Introduction	395
10.2	Reference – Frame Theory Applied to the Analysis of Asynchronous and Unbalanced Operation	396
10.3	Asynchronous Operation	404
10.4	Unbalanced Operation	408
10.5	References	414
<b>Chapter11</b>	<b>Theory of Symmetrical and unsymmetrical Two-Phase Induction Machines</b>	<b>415</b>
11.1	Introduction	415
11.2	Analysis of Symmetrical Two – Phase Induction Machines	416
11.3	Voltage and Torque Equations in Machine Variables for Unsymmetrical Two-Phase Induction Machines	425
11.4	Voltage and Torque Equations in Stationary Reference-Frame Variables for Unsymmetrical Two-Phase Induction Machines	427
11.5	Analysis of Steady State Operation of Unsymmetrical Two-Phase Induction Machines	431
11.6	Single-Phase Induction Machines	438
11.7	References	447
11.8	Problems	447
<b>Chapter 12</b>	<b>Computer Simulations for Induction and Synchronous Machines</b>	<b>449</b>
12.1	Introduction	449
12.2	Simulation of Symmetrical Induction Machines in the Arbitrary Reference Frame	449

12.3	Simulation of Various Modes of Operation of Symmetrical Induction Machines	452
12.4	Simulation of Unsymmetrical Two-Phase Induction Machines	456
12.5	Simulation of Synchronous Machines	457
12.6	Simulation of Various Modes of Operation of Synchronous Machines	465
12.7	Simulation of Reduced-Order Models	466
12.8	References	469
12.9	Problems	469
<b>Chapter13</b>	<b>Reference – Frame Theory Used in the Analysis and Simulation of Power Systems and Electric Drives</b>	<b>471</b>
13.1	Introduction	471
13.2	Power Systems	472
13.3	Rectifier-Inverter Electric Drive Systems	474
13.4	Inverter Operation Expressed in Synchronously Rotating Reference Frame	487
13.5	Simplified System Equations for Rectifier-Inverter Drives	492
13.6	References	497
13.7	Problems	498
<b>Chapter14</b>	<b>Theory of Brushless DC Machines</b>	<b>499</b>
14.1	Introduction	499
14.2	Voltage and Torque Equations in Machine Variables	500
14.3	Voltage and Torque Equations in Rotor References-Frame Variables	502
14.4	Analysis of Steady State Operation	504
14.5	Block Diagram and Transfer Functions	512
14.6	Dynamic Performance	515
14.7	Brushless DC Motor-Inverter Drives	519
14.8	Consideration of Steady State Harmonics	528
14.9	References	534
14.10	Problems	534
<b>Index</b>		<b>559</b>