## CONTENTS

Chapter	1.	What Machines and Transformers Have in common	
- 1	1.1	Purposes of Electrical Machines and Transformers	1
1	.2	Mechanical Torque and Power	3
1		The Role of the Magnetic Field	5
1		Types of Machines	7
		Machine Terminology	8
		Magnetic Poles in Machines	16
		Torque Development in the Three Basic Machines	20
		"Losses" and "Efficiency"	$\frac{1}{23}$
		Maximum Efficiency	26
		The Nameplate	28
		Regulation	29
	Proble	•	31
Chantan	2	Sunchannana Mashinas	
Chapter		Synchronous Machines	25
		Synchronous Machine Characteristics	35
		Construction of a Synchronous Machine	36
		Cylindrical-Rotor Theory Versus Salient-Pole Theory	49
		The Magnetomotive-Force Field of the Rotor	50
		The Rotating MMF of the Stator Armature Winding	54
		Air Gap Magnetic Field and the Flux per Pole	64
		The Voltage Induced in the Armature Winding of a Synchronous Machine	70
		The Leakage Impedance and Equivalent Circuit	87
		The Circuit Model of the Synchronous Machine	92
2		Relative Magnitudes of Synchronous-Machine Impedances: The Per-Unit	99
2		System	102
			107
		8	108
		1	110
		1 5	118
		5	119
		6 .	124
			131
			133
		1 5	144
		5	148
F	Proble	ms	152
Chapter	3.	Transformers	
- 3	3.1	Why Transformers Are Essential to Power Systems	159
3			160
3			161
3	3.4	Faraday's Law and Lenz' Law	167
3			169
		•	170
		-	179
			182
			194
		Relative Magnitudes of the Circuit – Model Constants : The	
		•	196
2	8.11	How to Find the Primary Voltage Necessary to produce a Desired	
			202
		Secondary , onage	

	3.12	Transformer Voltage Regulation	204
	3.13	Transforming Three-Phase	209
	3.14	Three-Phase Transformation with Two Transformers	216
	3.15		222
	3.16	Measuring Transformer Quantities	225
	3.17	Measurements on Three-Phase Transformers	229
	3.18	Autotransformers	233
		Instrument Transformers	235
	Probl	ems	240
Chanta	- 1	Induction on "Agraphianous" Machines	
Chapter		Induction or "Asynchronous" Machines	245
	4.1	History and Application of Induction Machines	245
	4.2	Construction of Induction Machines	247
	4.3	How the Induction Motor Works	250
	4.4	The Concept of Slip	252
	4.5	The Frequency of Rotor Voltages and Currents	253
	4.6	The Induction Motor Under Load	254
	4.7	Circuit Model of the Induction Machine	255
	4.8	Losses. Power Flow, and Efficiency of Induction Motors	266
	4.9	Air-Gap Power : The Magic Quantity	268
	4.10	Separation of Mechanical Load from Rotor Copper Loss in	
		the Circuit Model	271
	4.11	Performance Calculation Using the Circuit Model	272
	4.12	Torque – Speed Characteristics of Induction Machines	272
			270
	4.13	Some Useful Exact and Approximate Relationships	
	4.14	Control of Performance Characteristics by Rotor Design	284
	4.15	Tests to Determine Circuit – Model Impedances	291
	4.16	Starting Induction Motors	301
	4.17	Speed Control of Induction Motors	305
	Probl	ems	326
			520
	_		220
Chapter		Direct-Current Machines	
Chapter	5.1	<b>Direct-Current Machines</b> The Importance of d-c Machines	331
Chapter	5.1 5.2	<b>Direct-Current Machines</b> The Importance of d-c Machines Construction of d-c Machines	331 332
Chapter	5.1 5.2 5.3	<b>Direct-Current Machines</b> The Importance of d-c Machines Construction of d-c Machines How d-c Machines Work	331 332 335
Chapter	5.1 5.2	<b>Direct-Current Machines</b> The Importance of d-c Machines Construction of d-c Machines	331 332
Chapter	5.1 5.2 5.3	<b>Direct-Current Machines</b> The Importance of d-c Machines Construction of d-c Machines How d-c Machines Work	331 332 335
Chapter	5.1 5.2 5.3 5.4	<b>Direct-Current Machines</b> The Importance of d-c Machines Construction of d-c Machines How d-c Machines Work The Generated Voltage of a d-c Machine	331 332 335 339
Chapter	5.1 5.2 5.3 5.4 5.5 5.6	<b>Direct-Current Machines</b> The Importance of d-c Machines Construction of d-c Machines How d-c Machines Work The Generated Voltage of a d-c Machine Circuit Model of a d-c Machine Developed Torque	331 332 335 339 343 346
Chapter	5.1 5.2 5.3 5.4 5.5 5.6 5.7	<b>Direct-Current Machines</b> The Importance of d-c Machines Construction of d-c Machines How d-c Machines Work The Generated Voltage of a d-c Machine Circuit Model of a d-c Machine Developed Torque Field Excitation, Wound-Pole Machines	331 332 335 339 343 346 349
Chapter	5.1 5.2 5.3 5.4 5.5 5.6 5.7 5.8	Direct-Current Machines The Importance of d-c Machines Construction of d-c Machines How d-c Machines Work The Generated Voltage of a d-c Machine Circuit Model of a d-c Machine Developed Torque Field Excitation, Wound-Pole Machines Finding Kaф	331 332 335 339 343 346 349 352
Chapter	5.1 5.2 5.3 5.4 5.5 5.6 5.7 5.8 5.9	Direct-Current Machines The Importance of d-c Machines Construction of d-c Machines How d-c Machines Work The Generated Voltage of a d-c Machine Circuit Model of a d-c Machine Developed Torque Field Excitation, Wound-Pole Machines Finding Kaф Speed Control of Shunt and Permanent-Magnet Motors	331 332 335 339 343 346 349 352 359
Chapter	5.1 5.2 5.3 5.4 5.5 5.6 5.7 5.8 5.9 5.10	Direct-Current Machines The Importance of d-c Machines Construction of d-c Machines How d-c Machines Work The Generated Voltage of a d-c Machine Circuit Model of a d-c Machine Developed Torque Field Excitation, Wound-Pole Machines Finding Kaф Speed Control of Shunt and Permanent-Magnet Motors Per-Unit Values of d-c Machine Resistances and Losses	331 332 335 339 343 346 349 352 359 367
Chapter	5.1 5.2 5.3 5.4 5.5 5.6 5.7 5.8 5.9 5.10 5.11	<b>Direct-Current Machines</b> The Importance of d-c Machines Construction of d-c Machines How d-c Machines Work The Generated Voltage of a d-c Machine Circuit Model of a d-c Machine Developed Torque Field Excitation, Wound-Pole Machines Finding Kaф Speed Control of Shunt and Permanent-Magnet Motors Per-Unit Values of d-c Machine Resistances and Losses D-c Motor Starting and Dynamic Braking	331 332 335 339 343 346 349 352 359 367 372
Chapter	5.1 5.2 5.3 5.4 5.5 5.6 5.7 5.8 5.9 5.10 5.11 5.12	<b>Direct-Current Machines</b> The Importance of d-c Machines Construction of d-c Machines How d-c Machines Work The Generated Voltage of a d-c Machine Circuit Model of a d-c Machine Developed Torque Field Excitation, Wound-Pole Machines Finding Kaф Speed Control of Shunt and Permanent-Magnet Motors Per-Unit Values of d-c Machine Resistances and Losses D-c Motor Starting and Dynamic Braking Armature Reaction and Commutation	331 332 335 339 343 346 349 352 359 367 372 381
Chapter	5.1 5.2 5.3 5.4 5.5 5.6 5.7 5.8 5.9 5.10 5.11 5.12 5.13	<b>Direct-Current Machines</b> The Importance of d-c Machines Construction of d-c Machines How d-c Machines Work The Generated Voltage of a d-c Machine Circuit Model of a d-c Machine Developed Torque Field Excitation, Wound-Pole Machines Finding Ka¢ Speed Control of Shunt and Permanent-Magnet Motors Per-Unit Values of d-c Machine Resistances and Losses D-c Motor Starting and Dynamic Braking Armature Reaction and Commutation Characteristics of Series and Compound d-c Motors	331 332 335 339 343 346 349 352 359 367 372 381 391
Chapter	5.1 5.2 5.3 5.4 5.5 5.6 5.7 5.8 5.9 5.10 5.11 5.12 5.13 5.14	Direct-Current Machines The Importance of d-c Machines Construction of d-c Machines How d-c Machines Work The Generated Voltage of a d-c Machine Circuit Model of a d-c Machine Developed Torque Field Excitation, Wound-Pole Machines Finding Kaф Speed Control of Shunt and Permanent-Magnet Motors Per-Unit Values of d-c Machine Resistances and Losses D-c Motor Starting and Dynamic Braking Armature Reaction and Commutation Characteristics of Series and Compound d-c Motors Permanent Magnet d-c (PMDC) Machines	331 332 335 339 343 346 349 352 359 367 372 381 391 393
Chapter	5.1 5.2 5.3 5.4 5.5 5.6 5.7 5.8 5.9 5.10 5.11 5.12 5.13 5.14 5.15	Direct-Current Machines The Importance of d-c Machines Construction of d-c Machines How d-c Machines Work The Generated Voltage of a d-c Machine Circuit Model of a d-c Machine Developed Torque Field Excitation, Wound-Pole Machines Finding Kaф Speed Control of Shunt and Permanent-Magnet Motors Per-Unit Values of d-c Machine Resistances and Losses D-c Motor Starting and Dynamic Braking Armature Reaction and Commutation Characteristics of Series and Compound d-c Motors Permanent Magnet d-c (PMDC) Machines Self-Excited d-c Generators	331 332 335 339 343 346 349 352 359 367 372 381 391 393 402
Chapter	5.1 5.2 5.3 5.4 5.5 5.6 5.7 5.8 5.9 5.10 5.11 5.12 5.13 5.14 5.15 5.16	Direct-Current Machines The Importance of d-c Machines Construction of d-c Machines How d-c Machines Work The Generated Voltage of a d-c Machine Circuit Model of a d-c Machine Developed Torque Field Excitation, Wound-Pole Machines Finding Kaф Speed Control of Shunt and Permanent-Magnet Motors Per-Unit Values of d-c Machine Resistances and Losses D-c Motor Starting and Dynamic Braking Armature Reaction and Commutation Characteristics of Series and Compound d-c Motors Permanent Magnet d-c (PMDC) Machines Self-Excited d-c Generators Armature Windings for Commutator Machines	331 332 335 339 343 346 349 352 359 367 372 381 391 393 402 413
Chapter	5.1 5.2 5.3 5.4 5.5 5.6 5.7 5.8 5.9 5.10 5.11 5.12 5.13 5.14 5.15 5.16 5.17	<b>Direct-Current Machines</b> The Importance of d-c Machines Construction of d-c Machines How d-c Machines Work The Generated Voltage of a d-c Machine Circuit Model of a d-c Machine Developed Torque Field Excitation, Wound-Pole Machines Finding Kaф Speed Control of Shunt and Permanent-Magnet Motors Per-Unit Values of d-c Machine Resistances and Losses D-c Motor Starting and Dynamic Braking Armature Reaction and Commutation Characteristics of Series and Compound d-c Motors Permanent Magnet d-c (PMDC) Machines Self-Excited d-c Generators Armature Windings for Commutator Machines Metadynes	331 332 335 339 343 346 349 352 359 367 372 381 391 393 402 413 418
Chapter	5.1 5.2 5.3 5.4 5.5 5.6 5.7 5.8 5.9 5.10 5.11 5.12 5.13 5.14 5.15 5.16	<b>Direct-Current Machines</b> The Importance of d-c Machines Construction of d-c Machines How d-c Machines Work The Generated Voltage of a d-c Machine Circuit Model of a d-c Machine Developed Torque Field Excitation, Wound-Pole Machines Finding Kaф Speed Control of Shunt and Permanent-Magnet Motors Per-Unit Values of d-c Machine Resistances and Losses D-c Motor Starting and Dynamic Braking Armature Reaction and Commutation Characteristics of Series and Compound d-c Motors Permanent Magnet d-c (PMDC) Machines Self-Excited d-c Generators Armature Windings for Commutator Machines Metadynes	331 332 335 339 343 346 349 352 359 367 372 381 391 393 402 413
-	5.1 5.2 5.3 5.4 5.5 5.6 5.7 5.8 5.9 5.10 5.11 5.12 5.13 5.14 5.15 5.16 5.17 Proble	Direct-Current Machines The Importance of d-c Machines Construction of d-c Machines How d-c Machines Work The Generated Voltage of a d-c Machine Circuit Model of a d-c Machine Developed Torque Field Excitation, Wound-Pole Machines Finding Kaф Speed Control of Shunt and Permanent-Magnet Motors Per-Unit Values of d-c Machine Resistances and Losses D-c Motor Starting and Dynamic Braking Armature Reaction and Commutation Characteristics of Series and Compound d-c Motors Permanent Magnet d-c (PMDC) Machines Self-Excited d-c Generators Armature Windings for Commutator Machines Metadynes	331 332 335 339 343 346 349 352 359 367 372 381 391 393 402 413 418
Chapter	5.1 5.2 5.3 5.4 5.5 5.6 5.7 5.8 5.9 5.10 5.11 5.12 5.13 5.14 5.15 5.16 5.17 Proble	Direct-Current Machines The Importance of d-c Machines Construction of d-c Machines How d-c Machines Work The Generated Voltage of a d-c Machine Circuit Model of a d-c Machine Developed Torque Field Excitation, Wound-Pole Machines Finding Kaф Speed Control of Shunt and Permanent-Magnet Motors Per-Unit Values of d-c Machine Resistances and Losses D-c Motor Starting and Dynamic Braking Armature Reaction and Commutation Characteristics of Series and Compound d-c Motors Permanent Magnet d-c (PMDC) Machines Self-Excited d-c Generators Armature Windings for Commutator Machines Metadynes ems	331 332 335 339 343 346 349 352 359 367 372 381 391 393 402 413 418 425
-	5.1 5.2 5.3 5.4 5.5 5.6 5.7 5.8 5.9 5.10 5.11 5.12 5.13 5.14 5.15 5.16 5.17 Proble	Direct-Current Machines The Importance of d-c Machines Construction of d-c Machines How d-c Machines Work The Generated Voltage of a d-c Machine Circuit Model of a d-c Machine Developed Torque Field Excitation, Wound-Pole Machines Finding Kaф Speed Control of Shunt and Permanent-Magnet Motors Per-Unit Values of d-c Machine Resistances and Losses D-c Motor Starting and Dynamic Braking Armature Reaction and Commutation Characteristics of Series and Compound d-c Motors Permanent Magnet d-c (PMDC) Machines Self-Excited d-c Generators Armature Windings for Commutator Machines Metadynes ems Single – Phase Machines Why Single-Phase Motors Are Different	331 332 335 339 343 346 349 352 359 367 372 381 391 393 402 413 418 425
-	5.1 5.2 5.3 5.4 5.5 5.6 5.7 5.8 5.9 5.10 5.11 5.12 5.13 5.14 5.15 5.16 5.17 Proble	Direct-Current Machines The Importance of d-c Machines Construction of d-c Machines How d-c Machines Work The Generated Voltage of a d-c Machine Circuit Model of a d-c Machine Developed Torque Field Excitation, Wound-Pole Machines Finding Kaф Speed Control of Shunt and Permanent-Magnet Motors Per-Unit Values of d-c Machine Resistances and Losses D-c Motor Starting and Dynamic Braking Armature Reaction and Commutation Characteristics of Series and Compound d-c Motors Permanent Magnet d-c (PMDC) Machines Self-Excited d-c Generators Armature Windings for Commutator Machines Metadynes ems Single – Phase Machines Why Single-Phase Motors Are Different The Universal Motor	331 332 335 339 343 346 349 352 359 367 372 381 391 393 402 413 418 425 431 432
-	5.1 5.2 5.3 5.4 5.5 5.6 5.7 5.8 5.9 5.10 5.11 5.12 5.13 5.14 5.15 5.16 5.17 Proble	Direct-Current Machines The Importance of d-c Machines Construction of d-c Machines How d-c Machines Work The Generated Voltage of a d-c Machine Circuit Model of a d-c Machine Developed Torque Field Excitation, Wound-Pole Machines Finding Kaф Speed Control of Shunt and Permanent-Magnet Motors Per-Unit Values of d-c Machine Resistances and Losses D-c Motor Starting and Dynamic Braking Armature Reaction and Commutation Characteristics of Series and Compound d-c Motors Permanent Magnet d-c (PMDC) Machines Self-Excited d-c Generators Armature Windings for Commutator Machines Metadynes ems Single – Phase Machines Why Single-Phase Motors Are Different the Universal Motor the Shaded-Pole Motor	331 332 335 339 343 346 349 352 359 367 372 381 391 393 402 413 418 425 431 432 434
-	5.1 5.2 5.3 5.4 5.5 5.6 5.7 5.8 5.9 5.10 5.11 5.12 5.13 5.14 5.15 5.16 5.17 Proble	Direct-Current Machines The Importance of d-c Machines Construction of d-c Machines How d-c Machines Work The Generated Voltage of a d-c Machine Circuit Model of a d-c Machine Developed Torque Field Excitation, Wound-Pole Machines Finding Kaф Speed Control of Shunt and Permanent-Magnet Motors Per-Unit Values of d-c Machine Resistances and Losses D-c Motor Starting and Dynamic Braking Armature Reaction and Commutation Characteristics of Series and Compound d-c Motors Permanent Magnet d-c (PMDC) Machines Self-Excited d-c Generators Armature Windings for Commutator Machines Metadynes ems Single – Phase Machines Why Single-Phase Motors Are Different the Universal Motor he Shaded-Pole Motor ingle-Phase Induction Motors-Introduction	331 332 335 339 343 346 349 352 359 367 372 381 391 393 402 413 418 425 431 432 434 439
-	5.1 5.2 5.3 5.4 5.5 5.6 5.7 5.8 5.9 5.10 5.11 5.12 5.13 5.14 5.15 5.16 5.17 Proble 6.1 W 6.2 T 6.3 T 6.4 S 6.5 T	Direct-Current Machines The Importance of d-c Machines Construction of d-c Machines How d-c Machines Work The Generated Voltage of a d-c Machine Circuit Model of a d-c Machine Developed Torque Field Excitation, Wound-Pole Machines Finding Kaф Speed Control of Shunt and Permanent-Magnet Motors Per-Unit Values of d-c Machine Resistances and Losses D-c Motor Starting and Dynamic Braking Armature Reaction and Commutation Characteristics of Series and Compound d-c Motors Permanent Magnet d-c (PMDC) Machines Self-Excited d-c Generators Armature Windings for Commutator Machines Metadynes ems Single – Phase Machines Why Single-Phase Motors Are Different the Universal Motor the Shaded-Pole Motor ingle-Phase Induction Motors-Introduction the Split-Phase Motor	<ul> <li>331</li> <li>332</li> <li>335</li> <li>339</li> <li>343</li> <li>346</li> <li>349</li> <li>352</li> <li>359</li> <li>367</li> <li>372</li> <li>381</li> <li>391</li> <li>393</li> <li>402</li> <li>413</li> <li>418</li> <li>425</li> <li>431</li> <li>432</li> <li>434</li> <li>439</li> <li>443</li> </ul>
-	5.1 5.2 5.3 5.4 5.5 5.6 5.7 5.8 5.9 5.10 5.11 5.12 5.13 5.14 5.15 5.16 5.17 Proble 6.1 W 6.2 T 6.3 T 6.4 S 6.5 T 6.6 C	Direct-Current Machines The Importance of d-c Machines Construction of d-c Machines How d-c Machines Work The Generated Voltage of a d-c Machine Circuit Model of a d-c Machine Developed Torque Field Excitation, Wound-Pole Machines Finding Kaф Speed Control of Shunt and Permanent-Magnet Motors Per-Unit Values of d-c Machine Resistances and Losses D-c Motor Starting and Dynamic Braking Armature Reaction and Commutation Characteristics of Series and Compound d-c Motors Permanent Magnet d-c (PMDC) Machines Self-Excited d-c Generators Armature Windings for Commutator Machines Metadynes ems Single – Phase Machines Why Single-Phase Motors Are Different he Universal Motor he Shaded-Pole Motor ingle-Phase Induction Motors-Introduction he Split-Phase Motor Spacitor Motors	<ul> <li>331</li> <li>332</li> <li>335</li> <li>339</li> <li>343</li> <li>346</li> <li>349</li> <li>352</li> <li>359</li> <li>367</li> <li>372</li> <li>381</li> <li>391</li> <li>393</li> <li>402</li> <li>413</li> <li>418</li> <li>425</li> <li>431</li> <li>432</li> <li>434</li> <li>439</li> <li>443</li> <li>445</li> </ul>
-	5.1 5.2 5.3 5.4 5.5 5.6 5.7 5.8 5.9 5.10 5.11 5.12 5.13 5.14 5.15 5.16 5.17 Proble 6.1 W 6.2 T 6.3 T 6.4 S 6.5 T 6.6 C 6.7 R	Direct-Current Machines The Importance of d-c Machines Construction of d-c Machines How d-c Machines Work The Generated Voltage of a d-c Machine Circuit Model of a d-c Machine Developed Torque Field Excitation, Wound-Pole Machines Finding Kaф Speed Control of Shunt and Permanent-Magnet Motors Per-Unit Values of d-c Machine Resistances and Losses D-c Motor Starting and Dynamic Braking Armature Reaction and Commutation Characteristics of Series and Compound d-c Motors Permanent Magnet d-c (PMDC) Machines Self-Excited d-c Generators Armature Windings for Commutator Machines Metadynes ems Single – Phase Machines Why Single-Phase Motors Are Different the Universal Motor the Shaded-Pole Motor ingle-Phase Induction Motors-Introduction the Split-Phase Motor	<ul> <li>331</li> <li>332</li> <li>335</li> <li>339</li> <li>343</li> <li>346</li> <li>349</li> <li>352</li> <li>359</li> <li>367</li> <li>372</li> <li>381</li> <li>391</li> <li>393</li> <li>402</li> <li>413</li> <li>418</li> <li>425</li> <li>431</li> <li>432</li> <li>434</li> <li>439</li> <li>443</li> </ul>

Index

457