

---

# Contents

---

<b>Foreword</b>	<i>Page</i>
	<b>xv</b>
<b>Preface</b>	<b>xvi</b>
<b>Acknowledgments</b>	<b>xviii</b>
<b>List of symbols</b>	<b>xxi</b>
<b>Part I Direct resistance heating</b>	
<b>1 Fundamentals</b>	
1.1 Introduction	3
1.2 Simple electrical equations	4
1.3 Simple electrothermal equations	5
1.4 Practical modifications	8
1.5 Contacts	12
<b>2 Alternating currents in conductors: the semi-infinite slab</b>	
2.1 The problem	13
2.2 Current flow in a semi-infinite slab	14
2.2.1 Skin depth	17
2.2.2 Current	18
2.2.3 Power loss per unit surface area	19
2.2.4 Effective resistance	19
2.2.5 Electric field intensity	20
2.2.6 Surface magnetic field intensity	21
2.2.7 Total flux	21
2.3 Physical interpretation	22
<b>3 Alternating currents in conductors: wide rectangular slab</b>	
3.1 Introduction	
3.2 Current-density distribution	
3.3 Total current	
3.4 Power density	
3.4.1 Real and reactive power density using <i>EI</i>	

# *viii Contents*

3.4.2	Power in circuit terms	29
3.4.3	Power under AC and DC conditions	31
3.4.4	Power factor	31
3.4.5	Limits of size: strip	31
3.5	Loss approximations	31
3.5.1	Resistance	31
3.5.2	Power density	32
3.6	Flux-density distribution	33
3.7	Depth of penetration	34

## **4 Alternating currents in conductors: circular cross-section 35**

4	Solid conductor	35
4.1.1	Solutions of the Bessel equation	37
4.1.2	Functions ber, bei, ker, kei	37
4.1.3	Polar forms	39
4.2	Current-density distribution and total current in a solid conductor	41
4.2.1	Phase angle and power factor	43
4.3	Power	44
4.3.1	Real power	44
4.3.2	Reactive power	46
4.3.3	Power factor, using $p_r$ and $q_r$	46
4.4	Circuit quantities	47
4.5	Loss approximations	48
4.5.1	Resistance	48
4.5.2	Resistance at high frequencies	49
4.5.3	Power	49

## **5 Hollow conductors: tubes 51**

5.1	Introduction	51
5.2	Equations for tubes	51
5.3	Current-density distribution	52
5.4	Loss density	55
5.5	Total current	55
5.6	Power	56
5.7	Circuit quantities	58
5.7.1	Power factor	61
5.8	Example calculation: power loss constants and impedance ratios for tube	61

## **6 Wire and strip heating 64**

6.1	Introduction	64
6.2	Constant $\rho$ and $(c\gamma)$	64
6.3	Variable $\rho$ and $(c\gamma)$	67
6.3.1	General	67
6.3.2	Analytical solution	67
6.4	Practical conditions	71

## Part II Induction heating

<b>7</b>	<b>Basic induction heating</b>	<b>75</b>
7.1	Introduction	75
7.2	The semi-infinite slab	76
7.3	Duality of DRH and induction heating	77
7.4	Depth of penetration	78
7.5	Flux density, current density and electric field	78
7.6	Total current	80
7.7	Loss	80
7.8	Total flux and power factor	82
7.9	Power, using the Poynting theorem	83
<b>8</b>	<b>Induction heating of thin slabs</b>	<b>85</b>
8.1	Introduction	85
8.2	Magnetic field distribution	86
8.3	Current-density distribution	87
8.4	Flux distribution	88
8.5	Power	89
8.6	Power factor	91
8.7	Duality	91
<b>9</b>	<b>Induction heating of cylinders</b>	<b>93</b>
9.1	Basic principles	93
9.2	Magnetic field distribution	94
9.3	Flux distribution	95
9.4	Current-density distribution	96
9.5	Power	99
9.6	Power factor	101
9.7	Duality	102
<b>10</b>	<b>Induction heating of tubes</b>	<b>103</b>
10.1	Relationship between the constants $A$ and $B$ in the field distribution	103
10.2	Magnetic field distribution	104
10.3	Current-density distribution	105
10.4	Loss-density distribution	110
10.5	Power	112
10.5.1	Tube power loss constant	115
10.5.2	Tube reactive power loss constant	117
<b>11</b>	<b>Induction heating of hollow cylinder from inside</b>	<b>118</b>
11.1	Magnetic field distribution	118
11.2	Current-density distribution	119
11.3	Power loss	120
11.4	Power factor	121

## x Contents

<b>12</b>	<b>Effects of changing permeability and resistivity</b>	<b>123</b>
12.1	Introduction	123
12.2	Semi-infinite slab	123
12.2.1	Change $\mu$ : conduction, semi-infinite slab	123
12.2.2	Change $\mu$ : induction, semi-infinite slab	124
12.2.3	Change $\rho$ : conduction, semi-infinite slab	125
12.2.4	Change $\rho$ : induction, semi-infinite slab	125
12.3	Thin slabs and cylinders	125
12.3.1	Change $\mu$ : conduction, thin slabs and cylinders	127
12.3.2	Change $\rho$ : conduction, thin slabs and cylinders	127
12.3.3	Change $\mu$ : induction, thin slabs and cylinders	127
12.3.4	Change $\rho$ : induction, thin slabs and cylinders	127
	Combined resistivity and permeability changes	127
12.4.1	Change $\rho$ and $\mu$ : conduction, semi-infinite slab	127
12.4.2	Change $\rho$ and $\mu$ : conduction, thin slab	127
12.4.3	Change $\rho$ and $\mu$ : conduction, cylinder	128
12.4.4	Change $\rho$ and $\mu$ : induction	128
<b>13</b>	<b>Non-linear theory</b>	<b>130</b>
<b>14</b>	<b>Proximity heating</b>	<b>133</b>
	Scanning heating	135
<b>Part III Heat transfer for electroheat</b>		
<b>15</b>	<b>Basic heat transfer</b>	<b>139</b>
15.1	Introduction	139
15.2	Heat storage: relationship between power, mean temperature and time	140
15.3	Temperature distribution during heating	142
15.3.1	Qualitative treatment	142
15.3.2	Mathematical treatment	143
15.3.3	Generalised values in terms of surface-centre temperature difference	145
15.3.4	Surface temperature	147
15.4	Identity of slab solutions	147
<b>16</b>	<b>Soaking conditions</b>	<b>152</b>
16.1	Introduction	152
16.1.1	Value of final temperature $\theta_m$	152
16.1.2	Solutions for temperature distribution	153
16.2	Soaking of slab previously heated from one side	153
16.3	Soaking of slab previously heated from both sides	156
16.4	Soaking of cylinders	156
	<b>Radiation</b>	<b>159</b>
17.1	Time to heat a billet, including radiation	159
17.2	Time to heat a slab, including radiation	160

17.3	Mean radiated power over a temperature interval	161
17.4	Cooling by radiation	162
<b>Effect of current depth and radiation</b>		<b>164</b>
18.1	General heat-flow equation	164
18.2	Loss density	165
18.3	Rectangular slab: conduction and induction heating	166
18.4	Cylindrical billets: conduction and induction heating	172
18.4.1	Induction	174
18.4.2	Conduction	176
18.5	Effect of radiation	178
<b>19</b>	<b>Heat transfer during surface hardening</b>	<b>180</b>
19.1	Slab subjected to sudden increase in surface temperature	180
19.2	Slab subjected to a temperature $\theta(t)$ varying with time	182
19.3	Slab subjected to a constant power-density	183
19.4	Slab subjected to a surface power-density $\mathcal{P}_s(t)$ varying with time	185
19.5	Slab allowed to soak	185
<b>20</b>	<b>Water cooling in conductors</b>	<b>186</b>
20.1	General	186
20.2	Temperature difference	190
20.3	Water quantity	190
20.4	Arrangement of cooling paths	191
20.5	Pressure drops	192
20.6	Non-circular pipes and ducts	194
<b>21</b>	<b>Billet with initial temperature distribution</b>	<b>195</b>
<b>Part IV Practical heating</b>		
<b>22</b>	<b>Through-heating by induction</b>	<b>201</b>
22.	Introduction to applications of through-heating	201
22.1.1	Comparison with fossil-fuel-fired heating furnaces	202
22.1.2	Induction-heating configurations	203
22.2	Temperature effects	204
22.2.1	Specific heat	204
22.2.2	Resistivity	207
22.3	Heat radiation and convection	209
22.4	Temperature distribution in induction through-heating	211
22.5	Effects of current depth and radiated heat	213
22.6	Temperature distributions in a heating cycle	213
22.7	Selection of frequencies for induction heating	217
22.8	Coil design for given applications	219
22.8.1	Coil design for aluminium billet heater	219
22.8.2	Coil design for ferromagnetic billets	223
22.8.3	Semi-empirical approximations	227

## Contents

22.9	Equivalent circuit coil-design method	229
22.9.1	Coil design for ferromagnetic billet: equivalent circuit method	234
22.10	Mechanical construction of coils	237
22.11	Slab reheating	240
22.12	Travelling-wave induction heating	242
22.12.1	Advantages of travelling-wave induction heating	244
22.12.2	Comparison of travelling-wave induction heating with the Ross coil	244
22.12.3	Implementation of travelling-wave heaters	245
22.13	Multi-layer coils	246
22.14	Tapered heating for extrusion	246
22.15	Scale-model analogue methods	247
22.16	Heating of powdered-metal preforms for sintering	248
<b>Surface heating by induction</b>		<b>249</b>
	Metallurgical principles of heat treatment	251
23.1.1	Typical induction-hardening steels	253
23.2	Quenches and quenching	257
23.3	Selection of frequency for induction heat-treatment	261
23.4	Temperature distribution in induction surface-hardening	267
23.4.1	Constant surface temperature	267
23.4.2	Constant power input	268
23.5	Application specifications for coil design	269
23.6	Mechanical construction of coils	272
<b>Other applications of induction heating</b>		<b>275</b>
24.1	Soldering and brazing	275
24.1.1	Basic joining techniques	275
24.1.2	Choice of frequency	276
24.1.3	Design calculations	277
24.2	Tube welding	289
24.2.1	Work coil	290
24.2.2	Impeder	292
24.2.3	Strip	294
24.2.4	Seam guide	294
24.2.5	Squeeze rolls	295
24.3	Heating of resin kettles and other vessels	296
24.4	Paint drying	298
24.5	Induction heating in plastic working	299
24.5	Annealing and stress relieving	300
24.6.1	Tempering	301
24.6.2	Annealing	301
24.6.3	Stress relieving	302
24.7	Longitudinal flux induction heating	302
24.8	Transverse-flux heating	303
24.9	Semiconductor processing	305
24.10	Miscellaneous uses of induction heating	308
24.11	Travelling-wave heaters	309

<b>25</b>	<b>Induction melting</b>	<b>311</b>
	Principles of induction melting	311
	25.1.1 Coreless induction furnaces	312
	25.1.2 Channel induction furnaces	315
	The coreless induction furnace	317
	25.2.1 Refractory linings	317
	25.2.2 Windings	319
	25.2.3 Flux guides	320
	25.2.4 Frame	321
	25.2.5 Electrical connections	321
	25.2.6 Choice of frequency	322
	25.2.7 Sizes of furnace	323
	The channel furnace	324
	25.3.1 The main vessel	324
	25.3.2 The inductor	325
	25.3.3 Loading and pouring	326
	25.3.4 Choice of size	327
25.4	Comparison of coreless and channel furnaces	327
	25.4.1 Combination methods	328
25.5	Special features in melting furnaces	329
	25.5.1 Furnaces using separate crucibles	329
	25.5.2 Vacuum furnaces	331
	25.5.3 Rollover furnaces	333
<b>26</b>	<b>Direct resistance heating</b>	<b>335</b>
26.1	Introduction	335
26.2	AC versus DC for DRH	336
	26.2.1 Unrectified AC	336
	26.2.2 Rectified AC	337
	26.2.3 Comparison: single phase	338
	26.2.4 Polyphase AC	339
26.3	Value of $\mu$ in DRH	340
26.4	Contacts	340
	26.4.1 Contact materials	340
	26.4.2 Liquid metal contacts	341
26.5	Practical applications: case studies	341
	26.5.1 Spring winding	341
	26.5.2 Warm cropping	342
	26.5.3 Heating for forging	343
Appendix A.1 Resistivity, specific heat and thermal conductivity as functions of temperature		345
Appendix A.2 Relations for $\tanh (1 \pm j)\theta$		351
Appendix A.3 Bessel functions and values of $M_0$ , $M_1$ , $N_0$ and $N_1$ for $x\sqrt{2}$		353