

CONTENTS

PREFACE

PAGE
v

PART I: THEORY AND PRACTICE

CHAPTER I

FUNDAMENTALS

1

FUNDAMENTALS OF THEORY—Definitions—Fundamental considerations—Meaning of limits—Tolerance units—GAUGING AND MEASUREMENT—Introduction—Elementary methods: the rule; vernier calipers—Normal shop methods: micrometers; snap or gap gauges; plug and ring gauges; dial instruments—Precision methods: lever comparators; electrical comparators; pneumatic comparators; slip gauges or blocks—Miscellaneous processes: measuring angles and tapers; measuring hole pitching; "automatic" inspection methods; devices for measuring wall thickness from one side—Temperature effects—TOLERANCES IN RELATION TO FACTORY MACHINE PROCESSES—Introduction—Interchangeability—Tolerance and limits: general limits or tolerance; quality of tolerance or grade of workmanship—Limits and the production facilities—Machine limitations—Lathes: centre lathes; capstans and turret; automatics—Milling processes; milling; hobbing—Rectilinear processes—Abrasive processes: grinding; honing; lapping—Boring operations: drilling; reaming; boring—Heavy machines

CHAPTER II

LIMITS AND FITS IN THE DESIGN OFFICE

40

INTRODUCTORY—DRAWING PRACTICE—General tolerances—Method of indicating limits—Choice of tolerance system: standard systems; unilateral or bilateral—Dimensioning of drawings in relation to interchangeability: notes on dimensioning—Geometrical or macro errors: errors of circularity; errors of flatness; errors of axial truth; errors of concentricity—Selective assembly methods—PRESS FITS—Determination of basic deviation—Factors affecting grip—Methods of assembly: force fits; shrink fits; freeze fits—Assembly loads with press fits—Bore closure on bushes—Note on tolerance tables—TRANSITION FITS—Spigots—Light press fits by selective assembly—Assembly with least play—Assembly with least play compatible with ease of assembly—CLEARANCE FITS—Variation of clearance with diameter—Minimum running clearance—Normal running clearance—The effect of tolerance on bearing performance—OVERSIZE AND UNDERSIZE HOLES—Oversize holes—Application—An important example—Undersize holes—TOLERANCES ON COMPONENTS INVOLVING ANGLES—Tapers—Position of drilled holes—Splines—TOLERANCE ON PLATED PARTS—SELECTION TABLES—Holes—True press fits—Transition fits—Clearance fits—EXAMPLE OF LIMIT AND TOLERANCE APPLICATION—Fits of fundamental importance—Other limits—Conclusion

CHAPTER III

QUALITY CONTROL—ITS INTEREST IN TOLERANCE SETTING

104

Introduction—Conditions under which theory of probability can be applied—The theory of probability—Miscellaneous definitions—The use of the theory of probability in widening limits—Control charts and their interest to designers

STANDARD LIMIT AND TOLERANCE SYSTEMS

THE NEWALL TOLERANCE SYSTEM—Historical—Grades of fit—Association of holes and shafts—Diameter steps—Derivation of limits—Description of fits—Gauge limits—B.S. 164 LIMITS AND FITS FOR ENGINEERING—Historical—Grades of fit—Association of holes and shafts—Diameter steps—Derivation of limits—Description of fits—Gauge limits—THE AMERICAN STANDARDS ASSOCIATION TOLERANCE SYSTEM—Grades of fit—Association of holes and shafts—Diameter steps—Derivation of limits—Description of fits—Gauge limits—THE I.S.A. TOLERANCE SYSTEM—Historical—Grades of fit—Association of holes and shafts—Diameter steps—Fundamental tolerances—Derivation of limits—Rounding-off methods used in the translation—Special notes on tables of fits—Description of fits—Gauge limits—THE D.I.N. TOLERANCE SYSTEM—MISCELLANEOUS TOLERANCE SYSTEMS—The Brown and Sharpe table of "Allowances for Fits"—The "Machinist" chart of allowances for shaft fits

CHAPTER V

STANDARD LIMIT AND TOLERANCE SYSTEMS—*contd.*

BALL AND ROLLER BEARING LIMITS AND TOLERANCES—Manufacturing limits for ball and roller bearings—Installation limits for ball and roller bearings—Needle bearings—MISCELLANEOUS REFERENCES AND TABLES—Oil seal tolerances—Tolerances recommended for furnace copper brazing—Tolerances on drilled holes—Self-lubricating (sintered) bearings—Press fits—Hexagon tolerances

PART III: MISCELLANEOUS PRODUCTION PROBLEMS

CHAPTER VI

TOLERANCES IN MISCELLANEOUS FABRICATION PROCESSES

ROLLING—Bars, sheet and strip—STAMPING—Steel stampings and forgings—Cold heading—Light alloy stampings—DRAWING—Tube drawing—Bar, rod or wire drawing—EXTRUSION—Tolerances for special sections: aircraft light alloys—Tolerances for aluminium alloy extruded sections—Tolerances on impact extrusion—CASTING—Sand and die—MOULDING—Plastic moulding—Sintering—RUBBER—Rubber moulding—Rubber cutting—MISCELLANEOUS—Flame cutting—Continuous centreless ground steel rod—Pressing—Spinning

CHAPTER VII

SCREW THREAD TOLERANCES

Introduction—Thread forms and tolerance zones—Types of fit; clearance; normal; transition; interference—Selection of fit: general; studs; truncation—Manufacturing errors in screw production—Derivation of limits and tolerances: B.S. Whitworth form; British Association; American National; Metric (D.I.N.); Metric (B.S.)—Screw thread gauging practice: general considerations; screw gauge tolerances

CHAPTER VIII

GAUGE TOLERANCES

Introduction—General considerations for all gauges—Published limit gauge tolerance systems: British Standard System (B.S. 969); The I.S.A. Gauge Tolerance System

APPENDICES

	PAGE
1. MICROMETER READING TESTS	273
2. ERRORS IN MEASUREMENT DUE TO SURFACE INDENTATION DURING GAUGING	275
3. COEFFICIENTS OF LINEAR EXPANSION; MODULI OF ELASTICITY	277
4. POSITION ERRORS EXPRESSED AS ANGULAR EQUIVALENTS, FOR A RADIUS OF ONE INCH	278
5. CONVERSION TABLE FOR SMALL TOLERANCES	279
6. TERMINOLOGY	280
7. BIBLIOGRAPHY	284
INDEX	285