CONTENTS

CHAP.

1. TESTING AND INSPECTION OF ENGINEERING MATERIALS

Testing and inspection of engineering materials. Tensile, transverse, and bend tests. Impact tests. Hardness and ductility tests. Fatigue testing. Magnetic and ultrasonic methods.

- 2. FERROUS MATERIALS Pig-iron, wrought iron, mild, carbon, and alloy steels. Structure of metals. Cooling curves and equilibrium diagrams. Heat treatment of steels. Surface hardening, carburisation, nitriding, and flame hardening. Tool steels. Cast iron. High strength and special irons.
- 3. NON-FERROUS ALLOYS . Copper, brasses, bronzes. Special brasses and bronzes. Copper-nickel alloys. Bearing alloys. Aluminium and magnesium alloys. Titanium alloys. Miscellaneous alloys.
- 4. THE PRODUCTION OF CASTINGS Principles of moulding and casting. Mould materials, moulding sands. Preparation of mould. Examples of moulding practice. Mechanical aids in moulding. "Shell" moulds. Preparation of metal for pouring. Fettling of castings. Defects in castings. Die-castings, gravity and pressure types. Investment castings. Examples of dies. Advantages and drawbacks of die castings.
- 5. FORGING .

Methods and tools used in hand and hammer forging. Machine forging. Drop forging, die design, and cost. Comparison of hand and drop forgings.

6. PRESS-TOOL WORK AND SPINNING Basic principle of press-tool work. Examples of tools. Types of press. Trimming, blanking, and drawing tools. The spinning process and its advantages.

65

21

88

141

HAP.

- 7. FABRICATION BY WELDING . Welding processes and techniques. Gas and electric welding. Flash, spot, seam, and projection welding. Arc welding. Shielded arc processes. Welding rods. Distortion difficulties. Inspection of welds.
- 8. PLASTIC MOULDING Outline of processes. Thermo-plastic and thermo-setting materials. Examples of dies and presses. Injection moulding. Vacuum forming. Blow moulding.
- 9. CLASSIFICATION OF MACHINE TOOLS
 - Single purpose, multi-purpose, special, transfer, and tape controlled machines. Copying and generating principles. Using cutting or abrasive tools. Cutting-tool action. Orthogonal cutting.
- 10. THE LATHE Brief description of typical lathe. Methods of holding work. Tools used. Cutting speeds and feeds. Example of engine lathe work. Screw cutting. The vertical lathe.
- 11. TOOL LIFE Effect of tool angles, cutting speeds, and feeds.
- 12. THE CAPSTAN AND TURRET LATHES . . . Brief description of types. Examples of capstan and turret "tool-ups". The die-head. Single and multi-spindle automatic lathes.
- 13. THE MACHINING OF HOLES Flat, spade and twist drills. D-bits. Boring and trepanning. Drilling and boring machines. Reamers.
- 14. JIGS AND FIXTURES Principle of the jig and fixture. Examples. Production of jigs; jig-boring machines. Marking-out work.
- 15. THE MILLING PROCESS Description. Cutters used. Types of machine. Examples of work done. Speeds and feeds. The dividing head and its use. Thread and worm milling.
- 16. PLANING, SHAPING, AND SLOTTING MACHINES Description of the types. Tools used and work done. Special field.

PAGE 157 CONTENTS

	COMTENTS	лі
снар. 17. В	BROACHING Basic principle. Internal broaching. Examples of broach Broaching machines. External broaching.	PAGE 297
(GEAR CUTTING Spur gear cutting. Form cutters. Generating machines, rack and pinion types. Hobbing. Bevel gear cutting. Straight and spiral bevels. Worm gear cutting.	302
19. Л	THE GRINDING PROCESS Construction of grinding wheel. Abrasives and bonding materials. Grading of wheels. Accurate attainable. Types of machines. Cylindrical and surface grinding. Centre- less grinding. Internal grinding. Tool and cutter grind- ing. Cam, spline, and gear tooth grinding.	323
20. H	HONING, SUPER-FINISHING, AND LAPPING . Principle of honing process. Examples of hones. Advan- tages of honing. The super-finishing process. Laps and lapping.	340
21. N	MEASURING METHODS AND GAUGING Instruments available. Standards of accuracy. Measuring machines and comparators. Air gauging systems. Tool and gauge-room measurements. Fixed gauges. Limit gauges. Tolerances and allowances. British and Inter- national standard limits and fits. Gauge tolerances and wear allowances. Multi-dimension gauges. Gauging of screw threads and gear teeth.	355
22. 7	TRANSFER MACHINES AND AUTOMATION . Rotary and linear transfer machines. Contour machining. <i>Keller</i> die-sinker. <i>G-F</i> copying lathe. <i>Hydrotel</i> system. Magnetic and punched tape control.	396

INDEX

421

xì